

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21001429/UPA3Q2

Date: 15/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900107739

Claimant Vehicle No : SLE7389P **Insured Vehicle No :** SMM3270U

Date of Loss: 28/01/2021 Nature of Claim: TP Claim No: 0135838199SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE7389P		
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Engine No:	K24W1409365
Reg. Date:	29/07/2016 (Man. Year: 2015)	Chassis No:	RC11109207
Colour:	Black	Odometer:	69030 km
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,964.16	2,370.40	5,593.76	70.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	1,790.00	1,270.00	41.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,024.16	4,160.40	6,863.76	62.26
Approved Total (Overridden) (\$\$)		3,300.00		
(\$\$)	11,024.16	3,300.00	7,724.16	70.07
+ GST 7.00/7.00% (\$\$)	771.69	231.00	540.69	70.07
Nett Amount (\$\$)	11,795.85	3,531.00	8,264.85	70.07
+ Loss of Use (4.0 x \$100.00/day) (\$\$)		400.00		
Nett Liability (\$\$)		3,931.00		
Global Sum Settlement (\$\$)		3,930.00		

INSPECTION

Date of Assignment: 29/01/2021

Date Inspected: 01/02/2021 Inspected At:

Automobile Integrated Management
Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01, Kaki Bukit
(South Wing)
Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,271.50 FL	*1,271.50 FL
2	1		*TAILGATE GLASS MOULDING	Necessary	141.20 FL	*141.20 FL
3	1		*TAILGATE EMBLEM H	Necessary	48.60 FL	*48.60 FL
4	1		*TAILGATE CHROME MOULDING	Not Necessary	230.40 FL	*- FL
5	2		*TAILGATE LAMPS-L/R	Not Necessary	772.40 FL	*- FL
6	1		*TAILGATE INNER LOCK	Serviceable	231.60 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	310.60 FL	*- FL
8	1		*TAILGATE INNER PULL POCKET	Not Necessary	58.80 FL	*- FL
9	1		*TAILGATE W/STRIP	Serviceable	110.90 FL	*- FL
10	2		*TAILGATE STOPPERS	Not Necessary	25.20 FL	*- FL
11	1		*TAILGATE LOCK STRIKER	Not Necessary	41.20 FL	*- FL
12	2		*TAILLAMPS -L/R	Not Necessary	1,676.20 FL	*- FL
13	1		*REAR BUMPER	Dented / Deformed	686.30 FL	*686.30 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	173.20 FL	*- FL
15	2		*REAR BUMPER CHROME MOULDINGS	Not Necessary	179.20 FL	*- FL
16	2		*REAR BUMPER SIDES- L/R	Not Necessary	220.40 FL	*- FL
17	2		*REAR BUMPER PDC SENSORS	Shorted	450.56 FS	*200.00 FS
18	2		*REAR BUMPER SIDE SKIRTS -L/R	Not Necessary	462.40 FL	*- FL
19	1		*REAR END PANEL	Dented	427.90 FL	*427.90 FL
20	1		*REAR END PANEL TRIM	Not Necessary	151.60 FL	*- FL
21	1		*REAR FLOOR MAT	Not Necessary	161.30 FL	*- FL
22	1		*REAR FLOOR PANEL	Not Necessary	1,055.90 FL	*- FL
23	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	155.20 FL	*- FL
24	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
25	1		*SET TAILGATE GLASS FOAM TAPE	Necessary	65.00 FS	*30.00 FS
26	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*40.00 FS
27	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,682.56	2,885.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,718.40	515.10
Total Parts (\$\$)	7,964.16	2,370.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE,REFIX TAILGATE GLASS	New	180.00	120.00
3	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	New	180.00	60.00
4	TO REMOVE ,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	80.00
5	TO RESPRAY UNDERCOATING	New	100.00	60.00
6	TO RESPRAY PAINTING AND ETC	New	1,200.00	850.00
7	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,060.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >