

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001452/EVF3Q2

Date: 18/03/2021

REFERENCE

Insured/Claimant: SAAKE ANGELIKA GOTTFRIEDE MARIA Policy No: 2100486884
Date of Loss: 23/10/2020 Nature of Claim: OD Claim No: 3986397941SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	S1528CD	Engine No:	G4NAGH879467
Make & Model:	KIA SPORTAGE, 2.0 (A)	Chassis No:	KNAPN81AMG7132438
Reg. Date:	20/10/2016 (Man. Year: 2016)	Odometer:	26002 km
Colour:	Silver		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	S\$69,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,402.00	3,043.20	358.80	10.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	2,200.00	1,650.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,252.00	5,243.20	2,008.80	27.70
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,652.00	4,643.20	2,008.80	30.20
+ GST 7.00/7.00% (S\$)	465.64	325.02	140.62	30.20
Nett Amount (S\$)	7,117.64	4,968.22	2,149.42	30.20

INSPECTION

Date of Assignment: 01/02/2021

Date Inspected: 01/02/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-REAR DOOR,LH	Dented	819.00 FL	*819.00 FL
2	1		*PANEL ASSY-FRONT DOOR,LH	Dented	970.00 FL	*970.00 FL
3	1		*GARNISH ASSY-QTR SIDE,LH	Cut	128.00 FL	*128.00 FL
4	1		*GARNISH ASSY-FNDR SIDE LH	Not Necessary	156.00 FL	*- FL
5	1		*COVER-RR BUMPER LWR	Cut	457.00 FL	*457.00 FL
6	1		*GUARD ASSY-REAR WHEEL,LH	Not Necessary	255.00 FL	*- FL
7	1		*WHEEL ASSY-ALUMINIUM	Cut	1,105.00 FL	*1,105.00 FL
8	1		*MOULDING ASSY-SIDE SILL,LH	Cut	265.00 FL	*265.00 FL
9	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
10	1		*BLACK TAPE-FRT DR FRAME DD ORT (Supplementary)	Necessary	7.00 FL	*7.00 FL
11	1		*BLACK TAPE-RR DR FRAME FR OTR (Supplementary)	Necessary	7.00 FL	*7.00 FL
12	1		*FILM-RR DR ANTI CHIPPING,LH (Supplementary)	Necessary	21.00 FL	*21.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,240.00	3,799.00
- List Item Discount on L Items 20.00/20.00% (\$)	838.00	755.80
Total Parts (\$)	3,402.00	3,043.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT LH DOOR,REAR LH DOOR,LH SIDE SILL MOULDING & AFFECTED AREA	New	1,600.00	880.00
2	PAINT WORK FRT LH DOOR,REAR LH DOOR & REAR BUMPER	New	1,050.00	700.00
3	TO REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR	New	120.00	0.00
4	TO TRANSFER FRT LH DOOR ATTACHMENT TO NEW PANEL	New	150.00	120.00
5	TO TRANSFER REAR LH DOOR ATTACHMENT TO NEW PANEL	New	150.00	120.00
6	PERFORM RUST PREVENTION	New	150.00	0.00
7	TO APPLY SEALANT ON AFFECTED AREA	New	120.00	80.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	80.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	120.00
10	TO TRANSFER REAR LH RIM INCLUDING BALANCING	New	50.00	30.00
11	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	180.00	120.00
Gross Labour Cost (\$\$)			3,850.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >