

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21001458/R1QF3Q2

Date: 05/03/2021

REFERENCE

Insured/Claimant: THARMALINGAM KAVINDRAN Policy No: DMPCSNW00009842101

Date of Loss: 28/01/2021

Nature of Claim: OD

Claim No: SNM21D200557/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ2166A**

Make & Model: MERCEDES-BENZ GLA180, 1.6 (A)

Reg. Date: 14/01/2016 (Man. Year: 2015)

Colour: Red

Engine Capacity: 1595 cc

Market Value/New Car Price: S\$87,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 27091030642606

Chassis No: WDC1569422J123873

Odometer: 38123 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Front Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size: 235/50 R18

Rear Left Side: Continental 6 mm

Rear Right Side: Continental 6 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,110.14	5,541.59	2,568.55	31.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,830.00	840.00	31.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,780.14	7,371.59	3,408.55	31.62
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	10,280.14	6,871.59	3,408.55	33.16
+ GST 7.00/7.00% (S\$)	719.61	481.01	238.60	33.16
Nett Amount (S\$)	10,999.75	7,352.60	3,647.15	33.16

INSPECTION

Date of Assignment: 29/01/2021

Date Inspected: 01/02/2021 Inspected At:

Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Mar 2021)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ2166A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHF FENDER WHEEL ARCH MOULDING	Scratched	218.89 FS	*218.89 FS
2	1		*FRONT BUMPER	Scratched	1,388.72 FS	*1,388.72 FS
3	1		*IMPACT ABSORBER	Serviceable	155.41 FS	*- FS
4	4		*SPRING NUT	Not Necessary	14.08 FS	*- FS
5	1		*CENTRAL TOP TRIM BUMPER	Serviceable	72.47 FS	*- FS
6	1		*LHF BUMPER MOULDING	Scratched	82.40 FS	*82.40 FS
7	1		*RHF BUMPER MOULDING (NOT NECESSARY)	Not Consistent With The Impact	82.40 FS	*- FS
8	1		*FRONT CENTRAL BUMPER COVER-SILVER	Broken	653.25 FS	*653.25 FS
9	1		*ENGINE COVER LOWER SUPPORT	Cracked	296.93 FS	*296.93 FS
10	1		*FRONT BUMPER LOWER GRILLE	Serviceable	137.09 FS	*- FS
11	1		*LEFT FRONT BUMPER FOGLAMP COVER	Serviceable	36.60 FS	*- FS
12	1		*COMPANY SIGN	Not Necessary	63.68 FS	*- FS
13	2		*GROMMET	Not Necessary	5.28 FS	*- FS
14	1		*ELECTRICAL WIRING HARNESS	Serviceable	158.99 FS	*- FS
15	1		*OUTER LEFT DISTANCE SENSOR	Scratched	182.48 FS	*182.48 FS
16	1		*LEFT INNER DISTANCE SENSOR	Serviceable	182.48 FS	*- FS
17	1		*SPACER RING (2Pcs)	Necessary (1 Pc only)	12.70 FS	*6.35 FS
18	1		*LICENSE PLATE MOLDING	Cracked	71.25 FS	*71.25 FS
19	1		*LHF ARM SUPPORT	Serviceable	16.62 FS	*- FS
20	1		*CROSS MEMBER	Serviceable	340.68 FS	*- FS
21	1		*LEFT HEADLAMP UNIT	Scratched	2,581.32 FS	*2,581.32 FS
22	1		*RADAR SENSOR	Serviceable	1,250.12 FS	*- FS
23	1		*FIXTURE-RADAR	Serviceable	46.30 FS	*- FS
24	1		*NUMBER PLATE WITH HOUSING	Bent	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 8,110.14 5,541.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHT TOWING FROM 218 SOUTH BRIDGE RD OTR TO PLSC USING KING DOLLEY	New	150.00	150.00
2	REMOVE & REPLACE HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
3	REMOVE & REPLACE ON FRONT BUMPER	New	1,200.00	960.00
4	RESPRAY ON FRONT BUMPER	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,670.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >