

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21001461/GQF3E2

Date: 11/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900247833
Claimant Vehicle No : SMU875C Insured Vehicle No : SKL6843B
Date of Loss: 25/01/2021 Nature of Claim: TP Claim No: 7355924155SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU875C**
Make & Model: MERCEDES-BENZ A180, 1.6 FL STYLE (R17 HLG) (A) Engine No: 27091031273502
Reg. Date: 21/06/2017 (Man. Year: 2017) Chassis No: WDD1760422J598809
Colour: Grey Odometer: 65926 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/02/2021
Date Inspected: 01/02/2021 Inspected At: Hong Autoservices (HQ)
2 KAKI BUKIT AVENUE 2 #01-28 KAKI BUKIT
AUTOHUB
Singapore 417921
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT RH DOOR	Repair	0.00 F	*- F	
2	1		*REAR RH DOOR	Buckled	0.00 F	*- F	
3	1		*REAR RH DOOR GLASS REGULATOR	Damaged	0.00 F	*- F	
4	1		*REAR RH DOOR LOCK	Damaged	0.00 F	*- F	
5	1		*REAR RH DOOR INNER TRIM BOARD	Deformed	0.00 F	*- F	
					Total Parts (\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >