

L.B.S Auto Consultants Pte Ltd (Co.Reg.No:200311321D)

Bik 8, Kensington Park Drive, #01-07

Singapore 557323

Tel: 6283 2666 Fax: 6283 2166 Email: admin@lbs-auto.com

VEHICLE DAMAGE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way #24-01, AXA Tower
Singapore 068811

Our File No: LBS/AXA/17/07/7088

Date: 03/11/2017

REFERENCE

Insured/Claimant: ONG KHIM HWA Policy No: GA226079
Date of Loss: 07/07/2017 Nature of Claim: OD Claim No: C0443512

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJT3664R
Make & Model: TOYOTA PRADO, 2.7 (A) Engine No: 2TR0447847
Reg. Date: 05/07/2007 (Man. Year: 2007) Chassis No: TRJ1205072469
Colour: White Odometer: 132573 km
Engine Capacity: 2693 cc
Market Value/New Car Price: N/A
Sum Insured (\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 265/65R17 Rear Tyre Size: 265/65R17
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,225.00	29,305.00	5,920.00	16.81
Miscellaneous Items	115.00	95.00	20.00	17.39
Labour	6,275.00	4,220.00	2,055.00	32.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	41,615.00	33,620.00	7,995.00	19.21
Approved Total (Overridden) (\$\$)		26,900.00		
- Excess (\$\$)	0.00	900.00	-900.00	
(\$\$)	41,615.00	26,000.00	15,615.00	37.52
+ GST 7.00/7.00% (\$\$)	2,913.05	1,820.00	1,093.05	37.52
Nett Amount (\$\$)	44,528.05	27,820.00	16,708.05	37.52

INSPECTION

Date of Assignment: 12/07/2017 Present Location: ETHOZ Protect Pte Ltd (Bukit Batok)
Date Inspected: 13/07/2017 Inspected At: ETHOZ Protect Pte Ltd (Bukit Batok)
30 Bukit Batok Crescent
Singapore 658075
Estimated Period of Repair: 18.0 days

Adjuster: STAN SEE CHEW SENG

Manager: BENSON LIM

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

POINT OF IMPACT/S

The impact was confined to the rear portion of the vehicle.

REPAIR DETAILS

Reference

Part Source: MRW-SG Version: 1.0 (Last Synchronised: 03 Nov 2017)
 Parts: M1-SUV TOYOTA PRADO 2.7 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: L.B.S Auto Consultants Pte Ltd/SJT3664R/03/11/2017 10:52
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	REPAIR	500.00 F	*.F
2	1		*FRONT BONNET HINGE RH	BENT	85.00 F	*85.00 F
3	1		*FRONT FENDER SEAL UPPER RH	MISSING	40.00 F	*40.00 F
4	1		*FRONT WINDSCREEN	CRACKED	1,700.00 F	*1,700.00 F
5	1		*FRONT WINDSCREEN MOULDING	NECESSARY	270.00 F	*270.00 F
6	1		*FRONT FENDER LH	REPAIR	-	*.F
7	1		*FRONT FENDER RH	BUCKLED	520.00 F	*520.00 F
8	1		*FRONT FENDER GARNISH LH	CUT/DEFORMED	570.00 F	*570.00 F
9	1		*FRONT FENDER GARNISH RH	CUT	570.00 F	*570.00 F
10	1		*FRONT FENDER INNER SHIELD LH	SERVICEABLE	250.00 F	*.F
11	1		*FRONT FENDER INNER SHIELD RH	CIT	250.00 F	*250.00 F
12	1		*FRONT FENDER INNER SEAL RH	NECESSARY	70.00 F	*70.00 F
13	1		*FRONT FENDER MUDFLAP LH	DEFORMED	240.00 F	*240.00 F
14	1		*FRONT FENDER MUDFLAP RH	SERVICEABLE	240.00 F	*.F
15	1		*FRONT DOOR LH	REPAIR	-	*.F
16	1		*FRONT DOOR GARNISH LH	DEFORMED	420.00 F	*420.00 F
17	1		*WING MIRROR LH	REPAIR	-	*.F
18	1		*REAR DOOR LH	REPAIR	-	*.F
19	1		*ROCKER PANEL GARNISH LH	DAMAGED	840.00 F	*840.00 F
20	1		*ROCKER PANEL GARNISH STEP PANEL LH	CUT	350.00 F	*350.00 F
21	1		*FRONT DOOR RH	TORN/BUCKLED	1,800.00 F	*1,800.00 F
22	1		*FRONT DOOR STICKER RH (SET)	NECESSARY	120.00 F	*120.00 F
23	1		*FRONT DOOR HINGE UPPER RH	DISTORTED	150.00 F	*150.00 F
24	1		*FRONT DOOR HINGE LOWER RH	DISTORTED	150.00 F	*150.00 F
25	1		*FRONT DOOR RUBBER RH	NECESSARY	220.00 F	*220.00 F
26	1		*FRONT BODY RUBBER RH	NECESSARY	220.00 F	*220.00 F
27	1		*FRONT DOOR CHECKER RH	BENT	110.00 F	*110.00 F
28	1		*FRONT DOOR GARNISH RH	SERVICEABLE	420.00 F	*.F
29	1		*FRONT DOOR GLASS RH	SMASHED	1,100.00 F	*1,100.00 F
30	1		*FRONT DOOR GLASS RUN CHANNEL RH	CUT	200.00 F	*200.00 F
31	1		*FRONT DOOR GLASS OUTER MOULDING RH	CUT	220.00 F	*220.00 F
32	1		*FRONT DOOR HANDLE OUTER RH	BROKEN	130.00 F	*130.00 F
33	1		*FRONT DOOR LOCK CAP RH	MISSING	55.00 F	*55.00 F
34	1		*FRONT DOOR HANDLE OUTER RH SEAL	NECESSARY	15.00 F	*15.00 F
35	1		*FRONT DOOR LOCK CAP SEAL RH	MISSING	15.00 F	*15.00 F
36	1		*FRONT DOOR HANDLE OUTER BRACKET RH	BENT	110.00 F	*110.00 F
37	1		*FRONT DOOR LOCK RH	HANNED	480.00 F	*480.00 F
38	1		*FRONT DOOR GLASS REGULATOR RH	DISTORTED	400.00 F	*400.00 F
39	1		*FRONT DOOR GLASS REGULATOR MOTOR RH	SHORT CIRCUIT	380.00 F	*380.00 F
40	1		*FRONT DOOR LOCK STRICKER RH	SERVICEABLE	55.00 F	*.F

L.B.S Auto Consultants Pte Ltd/SJT3664R/03/11/2017 10:52. Not valid without Reference section.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT DOOR TRIMBOARD RH	DEFORMED	1,400.00 F	*1,400.00 F
42	1		*WING MIRROR RH	BROKEN	580.00 F	*580.00 F
43	1		*REAR DOOR RH	BUCKLED	1,800.00 F	*1,800.00 F
44	1		*REAR DOOR STICKER RH (SET)	NECESSARY	120.00 F	*120.00 F
45	1		*REAR DOOR HINGE UPPER RH	BENT	150.00 F	*150.00 F
46	1		*REAR DOOR HINGE LOWER RH	SERVICEABLE	150.00 F	*-F
47	1		*REAR DOOR GLASS OUTER MOULDING RH	DAMAGED	220.00 F	*220.00 F
48	1		*REAR DOOR GARNISH RH	CUT	420.00 F	*420.00 F
49	1		*REAR DOOR LOCK RH	JAMMED	480.00 F	*480.00 F
50	1		*REAR DOOR HANDLE OUTER RH	BENT	130.00 F	*130.00 F
51	1		*REAR DOOR LOCK CAP RH	BENT	55.00 F	*55.00 F
52	1		*REAR DOOR GLASS REGULATOR RH	DISTORTED	400.00 F	*400.00 F
53	1		*REAR DOOR GLASS REGULATOR MOTOR RH	SHORT CIRCUIT	380.00 F	*380.00 F
54	1		*REAR DOOR LOCK STRICKER RH	SERVICEABLE	55.00 F	*-F
55	1		*REAR DOOR RUBBER RH	NECESSARY	220.00 F	*220.00 F
56	1		*REAR BODY RUBBER RH	NECESSARY	220.00 F	*220.00 F
57	1		*REAR DOOR TRIMBOARD RH	CUT	900.00 F	*900.00 F
58	1		*REAR FENDER RH	DISTORTED	2,800.00 F	*2,800.00 F
59	1		*REAR FENDER GLASS RH	SERVICEABLE	550.00 F	*-F
60	1		*REAR FENDER GLASS OUTER MOULDING RH	CUT	280.00 F	*280.00 F
61	1		*REAR FENDER GARNISH RH	DEFORMED	850.00 F	*850.00 F
62	1		*A PILLAR OUTER RH	DISTORTED	600.00 F	*600.00 F
63	1		*A PILLAR REINFORCEMENT RH	DISTORTED	400.00 F	*400.00 F
64	1		*CENTRE PILLAR OUTER RH	DISTORTED	600.00 F	*600.00 F
65	1		*CENTRE PILLAR REINFORCEMENT RH	REPAIR	400.00 F	*-F
66	1		*ROOF RACK COVER RH (REAR)	SERVICEABLE	180.00 F	*-F
67	1		*ROCKER PANEL GARNISH RH	DEFORMED	840.00 F	*840.00 F
68	1		*ROCKER PANEL GARNISH STEP PANEL RH	DISTORTED	350.00 F	*350.00 F
69	1		*REAR LAMP RH	BROKEN	400.00 F	*400.00 F
70	1		*ROOF LINING	CUT	1,800.00 F	*1,800.00 F
71	1		*FRONT SEATBELT UPPER GARNISH RH	DEFORMED	280.00 F	*280.00 F
72	1		*FRONT SEATBELT LOWER GARNISH RH	DEFORMED	280.00 F	*280.00 F
73	1		*DASHBOARD	SERVICEABLE	2,650.00 F	*-F
74	1		*ROOF MOULDING RH	SERVICEABLE	90.00 F	*-F
75	1		*AIR COND AIR VENT RH	SERVICEABLE	380.00 F	*-F
76	1		*FRONT DOOR SPEAKER RH	CONNECTOR SNAPPED	550.00 F	*550.00 F

F=Franchise part.

Total Parts (SS) 35,225.00 29,305.00

L.B.S Auto Consultants Pte Ltd/SJT3664R/03/11/2017 10:52. Not valid without Reference section.

NN

No photo see damaged.

NN

No photo see damaged.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	DOOR RIVET (NECESSARY)	40.00	40.00
2	1	IU STICKER (NECESSARY)	15.00	15.00
3	1	WINDSCREEN SEALANT (NECESSARY)	60.00	40.00
Sub Total (S\$)			115.00	95.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILIATE REPAIR	New	2,400.00	2,000.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	35.00	20.00
3	TO SPRAY PAINTING ON AFFECTED AREA	New	2,200.00	1,800.00
4	TO REMOVE & RENEW FRONT WINDSCREEN	New	150.00	120.00
5	TO REMOVE & RENEW ALL R/H/F DOOR COMPONENTS TO FACILIATE REPAIR	New	180.00	50.00
6	TO REMOVE & RENEW ALL R/H/R DOOR COMPONENTS TO FACILIATE REPAIR	New	180.00	50.00
7	TO REMOVE & RENEW REAR FENDER GLASS	New	100.00	0.00
8	TO REMOVE & REFIT ALL NECESSARY TRIMBOARDS, GARNISH, CARPET, FLOOR MATS & SEAT	New	180.00	100.00
9	TO REMOVE & RENEW ROOF LINING TO ASSIST REPAIR	New	200.00	80.00
10	TO REMOVE & RENEW DASHBOARD COMPONENTS	New	250.00	0.00
11	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	New	100.00	0.00
12	TO RESET AIRBAG WARNING LIGHT ON	New	300.00	0.00
Gross Labour Cost (S\$)			6,275.00	4,220.00

L.B.S Auto Consultants Pte Ltd/SJT3664R/03/11/2017 10:52. Not valid without Reference section.

< END OF ESTIMATES >

16 days.