

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001470/DGA3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070007030
Claimant Vehicle No :	GBC2192B	Insured Vehicle No :	SMR7968M
Date of Loss:	29/01/2021	Nature of Claim:	TP
		Claim No:	2842546873SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC2192B	Engine No:	K9KF276D123236
Make & Model:	NISSAN NV200, 1.5 L MT ABS AIRBAG 2WD 6DR (M)	Chassis No:	VSKYBAM20U0022575
Reg. Date:	31/08/2011 (Man. Year: 2011)	Odometer:	291631 km
Colour:	Silver		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,600.63	3,434.12	18,166.51	84.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,150.00	1,150.00	6,000.00	83.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,750.63	4,584.12	24,166.51	84.06
Approved Total (Overridden) (S\$)		3,600.00		

(S\$)	28,750.63	3,600.00	25,150.63	87.48
+ GST 7.00/7.00% (S\$)	2,012.54	252.00	1,760.54	87.48
Nett Amount (S\$)	30,763.17	3,852.00	26,911.17	87.48
+ Car Rental (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,368.45		

INSPECTION

Date of Assignment: 01/02/2021

Date Inspected: 01/02/2021

Estimated Period of Repair: 5.0 days

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT TAILGATE	Not Necessary	1,460.90 FL	*- FL
2	1		*RIGHT TAILGATE DOOR WINDSCREEN MOULDING	Not Necessary	229.30 FL	*- FL
3	1		*RIGHT TAILGATE DOOR WEATHERSTRIP	Serviceable	196.40 FL	*- FL
4	1		*RIGHT TAILGATE DOOR INNER TRIM	Not Necessary	495.40 FL	*- FL
5	2		*RIGHT TAILGATE DOOR HINGE	Not Necessary	190.00 FL	*- FL
6	1		*RIGHT TAILGATE DOOR LOCK	Not Necessary	305.00 FL	*- FL
7	1		*LEFT TAILGATE	Dented	1,681.90 FL	*1,281.10 FL
8	1		*LEFT TAILGATE WINDSCREEN MOULDING	Necessary	253.20 FL	*129.50 FL
9	1		*LEFT TAILGATE NV200 EMBLEM	Necessary	75.00 FL	*75.00 FL
10	1		*LEFT TAILGATE CENTER BLACK MOULDING	Not Necessary	336.00 FL	*- FL
11	2		*LEFT TAILGATE NO.PLATE LAMP LH/RH	Not Necessary	165.80 FL	*- FL
12	1		*LEFT TAILGATE INNER TRIM	Not Necessary	629.30 FL	*- FL
13	1		*LEFT TAILGATE WEATHERSTRIP	Serviceable	206.40 FL	*- FL
14	2		*LEFT TAILGATE HINGE	Bent (1 PCS ONLY)	190.00 FL	*95.00 FL
15	1		*LEFT TAILGATE SWITCH	Not Necessary	318.00 FL	*- FL
16	1		*LEFT TAILGATE LOCK	Not Necessary	305.50 FL	*- FL
17	1		*TAIL LAMP LH/RH	N/S Broken / O/S Not Necessary	873.00 FL	*281.30 FL
18	2		*TAIL LAMP PANEL LH/RH	Not Necessary	846.20 FL	*- FL
19	1		*REAR BUMPER	Distorted / Dented	781.90 FL	*485.90 FL
20	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	150.00 FL	*- FL
21	2		*REAR BUMPER REFLECTOR L+R	Serviceable	130.00 FL	*- FL
22	1		*REAR END PANEL INNER	Not Necessary	982.30 FL	*- FL
23	1		*REAR END PANEL OUTER	Dented	1,098.40 FL	*779.00 FL
24	1		*REAR END PANEL TOP GARNISH	Not Necessary	285.00 FL	*- FL
25	1		*REAR FLOOR PANEL	Not Necessary	1,950.90 FL	*- FL
26	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	1,599.90 FL	*- FL
27	2		*REAR FENDER LH	Not Necessary	2,310.00 FL	*- FL
28	1		*REAR EXHAUST PIPE	Not Necessary	1,350.00 FL	*- FL
29	1		*REAR EXHAUST MOUNTING	Not Necessary	95.00 FL	*- FL
30	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	210.00 FL	*- FL
31	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
32	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*LEFT TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*LEFT TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
35	1		*LEFT TAILGATE WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*RIGHT TAILGATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
37	1		*RIGHT TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
38	1		*RIGHT TAILGATE WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
39	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
42	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*70KM STICKER	Necessary	50.00 FS	*20.00 FS
44	1		*6 PAX STICKER	Not Necessary	50.00 FS	*- FS
45	1		*TAILGATE COMPANY STICKER	Not Necessary	1,000.00 FS	*- FS
46	1		*REAR FENDER COMPANY STICKER	Cut / Necessary	2,000.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	23,570.70	3,746.80
- List Item Discount on L Items 10.00/10.00% (S\$)	1,970.07	312.68
Total Parts (S\$)	21,600.63	3,434.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANSL	New	2,400.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	400.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	300.00	60.00
6	TO RNR REVERSE CAMERA	New	100.00	40.00
7	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	80.00
8	TO RNR REAR BOOT MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
11	TO COMOPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			7,150.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >