

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG21001471/UVF3E2

Date: 12/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001577323

Claimant Vehicle No : SMM6859C

Insured Vehicle No : SKX5924U

Date of Loss: 01/02/2021

Nature of Claim: TP

Claim No: 252835

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM6859C

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B5562750

Reg. Date: 10/07/2019 (Man. Year: 2018)

Chassis No: RU11312736

Colour: Silver

Odometer: 53809 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,983.80	7,949.76	13,034.04	62.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,860.00	3,740.00	2,120.00	36.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,843.80	11,689.76	15,154.04	56.45
Approved Total (Overridden) (S\$)		9,200.00		
(S\$)	26,843.80	9,200.00	17,643.80	65.73
+ GST 7.00/7.00% (S\$)	1,879.07	644.00	1,235.07	65.73
Nett Amount (S\$)	28,722.87	9,844.00	18,878.87	65.73

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 01/02/2021 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM6859C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	88.20 F	*88.20 FL
2	1		*REAR WINDSCREEN	Not Necessary	1,650.00 F	*- FL
3	1		*TAILGATE	Badly Dented	1,100.90 F	*953.00 FL
4	1		*TAILGATE OUTER GARNISH	Twisted/Cracked	315.20 F	*204.80 FL
5	1		*TAILGATE H LOGO	Necessary	32.50 F	*32.50 FL
6	1		*TAILGATE VEZEL EMBLEM	Necessary	56.50 F	*56.50 FL
7	2		*TAILGATE REFLECTORS	Cracked	729.20 F	*553.00 FL
8	1		*TAILGATE INNER LOCK	Bent/Twisted	181.90 F	*166.20 FL
9	1		*TAILGATE LOCK STRIKER	Not Necessary	48.60 F	*- FL
10	1		*TAILGATE INNER TRIM BOARD	Deformed/Cracked	368.20 F	*199.20 FL
11	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
12	1		*TAILGATE INNER HANDLE HOLDER	Not Necessary	32.00 F	*- FL
13	2		*TAILGATE DAMPERS	Not Necessary	385.00 F	*- FL
14	1		*TAILGATE WEATHERSTRIP	Twisted	199.00 F	*102.30 FL
15	1		*REAR BUMPER	Distorted	863.50 F	*549.20 FL
16	2		*REAR BUMPER SIDES	Deformed/Warped	790.20 F	*205.00 FL
17	2		*REAR BUMPER REFLECTORS	Cracked	330.00 F	*302.00 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
19	1		*REAR BUMPER LOWER UNDER COVER	Deformed/Warped	312.00 F	*285.30 FL
20	1		*SET REAR BUMPER LOWER UNDER COVER CLIPS	Necessary	50.00 F	*50.00 FL
21	1		*REAR BUMPER SIDE RETAINERS	O/s Bent	90.00 F	*35.00 FL
22	1		*REAR END PANEL	Badly Dented	517.00 F	*382.70 FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	188.00 F	*122.60 FL
24	2		*TAILLAMPS	Cracked	970.00 F	*824.00 FL
25	2		*TAILLAMP HOUSING PANELS	Repair	700.00 F	*- FL
26	1		*REAR FLOOR PANEL	Crumpled/Buckled	1,330.20 F	*912.30 FL
27	1		*REAR FLOOR PANEL TOP BOARD	Warped	426.50 F	*245.30 FL
28	1		*REAR FLOOR PANEL TOOLS SPONGE	Distorted/Torn	688.00 F	*365.20 FL
29	1		*REAR LOCK SENSOR	Cracked	295.00 F	*105.20 FL
30	1		*REAR FENDERS	O/s Buckled/N/s Repair	1,982.00 F	*891.20 FL
31	2		*REAR FENDER INNER TRIMS	Deformed/Torn	900.00 F	*562.40 FL
32	1		*REAR EXHAUST	Repair	785.20 F	*- FL
33	1		*REAR EXHAUST HEATSHIELD	Bent	188.90 F	*105.30 FL
34	2		*REAR FENDER OUTER PROTECTORS	Torn	598.00 F	*398.20 FL
35	1		*REAR CHASSIS MEMBER O/S	Repair	885.20 F	*- FL
36	1		*REAR DOOR O/S	Repair	905.20 F	*- FL
37	1		*REAR DOOR INNER LOCK O/S	Serviceable	366.50 F	*- FL
38	1		*REAR FLOOR INNER SIDE PANEL O/S	Buckled	425.20 F	*165.60 FL
39	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
40	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
41	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
42	1		*REAR LICENCE PLATE W/HOLDER	Scratched	50.00 FS	*40.00 FS
43	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	180.00 FS	*120.00 FS
44	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
45	1		*SET REAR REVERSE CAMERA	Shorted	450.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
7	TO DISMANTLE & REFIX FUEL TANK	New	100.00	60.00
8	TO SPRAY RUST PROOFING	New	150.00	100.00
9	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,800.00	1,880.00
11	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,300.00
Gross Labour Cost (\$\$)			5,860.00	3,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >