

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21001473/QQF3E2

Date: 20/05/2021

REFERENCE

Insured/Claimant: LEE SIEW CHONG JOHN Policy No: DMPCSNW00170322000

Date of Loss: 02/01/2021

Nature of Claim: OD

Claim No: SNM21D200015C01/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP5Z	Engine No:	20190986S63B44B
Make & Model:	BMW M5,	Chassis No:	WBSFV92020DX98239
Reg. Date:	18/12/2019 (Man. Year: 2014)	Odometer:	11516 km
Colour:	Silver		
Engine Capacity:	4395 cc		
Market Value/New Car Price:	S\$460,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/35ZR20	Rear Tyre Size:	265/35ZR20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,965.00	11,673.00	2,292.00	16.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	2,410.00	3,540.00	59.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,915.00	14,083.00	5,832.00	29.28
- Excess (S\$)	4,000.00	4,000.00	0.00	0.00
Nett Amount (S\$)	15,915.00	10,083.00	5,832.00	36.64

INSPECTION

Date of Assignment: 01/02/2021

Date Inspected: 02/02/2021 Inspected At:

Racetech (HQ)

BLK 1 SIN MING IND ESTATE #01-103

Singapore 575636

Estimated Period of Repair: 6.0 days

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,886.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2021)
Parts:	143	BMW M5 (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP5Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRONT	Crumpled	3,360.00 F	*3,360.00 F
2	3		*CLIPS	Necessary	36.00 F	*36.00 F
3	1		*FOAM SUPPORT	* Check	127.00 F	*- F
4	1		*RETAINER	Broken	36.00 F	*36.00 F
5	1		*HIGH PRESSURE NOZZLE	* Check	183.00 F	*- F
6	1		*MOUNTING FENDER	* Check	73.00 F	*- F
7	1		*BRACKET FENDER	* Check	47.00 F	*- F
8	1		*NUMBER PLATE AND HOLDER	Not Necessary	50.00 F	*- F
9	1		*HEADLAMP ADAPTIVE LED RIGHT	Crumpled	4,724.00 F	*4,724.00 F
10	1		*GASKET	Necessary	130.00 F	*130.00 F
11	4		*DECOUPLING RING	Necessary	64.00 F	*64.00 F
12	1		*SIDE VIEW CAMERA	Crumpled	791.00 F	*791.00 F
13	1		*HOLDER CAMERA	Necessary	23.00 F	*23.00 F
14	1		*BRACKET CAMERA	Necessary	65.00 F	*65.00 F
15	1		*RADIATOR RIGHT	* Check	894.00 F	*- F
16	1		*BRACKET RADIATOR	* Check	107.00 F	*- F
17	4		*GROMMET RADIATOR	* Check	52.00 F	*- F
18	1		*SURROUND (AIR GUARD)	Cracked	203.00 F	*203.00 F
19	1		*FENDER RIGHT	Dented	1,255.00 F	*1,255.00 F
20	1		*SUPPORT BRACKET	Missing	17.00 F	*17.00 F
21	3		*SIDE PANEL BRACKETS	* Check	192.00 F	*- F
22	1		*ENGINE COMPARTMENT SHIELDING FRONT	Cracked	613.00 F	*613.00 F
23	1		*HOLDER	* Check	37.00 F	*- F
24	1		*AIR DUCT RIGHT	* Check	174.00 F	*- F
25	1		*ULTRASONIC SENSOR	O/S Crumpled	712.00 F	*356.00 F
					Total Parts (S\$)	13,965.00 11,673.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TECHNICAL CHARGES TO REPLACE THE ABOVE	New	2,950.00	1,250.00
2	PAINTING	New	1,900.00	700.00
3	RESETTING SYSTEM	New	360.00	360.00
4	RUST PROOFING	New	170.00	50.00
5	TECHNICAL CHARGES TO REPAIR / RECTIFY WIRING	New	570.00	50.00
6	AIR FREIGHT CHARGES (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			5,950.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >