

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File CS/CTI21001473/QQF3E2
No:
Date: 28/06/2022

REFERENCE

Insured/Claimant: LEE SIEW
CHONG JOHN Policy No: DMPCSNW00170322000
Date of Loss: 02/01/2021 Nature of Claim: OD Claim No: SNM21D200015C01/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP5Z**
Make & Model: BMW M5, Engine No: 20190986S63B44B
Reg. Date: 18/12/2019 (Man. Year: 2014) Chassis No: WBSFV92020DX98239
Colour: Silver Odometer: 11516 km
Engine Capacity: 4395 cc
Market Value/New Car Price: S\$460,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35ZR20 Rear Tyre Size: 265/35ZR20
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,585.13	10,566.60	6,018.53	36.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	2,200.00	3,750.00	63.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,535.13	12,766.60	9,768.53	43.35
- Excess (S\$)	4,000.00	4,000.00	0.00	0.00
Nett Amount (S\$)	18,535.13	8,766.60	9,768.53	52.70

INSPECTION

Date of Assignment:

01/02/2021

Date Inspected:

02/02/2021 Inspected At:

Racetech
(HQ)
BLK 1 SIN
MING IND
ESTATE #01-
103
Singapore
575636

Estimated Period of Repair:

6.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2022)
Parts:	143	BMW M5 (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SMP5Z/28/06/2022 14:52	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRONT	Crumpled	3,360.00 F	*2,665.00 F
2	10		*CLIPS	Necessary	36.00 F	*5.50 F
3	1		*FOAM SUPPORT	Cracked	127.00 F	*82.00 F
4	1		*RETAINER }	Broken	221.85 F	*221.85 F
5	1		*MOUNTING FENDER }		0.00 F	*- F
6	1		*BRACKET FENDER }		0.00 F	*- F
7	1		*HIGH PRESSURE NOZZLE	Not Necessary	183.00 F	*- F
8	1		*NUMBER PLATE AND HOLDER	Not Necessary	50.00 F	*- F
9	1		*HEADLAMP ADAPTIVE LED RIGHT }	Crumpled	4,724.00 F	*2,900.00 F
10	1		*GASKET }	Necessary	130.00 F	*- F
11	1		*ULTRASONIC SENSOR }	O/S	712.00 F	*85.00 F
12	4		*DECOUPLING RING }	Crumpled Necessary	64.00 F	*- F
13	1		*SIDE VIEW CAMERA	Crumpled	791.00 F	*720.00 F
14	1		*HOLDER CAMERA }	Necessary	135.00 F	*135.00 F
15	1		*BRACKET CAMERA }	Necessary	0.00 F	*- F
16	1		*RADIATOR RIGHT	Cracked	894.00 F	*480.00 F
17	1		*BRACKET RADIATOR }	Necessary	495.00 F	*495.00 F
18	4		*GROMMET RADIATOR }		0.00 F	*- F
19	1		*SURROUND (AIR GUARD)	Cracked	203.00 F	*140.00 F
20	1		*FENDER RIGHT	Dented	1,255.00 F	*650.00 F

LKK Auto Consultants Pte Ltd/SMP5Z/28/06/2022 14:52. Not valid without Reference section.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
21	1		*SUPPORT BRACKET	Not Necessary	17.00 F	*- F
22	3		*SIDE PANEL BRACKETS	Not Necessary	192.00 F	*- F
23	1		*ENGINE COMPARTMENT SHIELDING FRONT	Cracked	613.00 F	*514.00 F
24	1		*HOLDER	Cracked	45.00 F	*45.00 F
25	1		*AIR DUCT RIGHT	Cracked	174.00 F	*50.00 F

F=Franchise part.

Sub Total (S\$)	14,421.85	9,188.35
+ Margin on L,N Items 15.00/15.00% (S\$)	2,163.28	1,378.25
Total Parts (S\$)	16,585.13	10,566.60

LKK Auto Consultants Pte Ltd/SMP5Z/28/06/2022 14:52. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TECHNICAL CHARGES TO REPLACE THE ABOVE	New	2,950.00	1,250.00
2	PAINTING	New	1,900.00	700.00
3	RESETTING SYSTEM	New	360.00	150.00
4	RUST PROOFING	New	170.00	50.00
5	TECHNICAL CHARGES TO REPAIR / RECTIFY WIRING	New	570.00	50.00
6	AIR FREIGHT CHARGES (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			5,950.00	2,200.00

LKK Auto Consultants Pte Ltd/SMP5Z/28/06/2022 14:52. Not valid without Reference section.

< END OF ESTIMATES >