

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21001474/R1BS3Q2
Date: 18/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : GBG8657S **Insured Vehicle No :** SLM6152U
 Date of Loss: 26/01/2021 Nature of Claim: TP Claim No: MFL2021D0000448

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG8657S**
 Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2756886
 Reg. Date: 20/11/2017 (Man. Year: 2017) Chassis No: JTFAT35Y90K209289
 Colour: Red Odometer: 124405 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C (D)
 Front Left Side: Falken 7 mm Rear Left Side: Falken 5/5 mm
 Front Right Side: Falken 7 mm Rear Right Side: Falken 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	531.25	385.00	146.25	27.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	730.00	500.00	40.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,761.25	1,115.00	646.25	36.69
+ GST 7.00/7.00% (S\$)	123.29	78.05	45.24	36.69
Nett Amount (S\$)	1,884.54	1,193.05	691.49	36.69
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 01/02/2021
 Date Inspected: 19/02/2021 Inspected At: Ethoz Group Ltd (HQ)
 30 Bukit Batok Crescent
 Singapore 658075
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Mar 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG8657S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE PANEL ASSY (NPA)	Not Necessary	0.00 FL	*- FL
2	1		*TAILLAMP BRACKET RH (NPA)	Not Necessary	0.00 FL	*- FL
3	1		*END PANEL (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*TAILLAMP RH	Serviceable	195.00 FL	*- FL
5	1		*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
6	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
7	1		*REAR ADVERTISEMENT STICKER	Necessary	150.00 FS	*150.00 FS
					Sub Total (\$\$)	580.00 385.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	48.75 0.00
					Total Parts (\$\$)	531.25 385.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	600.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	600.00	400.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
Gross Labour Cost (\$\$)			1,230.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >