LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001475/QQF3E2

Date: 28/04/2021

REFERENCE

China Taiping Insurance (Singapore) Handling Insurer: Pte. Ltd.

Policy No:

DMPCSNW00020722100

Claimant Vehicle

Insured Vehicle

SMW6833Z

No:

FBG8155Z

No:

Date of Loss:

26/01/2021

Nature of Claim: TP Claim No:

SNM21D200563/C02

KMYBZ1BLSAC000006

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBG8155Z Reg No:

DAELIM ROADWIN R250, 247cc (M) Make & Model:

VJF250E100336 Engine No:

Reg. Date: Colour: Black

03/12/2012 (Man. Year: 2009) Chassis No: Odometer:

Engine Capacity:

247 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

110/70-17

Pirelli 5 mm

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: Nο

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

Rear Tyre Size: Rear Left Side:

Rear Right Side:

1,531.38

110/70-17

90276 km

Pirelli 5 mm $0 \, \text{mm}$

Front Right Side: 0 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		961.20	794.70	166.50	17.32
Miscellaneous Items		0.00	0.00	0.00	
Labour		470.00	320.00	150.00	31.91
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculate	ed Gross Total (S\$)	1,431.20	1,114.70	316.50	22.11
Approved Tota	l (Overridden) (S\$)		900.00		
	(S\$)	1,431.20	900.00	531.20	37.12
+ G	ST 7.00/7.00% (S\$)	100.18	63.00	37.18	37.11

INSPECTION

Date of Assignment: 01/02/2021

Date Inspected: 01/02/2021 Inspected At: Choong Kok Agency Pte Ltd - Woodlands (HQ)

NO. 280 Woodlands Industrial Park E5, #01-27

568.38

37.12

Harvest @ Woodlands

963.00

Singapore 757322

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN Manager: SHIAU CHAN

Nett Amount (S\$)

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Apr 2021)

Parts: N/A DAELIM ROADWIN R250 247cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBG8155Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR LH	Crushed	70.00 FL	*70.00 FL
2	1		*HANDLE BAR LH	Serviceable	85.00 FL	*- FL
3	1		*SET CLUTCH HOLDER LINER	Bent	65.00 FL	*65.00 FL
4	1		*SIDE FAIRING LH	Cracked	280.00 FL	*280.00 FL
5	1		*CENTRE COVER	Cracked	25.00 FL	*25.00 FL
6	1		*GEAR PEDAL	Bent	105.00 FL	*105.00 FL
7	1		*HANDLE BAR WEIGHT CAP	Scratched	38.00 FL	*38.00 FL
8	1		*EXHAUST PIPE / MUFFLER	Scratched	400.00 FL	*300.00 FL
F=Fra	anchise	part. L=ListIten	nDisc.			
				Sub Total (S\$)	1,068.00	883.00
			- List Item Discount on	L Items 10.00/10.00% (S\$)	106.80	88.30
				Total Parts (S\$)	961.20	794.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	SPRAY COVER	New	150.00	100.00
2	LABOUR	New	250.00	150.00
3	TOWING	New	70.00	70.00
		Gross Labour Cost (S\$)	470.00	320.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >