

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21001476/AGA3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993629
<b>Claimant Vehicle No :</b>	SDT282A	<b>Insured Vehicle No :</b>	SMH9386G
Date of Loss:	31/01/2021	Nature of Claim:	TP
		Claim No:	0052156512SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDT282A</b>	Engine No:	HIDDEN
Make & Model:	AUDI Q3, 2.0 TFSI (A)	Chassis No:	WAUZZZ8U9DR070863
Reg. Date:	30/10/2013 (Man. Year: 2013)	Odometer:	37327 km
Colour:	Bronze		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,228.00	4,653.44	5,574.56	54.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,332.00	3,772.00	4,560.00	54.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,560.00</b>	<b>8,425.44</b>	<b>10,134.56</b>	<b>54.60</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,299.20	589.78	709.42	54.60
<b>Nett Amount (S\$)</b>	<b>19,859.20</b>	<b>9,015.22</b>	<b>10,843.98</b>	<b>54.60</b>
<b>+ Loss of Use (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>9,622.67</b>		

INSPECTION

Date of Assignment:	03/02/2021		
Date Inspected:	03/02/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,107.00 FS	*1,684.40 FS
2	1		*FRONT BUMPER FIXING PARS	Not Necessary	109.00 FS	*- FS
3	1		*FRONT BUMPER SPOILER	Not Necessary	581.00 FS	*- FS
4	1		*FRONT BUMPER TRIM LH	Not Necessary	24.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT LOWER	Not Necessary	176.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE LH	Not Necessary	118.00 FS	*- FS
7	1		*FRONT FENDER LH	Dented	902.00 FS	*721.60 FS
8	1		*FRONT FENDER ATTACHMENT PARTS LH	Not Necessary	70.00 FS	*- FS
9	1		*FRONT FENDER BRACKET LH FRONT	Not Necessary	83.00 FS	*- FS
10	1		*FRONT FENDER BRACE LH	Not Necessary	105.00 FS	*- FS
11	1		*FRONT WHEEL HOUSING LINER LH	Not Necessary	240.00 FS	*- FS
12	1		*WHEEL HOUSING LINER ATTACHMENT PARTS LH	Not Necessary	153.00 FS	*- FS
13	1		*FRONT WHEEL SPOILER LH	Not Necessary	137.00 FS	*- FS
14	1		*HEADLIGHT MOUNTING LH	Cracked	118.00 FS	*94.40 FS
15	1		*HEADLIGHT RETAINER PLATE LH	Not Necessary	87.00 FS	*- FS
16	1		*WEADLIGHT DISCHARGE LH	Not Necessary	2,052.00 FS	*- FS
17	1		*WEADLIGHT WASHER CYLINER LH	Not Necessary	210.00 FS	*- FS
18	2		*FRONT WHEEL ARCH COVER LH/RH	N/S Cut / O/S Necessary	1,056.00 FS	*844.00 FS
19	1		*FRONT ALUMINIUM RIM LH	Cut	1,600.00 FS	*1,280.00 FS
20	1		*SUNDRIES	Necessary	300.00 FS	*29.04 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)** **10,228.00** **4,653.44**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER ,FRONT LOWER SPOILER ,LHS FRONT FENDER ,BOTH FRONT WHEEL ARCH TRIM AND LHS FRONT DOOR	New	4,700.00	2,300.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,332.00</b>	<b>3,772.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >