

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21001480/UPA3Q2

Date: 19/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	GBJ2365H	Insured Vehicle No :	YP9801R
Date of Loss:	29/01/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000606

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2365H	Engine No:	1GD8330357
Make & Model:	TOYOTA HIACE, 2.8 D (A)	Chassis No:	GDH2012002662
Reg. Date:	22/02/2019 (Man. Year: 2018)	Odometer:	70508 km
Colour:	White		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,482.91	5,366.53	5,116.38	48.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,610.00	1,900.00	1,710.00	47.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,092.91	7,266.53	6,826.38	48.44
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	14,092.91	5,800.00	8,292.91	58.84
+ GST 7.00/7.00% (S\$)	986.50	406.00	580.50	58.84
Nett Amount (S\$)	15,079.41	6,206.00	8,873.41	58.84
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,613.45		
Global Sum Settlement (S\$)		6,600.00		

INSPECTION

Date of Assignment:	01/02/2021	
Date Inspected:	01/02/2021 Inspected At:	Automobile Integrated Management Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit

(South Wing)
Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Mar 2021)	
Parts:	N/A	TOYOTA HIACE 2.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2365H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,950.60 FL	*1,950.60 FL
2	1		*TAILGATE GLASS	Shattered	1,286.90 FL	*1,286.90 FL
3	1		*TAILGATE WIPER ARM	Not Necessary	110.25 FL	*- FL
4	1		*TAILGATE WIPER MOTOR	Not Necessary	561.90 FL	*- FL
5	1		*TAILGATE VIEW MIRROR	Not Necessary	481.60 FL	*- FL
6	1		*TAILGATE LOGO	Necessary	68.50 FL	*68.50 FL
7	1		*TAILGATE STICKER HIACE	Necessary	62.60 FL	*62.60 FL
8	1		*TAILGATE OUTER GARNISH	Not Necessary	291.43 FL	*- FL
9	1		*TAILGATE INNER TOP TRIM	Not Necessary	221.41 FL	*- FL
10	1		*TAILGATE INNER TRIM BOARD	Warped	341.66 FL	*341.66 FL
11	1		*TAILGATE INNER LOCK	Not Necessary	312.65 FL	*- FL
12	1		*TAILGATE INNER LOCK ACTUATOR	Not Necessary	296.55 FL	*- FL
13	1		*TAILGATE W/STRIP	Not Necessary	228.45 FL	*- FL
14	2		*TAILGATE DAMPERS-L/R	Not Necessary	482.40 FL	*- FL
15	2		*TAILGATE SIDE STOPPERS -L/R	Not Necessary	97.20 FL	*- FL
16	1		*TAILLAMPS-L/R	O/S Cracked	763.30 FL	*381.65 FL
17	1		*TAILLAMP LOWER GARNISH O/S	Dented	89.95 FL	*89.95 FL
18	1		*TAILLAMP LOWER GARNISH RETAINER -RH	Cracked	42.20 FL	*42.20 FL
19	1		*TAILLAMP FILLER PANEL -RH	Dented	481.90 FL	*481.90 FL
20	1		*REAR BUMPER	Distorted	581.60 FL	*566.10 FL
21	2		*REAR BUMPER SIDE RETAINERS -L/R	Not Necessary	91.00 FL	*- FL
22	1		*REAR BUMPER BRACKETS	O/S Bent	115.40 FL	*28.85 FL
23	1		*REAR END PANEL	Dented	871.30 FL	*629.10 FL
24	1		*REAR END PANEL INNER MEMBER	Repair	552.60 FL	*- FL
25	1		*REAR STEP PANEL	Bent	281.60 FL	*281.60 FL
26	1		*REAR SIDE BODY PANEL -RH	Repair	1,486.60 FL	*- FL
27	1		*REAR SIDE PANEL AIR VENT	Twisted	110.43 FL	*110.43 FL
28	1		*REAR SPARE WHEEL CARRIER	Not Necessary	311.45 FL	*- FL
29	1		*REAR SPARE WHEEL LOCK CATCH	Not Necessary	110.45 FL	*- FL
30	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
31	1		*SET TAILGATE GLASS FOAM TAPE	Necessary	65.00 FS	*30.00 FS
32	1		*REAR WIPER BLADE	Not Necessary	40.00 FS	*- FS
33	1		*REAR STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
34	1		*REAR STICKER 8 PAX	Necessary	10.00 FS	*10.00 FS
35	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
36	1		*SET REAR VIDEO CAM	Shorted	450.00 FS	*300.00 FS
37	1		*SET REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,653.88	6,947.04
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,170.97	1,580.51
Total Parts (\$\$)	10,482.91	5,366.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE,REFIX TAILGATE GLASS	New	180.00	120.00
3	TO TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	New	150.00	60.00
4	TO REMOVE,REFIX REAR REVERSE SENSOR /CAMERA	New	80.00	50.00
5	TO REMOVE,REFIX REAR INTERIOR TRIM TO ASSIST REPAIR	New	120.00	0.00
6	TO REMOVE, REFIX REAR EXHAUST SYSTEMS	New	80.00	0.00
7	TO RESPRAY UNDERCOATING	New	150.00	60.00
8	TO RESPRAY PAINTING AND ETC	New	1,200.00	700.00
9	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	1,600.00	880.00
Gross Labour Cost (\$)			3,610.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >