

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG21001481/ETF3Q2

**Date:** 23/02/2021

### REFERENCE

Insured/Claimant: LEE SHIH HWEI, JOCELYN Policy No: 1900093189  
Date of Loss: 31/01/2021 Nature of Claim: OD Claim No: 2166838710SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML1742T**  
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UHS1380  
Reg. Date: 08/05/2019 (Man. Year: 2018) Chassis No: MMBSTA13AKH001558  
Colour: White Odometer: 34976 km  
Engine Capacity: 1193 cc  
Market Value/New Car Price: S\$55,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,317.00	1,018.69	298.31	22.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	2,510.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,827.00</b>	<b>3,528.69</b>	<b>298.31</b>	<b>7.79</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>267.89</b>	<b>247.01</b>	<b>20.88</b>	<b>7.79</b>
<b>Nett Amount (S\$)</b>	<b>4,094.89</b>	<b>3,775.70</b>	<b>319.19</b>	<b>7.79</b>

### INSPECTION

Date of Assignment: 01/02/2021

Date Inspected: 01/02/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BRACKET,FR BUMPER,LH	Broken	13.00 F	*13.00 FL	
2	1		*GARNISH,FR BUMPER,LH	Cut	127.00 F	*127.00 FL	
3	1		*FENDER,FR LH	Dented	497.00 F	*497.00 FL	
4	1		*HEADLAMP ASSY,LH	Cut	660.00 F	*660.00 FL	
5	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS	
					<b>Sub Total (S\$)</b>	<b>1,317.00</b>	<b>1,317.00</b>
					<b>- List Item Discount on L Items 0.00/23.00% (S\$)</b>	0.00	298.31
					<b>Total Parts (S\$)</b>	<b>1,317.00</b>	<b>1,018.69</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT FENDER LH,REPAIR FRT AIRDAM,FRT BUMPER,FRT DOOR LH	New	900.00	900.00
2	SPRAY PAINT FOR FRT AIRDAN,FRT BUMPER,FRT FENDER LH,FRT DOOR LH	New	1,400.00	1,400.00
3	REMOVE & INSTALL FRT AIRDAM	New	60.00	60.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
			<b>Gross Labour Cost (\$)</b>	<b>2,510.00</b>
				<b>2,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >