

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120**Our File No:** CC3/AIG21001485/ETF3Q2**Date:** 19/02/2021**REFERENCE**

Insured/Claimant:	IGOR RYABCHIKOV	Policy No:	1900017695
Date of Loss:	01/02/2021	Nature of Claim:	OD Claim No: 9595145484SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMJ5913B</b>	Engine No:	4J11AC4847
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0600617
Reg. Date:	13/03/2019 (Man. Year: 2018)	Odometer:	11358 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$99,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 4 mm	Rear Left Side:	Toyo 4 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Toyo 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,086.45	110.86	975.59	89.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,585.00	1,360.00	225.00	14.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,671.45</b>	<b>1,470.86</b>	<b>1,200.59</b>	<b>44.94</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	2,071.45	870.86	1,200.59	57.96
<b>+ GST 7.00/7.00% (S\$)</b>	145.00	60.96	84.04	57.96
<b>Nett Amount (S\$)</b>	<b>2,216.45</b>	<b>931.82</b>	<b>1,284.63</b>	<b>57.96</b>

**INSPECTION**

Date of Assignment: 01/02/2021

Date Inspected: 01/02/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd  
(Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FACE,RR BUMPER	Repair	807.00 FL	*- FL	
2	1		*BRKT,R/BMPR FACE SIDE,LH	Broken	12.00 FL	*12.00 FL	
3	1		*MOULDING,RR BUMPER,LH	Cut	106.00 FL	*106.00 FL	
4	1		*REAR LEFT TYRE	Not Necessary	460.00 FL	*- FL	
5	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS	
					<b>Sub Total (S\$)</b>	<b>1,405.00</b>	<b>138.00</b>
					<b>- List Item Discount on L Items 23.00/23.00% (S\$)</b>	318.55	27.14
					<b>Total Parts (S\$)</b>	<b>1,086.45</b>	<b>110.86</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW REAR REAR BUMPER,REPAIR REAR FENDER LH	New	675.00	450.00
2	SPRAY PAINT FOR REAR BUMPER,REAR FENDER LH	New	700.00	700.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,585.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >