

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21001490/UVF3Q2
Date: 08/06/2021**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/20-410891-CA
Claimant Vehicle No :	FBN8781D	Insured Vehicle No :	FBD9392P
Date of Loss:	29/12/2020	Nature of Claim:	TP
			Claim No: MSC/V/21-000058

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN8781D		
Make & Model:	KTM 1290 ADVENTURE, 1.3	Engine No:	861409017
Reg. Date:	26/12/2018 (Man. Year: 2021)	Chassis No:	VBKV69406JM996514
Colour:	Orange	Odometer:	33911 km
Engine Capacity:	1301 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	150/55Z R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,415.00	2,392.20	1,022.80	29.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	250.00	200.00	50.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,665.00	2,592.20	1,072.80	29.27
Approved Total (Overridden) (S\$)		2,300.00		

Nett Amount (S\$)**3,665.00****2,300.00****1,365.00****37.24**INSPECTION

Date of Assignment: 01/02/2021

Date Inspected: 02/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Dirt Wheel Motor Trading (HQ)
Blk 9004 Tampines Street 93, #01-100
Singapore 528838**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE:NEW PARTS REPLACEMENT

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jun 2021)	
Parts:	N/A	KTM 1290 ADVENTURE 1.3 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN8781D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR (R)	Twisted	176.00 F	*176.00 FL
2	1		*TANK SPOILER (R) SILVER	Cut	732.00 F	*732.00 FL
3	1		*TANK 3D STICKER	Necessary	39.00 F	*39.00 FL
4	1		*SET CRASH BAR /ORANGE	Repair	660.00 F	*- FL
5	1		*SET LUGGAGE SPOILER /ORANGE	Cut	575.00 F	*575.00 FL
6	1		*LUGGAGE CASE (R) ONLY	Cut	970.00 F	*970.00 FL
7	1		*SET LOCK	Necessary	106.00 F	*106.00 FL
8	1		*LUGGAGE CASE 3D STICKER	Scratched	60.00 F	*60.00 FL
9	1		*SET CLUTCH SWITCH ATV	Not Necessary	97.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	3,415.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00
					Total Parts (\$\$)	2,658.00
						2,392.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	250.00	200.00
Gross Labour Cost (\$)			250.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >