

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001492/KGS3Q2
Date: 03/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070150856
Claimant Vehicle No :	SMH1714X	Insured Vehicle No :	SMV9098P
Date of Loss:	28/01/2021	Nature of Claim:	TP
		Claim No:	3281580998SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH1714X	Engine No:	3A92UHL9270
Make & Model:	mitsubishi attrage, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH000671
Reg. Date:	15/01/2019 (Man. Year: 2018)	Odometer:	68477 km
Colour:	Metallic Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	884.80	241.60	643.20	72.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	370.00	330.00	47.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,584.80	611.60	973.20	61.41
+ GST 7.00/7.00% (S\$)	110.94	42.81	68.13	61.41

Nett Amount (S\$)	1,695.74	654.41	1,041.33	61.41
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		856.41		

INSPECTION

Date of Assignment: 01/02/2021

Date Inspected: 02/02/2021

Estimated Period of Repair: 1.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*TAILLAMP LH	Cracked	276.00 FL	*276.00 FL	
2	1		*TAILLAMP PANEL LH	Repair	60.00 FL	*- FL	
3	1		*REAR BUMPER	Repair	708.00 FL	*- FL	
4	1		*REAR BUMPER SIDE RETAINER LH	Distorted	26.00 FL	*26.00 FL	
5	12		*REAR BUMPER CLIPS	Not Necessary	36.00 FL	*- FL	
					Sub Total (\$)	1,106.00	302.00
					- List Item Discount on L Items 20.00/20.00% (\$)	221.20	60.40
					Total Parts (\$)	884.80	241.60

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD ,TO KNOCK & REPAIR REAR INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	300.00	150.00
4	TO SPRAY REAR BUMPER	New	300.00	200.00
			Gross Labour Cost (S\$)	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >