

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 139007130R GS1 Reg. No. 13-3007130-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Re	f: CS/AGI21001495/Dvf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	te: 24/03/2021	
			Co	de: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJS 8387M	Veh. Inspected	SJR 8091X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10008880/JM	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	01/02/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	MR053HY9305121200	Colour	SILVER	
	Odometer	176034 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/50 R15	BRIDGESTONE	5 mm	
	L/H Front Tyre	195/50 R15	BRIDGESTONE	5 mm	
	R/H Rear Tyre	195/50 R15	BRIDGESTONE	5 mm	
	L/H Rear Tyre	195/50 R15	BRIDGESTONE	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	29/01/2021	Inspection Date	01/02/2021	
	Survey held at	JWG INTERNATIONAL PTE LTD			
		10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D. Estimate Days of Repair				

**8 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: