

# PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0111-20-TCA

11 August 2020

## ACCIDENT VEHICLE SURVEY REPORT

Star Universe Service Pte Ltd  
Blk 643 Punggol Central #10-326  
Singapore 820643

### VEHICLE INFORMATION:

Vehicle Reg No.:	GBE5437R	Odometer:	97929km
Make & Model:	Toyota Dyna 3.0	Colour:	White
Chassis number:	KDY2318022383	Date of accident:	30/07/2018
Year of Regn.:	07/01/2016	Date inspected:	01/08/2018
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	06/08/2018

### STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

### TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	3mm/Rovelo	3mm/Rovelo	195R15
Rear:x2	3mm/Yokohama	3mm/Yokohama	155R13

### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.

Please see details as described in the Annex for parts and labour.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

# PAR Automotive Consultancy

## Parts and Labour Assessment

### PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR END PANEL	1	buckled	350.00	350.00 ✓
REAR END PANEL REFLECTOR L/R	2	fractured	207.40	207.40 ✓
REAR END SIDE PANEL L/R <i>RH NHM</i>	2	bent	277.00	<del>277.00</del> 128.50
REAR END SIDE PANEL RUBBER STOPPER L/R <i>RH NHM</i>	2	abraded	78.00	<del>78.00</del> 39.00
REAR NUMBER PLATE BRACKET <i>NHMC</i>	1	bent	291.40	291.40 x
REAR NUMBER PLATE LAMP L/R <i>xHMC</i>	2	fractured	167.50	167.50 x
REAR NUMBER PLATE PANEL	1	buckled	98.00	98.00 ✓
REAR TAILGATE <i>330010</i>	1	buckled	1,367.60	1,367.60 ✓
REAR TAILGATE '1500KG' STICKER <i>2475 07</i>	1	necessary	60.30	60.30 ✓
REAR TAILGATE 'DYNA' STICKER	1	necessary	95.60	95.60 ✓
REAR TAILGATE HINGES	4	bent	303.20	303.20 ✓
REAR TAILGATE SIDE LOCK L/R <i>RH NHM</i>	2	bent	356.00	<del>356.00</del> 178.00
REAR TAILLAMP BRACKET L/R <i>RH NHM</i>	2	bent	190.40	<del>190.40</del> 95.20
REAR TAILLAMP INNER GARNISH L/R <i>NHMC</i>	2	deformed	136.00	136.00 x
REAR TAILLAMP L/R <i>RH xHMC</i>	2	fractured	502.60	<del>502.60</del> 251.30
REAR TAILLAMP LOWER REFLECTOR	2	fractured	116.00	116.00 ✓
REAR TOW HOOK BRACKET	1	repair	65.00	0.00 x

Subtotal before discount S\$ 4,662.00 S\$ 4,597.00

Percentage discount 25% and 25% S\$ 1,165.50 S\$ 1,149.25

Sub-total 1 S\$ 3,496.50 S\$ 3,447.75

REAR END PANEL REFLECTOR RIVET L/R	4	necessary	40.00	<del>40.00</del> 10.00
REAR NUMBER PLATE	1	bent	25.00	25.00 ✓
REAR STEP BRACKET	1	necessary	200.00	200.00 ✓
REAR TAILGATE '13PAX' STICKER	1	necessary	50.00	<del>50.00</del> 10.00
REAR TAILGATE '70KM' STICKER	1	necessary	25.00	<del>25.00</del> 10.00
REAR TAILGATE HINGES PIN & NUT - SET <i>305</i>	4	necessary	80.00	<del>80.00</del> 50.00

Subtotal before discount S\$ 420.00 S\$ 420.00

Sub-total 2 S\$ 420.00 S\$ 420.00

Parts-total S\$ 3,916.50 S\$ 3,867.75

### LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

120.00 ~~60.00~~ 30.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,200.00 ~~1,000.00~~ 200.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,200.00 ~~1,000.00~~ 200.00

To apply anti-rust chemical on repaired and replaced panel.

120.00 ~~90.00~~ 50.00

Labour Total S\$ 2,640.00 S\$ 2,150.00

Parts & Labour Total S\$ 6,556.50 S\$ 6,017.75


1580



Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 5,100.00  
and the recommended number of working days for the repairs is within 6 day(s).

  
B J Loi (I Eng., MIMI, AIRTE)  
Automotive Appraiser

total: 2360.07  
2/s: 3.5k.  
05 Days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: