

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21001499/GVF3E2

Date: 25/06/2021

REFERENCE

Insured/Claimant: DANIEL LIM WEN LONG Policy No: DMPCSNW00087262000

Date of Loss: 25/01/2021

Nature of Claim: OD

Claim No: SNM21D200558C01/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD4678T**

Make & Model: INFINITI Q30, 1.5 D PREM DCT EU6 (A)

Engine No: K9KG481D003883

Reg. Date: 29/06/2018 (Man. Year: 2017)

Chassis No: SJKDAAH15U1056141

Colour: Grey

Odometer: 0 km

Engine Capacity: 1461 cc

Market Value/New Car Price: S\$86,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Rear Tyre Size: 235/50 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,435.00	10,829.91	4,605.09	29.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,440.00	1,190.00	45.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,065.00	12,269.91	5,795.09	32.08
Approved Total (Overridden) (S\$)		9,800.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
Nett Amount (S\$)	17,565.00	9,300.00	8,265.00	47.05

INSPECTION

Date of Assignment: 01/02/2021

Date Inspected: 02/02/2021 Inspected At:

Sin Seng Hong Spray Painting & Service (HQ)

BLK 3022A UBI ROAD 1 #01-53

Singapore 408716

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Jun 2021)	
Parts:	N/A	INFINITI Q30 1.5 D PREM DCT EU6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD4678T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Cracked	1,200.00 FL	*864.50 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Broken	50.00 FL	*50.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	750.00 FL	*- FL
4	1		*FRONT BUMPER INNER FOAM	Not Necessary	280.00 FL	*- FL
5	1		*FRONT BUMPER DAYTIME RUNNING LIGHT LH	Cut	400.00 FL	*363.10 FL
6	1		*FRONT BUMPER DAYTIME RUNNING LIGHT GARR	Distorted	220.00 FL	*220.00 FL
7	1		*FRONT BUMPER LOWER SPLASH COVER	Cut	280.00 FL	*280.00 FL
8	1		*HEADLAMP ASSY LH	Cracked	3,800.00 FL	*3,800.00 FL
9	1		*LH HEADLAMP LOWER BRACKET	Broken	180.00 FL	*86.00 FL
10	1		*FRONT FENDER LH	Buckled	750.00 FL	*750.00 FL
11	1		*FRONT FENDER SPLASH SHIELD	Deformed	220.00 FL	*220.00 FL
12	1		*FRONT FENDER SPLASH SHIELD CLIP	Necessary	80.00 FL	*80.00 FL
13	1		*FRONT FENDER WHEEL ARC GARNISH LH	Missing	600.00 FL	*281.30 FL
14	10		*FRONT LH FENDER WHEEL ARC GARNISH CLIP	Necessary	80.00 FL	*40.00 FL
15	1		*FRONT SPORT RIM LH	Cut	1,400.00 FL	*1,400.00 FL
16	1		*FRONT SHOCK ABSORBER LH	Serviceable	650.00 FL	*- FL
17	1		*FRONT LOWER ARM LH	Serviceable	500.00 FL	*- FL
18	1		*FRONT KNUCKLE ARM LH	Serviceable	580.00 FL	*- FL
19	1		*FRONT WHEEL BEARING W/HUB ASSY LH	Jammed	280.00 FL	*280.00 FL
20	1		*FRONT TYRE LH	Cut	180.00 FS	*120.00 FS
21	1		*FRONT DOOR LH	Repair	1,400.00 FL	*- FL
22	1		*HOOD SWITCH	Not Working	330.00 FL	*330.00 FL
23	2		*RR ABS SENSOR RH / LH	Not Working	1,100.00 FL	*1,100.00 FL
24	2		*BONNET ACTUATOR	Not Working	1,820.00 FL	*1,755.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,130.00	12,019.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,695.00	1,189.99

Total Parts (\$\$)	15,435.00	10,829.91
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE AFFECTED PARTS / AREAS	New	600.00	400.00
2	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS / AREAS	New	600.00	500.00
3	TO REMOVE AND REPLACE DAMAGED LEFT HAND UNDERCARRIAGE AND SUSPENSION PARTS	New	450.00	50.00
4	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	90.00	60.00
5	TO CHECK AFFECTED WIRING AND REFOCUS HEADLAMP BEAMS	New	90.00	30.00
6	LABOUR CHARGES TO REMOVE AND REPLACE PARTS	New	800.00	400.00
Gross Labour Cost (\$\$)			2,630.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >