

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001534/KVF3Q2
Date: 22/03/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00045302001
Claimant Vehicle No : SKG5030M **Insured Vehicle No :** GBJ6072B
 Date of Loss: 28/01/2021 Nature of Claim: TP Claim No: SNM21D200583C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG5030M**
 Make & Model: BMW 320I, 1.6 EFFICIENT DYNAMICS (A) Engine No: A967H877N46B20BA
 Reg. Date: 28/09/2007 (Man. Year: 2007) Chassis No: WBAVA76090NL34627
 Colour: Metallic Light Blue Odometer: 182270 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35R19 Rear Tyre Size: 265/30R19
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	7,674.71	6,408.83	1,265.88	16.49	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,390.00	1,210.00	1,180.00	49.37	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	10,064.71	7,618.83	2,445.88	24.30	
Approved Total (Overridden) (S\$)		6,100.00			
	(S\$)	10,064.71	6,100.00	3,964.71	39.39
	+ GST 7.00/7.00% (S\$)	704.53	427.00	277.53	39.39
	Nett Amount (S\$)	10,769.24	6,527.00	4,242.24	39.39

INSPECTION

Date of Assignment: 01/02/2021
 Date Inspected: 02/02/2021 Inspected At: Optima Werkz Pte Ltd (HQ)
 6 Kung Chong Road
 Singapore 159143
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 Mar 2021)**Parts:** 143 BMW 320I 1.6 EFFICIENT DYNAMICS (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKG5030M)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,100.50 FL	*1,100.50 FL
2	1		*FRONT FENDER LH	Bent	770.85 FL	*770.85 FL
3	1		*FRONT FENDER INNER SHIELD LH	Cracked	124.30 FL	*124.30 FL
4	1		*HEADLAMP LH	Cracked	2,223.80 FL	*1,980.00 FL
5	1		*FRONT RIM LH	Dented	1,039.30 FL	*1,039.30 FL
6	1		*FRONT ABSORBER LH	Bent	584.20 FL	*535.80 FL
7	1		*FRONT LOWER ARM LH	Distorted	299.60 FL	*299.60 FL
8	1		*FRONT UPPER ARM LH	Serviceable	299.60 FL	*- FL
9	1		*FRONT KNUCKLE ARM LH	Bent	478.50 FL	*425.00 FL
10	1		*FRONT WHEEL BEARING LH	Necessary	462.65 FL	*355.00 FL
11	1		*FRONT STABILIZER BAR	Serviceable	472.45 FL	*- FL
12	1		*FRONT STABILIZER LINK LH	Serviceable	107.10 FL	*- FL
13	1		*FRONT BUMPER CLIPS	Necessary	75.00 FS	*75.00 FS
14	1		*FRONT INNER SHIELD CLIPS	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,072.85	6,740.35
- List Item Discount on L Items 5.00/5.00% (S\$)	398.14	331.52
Total Parts (S\$)	7,674.71	6,408.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REFIX,REPLACE,REPAIR & READJUST ACCIDENT AREA	New	1,000.00	400.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA	New	800.00	500.00
3	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	100.00	20.00
4	LABOUR CHARGES TO DISMANTLED & INSTALL UNDERCARRIAGE	New	250.00	200.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
6	TO APPLY ANTI-RUST	New	120.00	30.00
Gross Labour Cost (S\$)			2,390.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >