



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 1698A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	1800 X 900MM FLASHING ARROW C/W TN CONTROLLER BOX	SERVICEABLE	1,350.00	-
3	TN65-11 LED BEACON (3 BOLTS, UNBREAKABLE AMBER LENS) @\$135.00	CRUMPLED	405.00	405.00
1	FABRICATION, INSTALLATION OF METAL FRAME BRACKET, AND WIRING CHARGES FOR ABOVE	BENT	470.00	470.00
1	2400 X 1200MM X 1.5MM "CHEVRON" FLUORESCENT YELLOW GREEN TYPE 11 WIDE ANGLE PRISMATIC REFLECTIVE PANEL C/W WATERMARK	SERVICEABLE	480.00	-
1	INSTALLATION CHARGE FOR ABOVE ONTO YOUR EXISTING TRUCK	NECESSARY	80.00	80.00
1	SUPPLY OF METAL BRACKET FOR ABOVE CHEVRON PLATE	BENT	120.00	120.00
1	1220 X 485MM X 0.9MM "DANGER KEEP CLEAR" ASTM FLO-YELLOW GREEN TYPE XI WIDE ANGLE PRISMATIC REFLECTIVE SIGN PLATE	CRUMPLED	133.00	133.00
1	1220 X 570MM X 0.9MM "SPLIT CHEVRON" ASTM FLO-YELLOW GREEN TYPE XI WIDE ANGLE PRISMATIC REFLECTIVE SIGN PLATE	NECESSARY	148.00	148.00
1	TO LAMINATE 2335 X 735MM ASTM FLO-YELLOW GREEN TYPE XI WIDE ANGLE PRISMATIC REFLECTIVE STICKER ON STRIKE PLATE	BENT	380.00	380.00
1	SAFE-STOP (TMA'S) 180 TRUCK MOUNTED ATTENUATORS (PASSED NCHRP 350 TEST LVL 2 & 3 - 6 TESTS) C/W HYDRAULICS LIFT UP (50%)	CRUMPLED	38,000.00	19,000.00
1	610 X 1220MM LEDS FLASHING ARROW BOARD (4" DIAMETER) (NPA)	NOT NECESSARY	-	-
1	400 SERIES 24V XENON STROBE LIGHT (NPA)	NOT NECESSARY	-	-
			41,566.00	20,736.00
<b><u>LABOUR</u></b>				
TO PROVIDE & INSTALL NEW PAIR UNDERRIDE, WELDING INCLUDING WIRING & LABOUR AND TO INSTALL YOUR EXISTING SAFESTOP SS180 TMA ONTO YOUR NEW TRUCK.			3,250.00	3,250.00
TO ADJUST AND REALIGN THE TMA (NO CHARGE @\$420) (NPA)			-	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WELD, SUPPLY SUPPORTING FRAME, INSTALLATION & WIRING. (NPA)	NOT NECESSARY	-	-
			3,250.00	3,250.00
<b>GRAND TOTAL</b>			<b>44,816.00</b>	<b>23,986.00</b>
<b>RECOMMENDED COST OF REPLACEMENT</b>				<b>23,986.00</b>

Report Ref No. CS3/LPC20012247/Qvf3e2-1

**OI SUN PIN**

**Asst. Automotive Assessor**

**ANG BRYAN TANI**

**Automotive Assessor / Investigator**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.