

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001537/T1GS3Q2
Date: 17/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800120616
Claimant Vehicle No :	SHC2523J	Insured Vehicle No :	SMF529G
Date of Loss:	31/01/2021	Nature of Claim:	TP
		Claim No:	3595913774SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2523J	Engine No:	G4LEKU401812
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU188079
Reg. Date:	07/11/2019 (Man. Year: 2019)	Odometer:	111772 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,926.60	2,726.68	199.92	6.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	1,135.00	145.00	11.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,206.60	3,861.68	344.92	8.20
+ GST 7.00/7.00% (S\$)	294.46	270.32	24.14	8.20

Nett Amount (S\$)	4,501.06	4,132.00	369.06	8.20
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
(S\$)		4,657.57		
Liabe Amount (50.00%) (S\$)		2,328.79		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,330.79		
Global Sum Settlement (S\$)		2,300.00		

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 02/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -FR BUMPER	Cracked	430.90 FL	*430.90 FL
2	10		*BUMPER COVER CLIP REAR	Necessary	22.00 FL	*22.00 FL
3	1		*BRACKET -FR BUMPER SIDE SU	Not Necessary	35.00 FL	*- FL
4	1		*BRACKET -FR BUMPER SIDE RH	Not Necessary	28.00 FL	*- FL
5	1		*MOULDING -FRONT BUMPER RH	Repair	186.90 FL	*- FL
6	1		*LAMP ASSY -HEAD RH	Cracked	1,993.65 FL	*1,993.65 FL
7	1		*PANEL -FENDER RH	Bent	588.80 FL	*588.80 FL
8	1		*EMBLEM -BLUE DRIVE RH	Necessary	26.60 FL	*26.60 FL
9	1		*CAP ASSY -WHEEL HUB	Cut	346.40 FL	*346.40 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	3,658.25
					- List Item Discount on L Items 20.00/20.00% (\$\$)	731.65
					Total Parts (\$\$)	2,926.60
						3,408.35
						681.67
						2,726.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	525.00
2	SPRAYPAINT ON AFFECTED AREA	New	550.00	500.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	ADJUST FRONT WHEEL ALIGNMENT	New	80.00	80.00
Gross Labour Cost (\$)			1,280.00	1,135.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >