

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21001540/UTF3Q2

Date: 01/03/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : GBD8393T

Insured Vehicle No : YP7941H

Date of Loss: 30/01/2021

Nature of Claim: TP

Claim No: CDMCG21000221

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD8393T**

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2478949

Reg. Date: 09/06/2015 (Man. Year: 2014)

Chassis No: JTFAT35Y40K204257

Colour: White

Odometer: 117181 km

Engine Capacity: 2982 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 155R12 (D)

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6/6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,890.40	5,856.13	16,034.27	73.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,680.00	2,150.00	2,530.00	54.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	26,570.40	8,006.13	18,564.27	69.87
Approved Total (Overridden) (\$)		6,400.00		
(S\$)	26,570.40	6,400.00	20,170.40	75.91
+ GST 7.00/7.00% (S\$)	1,859.93	448.00	1,411.93	75.91
Nett Amount (S\$)	28,430.33	6,848.00	21,582.33	75.91

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 02/02/2021 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Mar 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD8393T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	681.60 F	*645.01 FL
2	2		*FRONT BUMPER BRACKETS	Not Necessary	290.20 F	*- FL
3	2		*FRONT BUMPER FOG LAMP GARNISHS	Not Necessary	204.50 F	*- FL
4	2		*HEADLAMPS	Cracked	2,120.20 F	*1,354.20 FL
5	1		*FRONT GRILLE	Cracked	898.40 F	*680.10 FL
6	1		*FRONT GRILLE LOGO	Cracked	105.20 F	*68.50 FL
7	1		*SET FRONT GRILLE CLIPS	Necessary	35.00 F	*35.00 FL
8	1		*FRONT PANEL	Dented	1,842.20 F	*1,299.10 FL
9	1		*FRONT PANEL DYNA EMBLEM	Necessary	62.50 F	*62.50 FL
10	1		*FRONT PANEL TOP BLACK GARNISH	Cracked	266.20 F	*261.10 FL
11	1		*FRONT WINDSCREEN RUBBER	Necessary	285.10 F	*222.50 FL
12	2		*FRONT CORNER PANELS	Not Necessary	770.20 F	*- FL
13	1		*FRONT CENTRE CROSS MEMBER	Bent	650.10 F	*600.90 FL
14	1		*AIR CON BLOWER	Cracked	1,665.10 F	*875.10 FL
15	1		*AIR CON HEATER ASSY	Cracked	1,845.10 F	*1,645.50 FL
16	1		*FRONT CABIN CROSS CENTRE BEAM	Serviceable	688.50 F	*- FL
17	1		*FRONT CABIN FRONT BRACKET	Serviceable	125.30 F	*- FL
18	1		*SET ENGINE WIRE HARNESS	Not Necessary	2,885.00 F	*- FL
19	1		*HORN	Not Necessary	89.30 F	*- FL
20	1		*AIR HOSE	Not Necessary	168.90 F	*- FL
21	2		*FRONT DOORS	Repair	2,710.20 F	*- FL
22	1		*WIPER PANEL GARNISH	Not Necessary	311.20 F	*- FL
23	1		*AIR CON CONTROL UNIT	No such part	350.00 F	*- FL
24	1		*BRAKE BOOSTER PUMP	Not Necessary	1,285.10 F	*- FL
25	1		*FRONT DASHBOARD	Not Necessary	1,355.30 F	*- FL
26	1		*FRONT LICENCE PLATE	Bent	20.00 FS	*14.00 FS
27	1		*FRONT PANEL SEALANT	Not Necessary	50.00 FS	*- FS
28	2		*FRONT DOOR ROC STICKER	Not Necessary	100.00 FS	*- FS
29	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,890.40	7,793.51
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,937.38
Total Parts (\$\$)	21,890.40	5,856.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO REMOVE & REFIX FRONT WIRE HARNESS	New	300.00	0.00
3	TO REMOVE & REFIX FRONT DASHBOARD	New	300.00	200.00
4	TO REMOVE & REFIX BRAKE BOOSTER	New	150.00	0.00
5	TO REMOVE & REFIX FRONT DOOR MECHANISM	New	150.00	0.00
6	TO REMOVE & REPLACED AIR CON BLOWER AND HEATER }	New	280.00	100.00
7	TO REFILL AIR CON GAS }	New	150.00	0.00
8	TO SPRAY RUST PROOFING	New	150.00	60.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
11	TO REMOVE & REFIX FRONT WINDSCREEN	New	120.00	60.00
Gross Labour Cost (S\$)			4,680.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >