

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001546/ETF3E2

Date: 04/03/2021

REFERENCE

Insured/Claimant:	TONY WOO QI LUN	Policy No:	1900001472		
Date of Loss:	02/02/2021	Nature of Claim:	OD	Claim No:	6198600242SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH441P	Engine No:	3A92UHL8844
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AKH000571
Reg. Date:	09/01/2019 (Man. Year: 2018)	Odometer:	33612 km
Colour:	White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,917.45	5,621.10	3,296.35	36.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,060.00	5,015.00	1,045.00	17.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,977.45	10,636.10	4,341.35	28.99
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	14,677.45	10,336.10	4,341.35	29.58
+ GST 7.00/7.00% (S\$)	1,027.42	723.53	303.89	29.58
Nett Amount (S\$)	15,704.87	11,059.63	4,645.24	29.58

INSPECTION

Date of Assignment:	02/02/2021	
Date Inspected:	02/02/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	10.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*PANEL ASSY, FR END	Dented	1,055.00 FL	*1,055.00 FL
3	1		*PANEL, HEADLAMP SUPPORT, UPR	Bent	65.00 FL	*65.00 FL
4	1		*CONDENSER ASSY, A/C REFRIGE	Bent	758.00 FL	*758.00 FL
5	1		*PIPE, A/C CONDENSER OUTLET	Not Necessary	305.00 FL	*- FL
6	1		*MOTOR, COOLING FAN	Not Necessary	479.00 FL	*- FL
7	1		*SHROUD, COOLING FAN	Not Necessary	130.00 FL	*- FL
8	1		*FAN, COOLING, LH	Not Necessary	77.00 FL	*- FL
9	1		*RADIATOR ASSY	Not Necessary	967.00 FL	*- FL
10	1		*PANEL, AIR GUIDE	Broken	112.00 FL	*112.00 FL
11	1		*TANK ASSY, RADIATOR COND	Not Necessary	42.00 FL	*- FL
12	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
13	1		*PANEL, AIR GUIDE, RH	Broken	11.00 FL	*11.00 FL
14	1		*PANEL, AIR GUIDE, LH	Broken	11.00 FL	*11.00 FL
15	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
16	1		*GRILLE, RADIATOR	Broken	554.00 FL	*554.00 FL
17	1		*BRACKET, FR BUMPER, LH	Not Necessary	13.00 FL	*- FL
18	1		*BRACKET, FR BUMPER, RH	Broken	13.00 FL	*13.00 FL
19	1		*GRILLE, FR UNDER	Broken	165.00 FL	*165.00 FL
20	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
21	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
22	1		*COVER, HEADLAMP SUPT PANEL	Broken	62.00 FL	*62.00 FL
23	1		*FACE, FR BUMPER	Broken	703.00 FL	*703.00 FL
24	1		*COVER, FR BUMPER	Crushed	13.00 FL	*13.00 FL
25	1		*BODY KIT, ATTRAGE	Not Necessary	1,643.00 FN	*- FN
26	1		*HEADLAMP ASSY, LH	Broken	660.00 FL	*660.00 FL
27	1		*HEADLAMP ASSY, RH	Broken	660.00 FL	*660.00 FL
28	1		*HINGE, HOOD, LH	Not Necessary	56.00 FL	*- FL
29	1		*HINGE, HOOD, RH	Not Necessary	56.00 FL	*- FL
30	1		*HOOD	Dented	734.00 FL	*734.00 FL
31	1		*INSULATOR, HOOD	Crushed	177.00 FL	*177.00 FL
32	8		*CLIP, HOOD INSULATOR	Necessary	24.00 FL	*24.00 FL
33	1		*LATCH, HOOD	Bent	69.00 FL	*69.00 FL
34	1		*FENDER, FR LH	Dented	497.00 FL	*497.00 FL
35	1		*FENDER, FR RH	Dented	497.00 FL	*497.00 FL
36	2		*EMBLEM ECO	Necessary	34.00 FS	*34.00 FS
37	1		*COVER, FR DECK, RH	Broken	16.00 FL	*16.00 FL
38	1		*GARNISH, FR FENDER RH	Not Necessary	65.00 FL	*- FL
39	1		*GARNISH, FR FENDER LH	Not Necessary	65.00 FL	*- FL
40	1		*GARNISH, FR PILLAR, RH	Broken	30.00 FL	*30.00 FL
41	1		*RIVET, FR BUMPER(6PCS) (Supplementary)	Necessary	30.00 FL	*30.00 FL
42	1		*CLIPS, FR BUMPER (10PCS) (Supplementary)	Necessary	40.00 FL	*40.00 FL
43	1		*DUCT, A/CINR INTAKE (Supplementary)	Broken	131.00 FL	*131.00 FL
44	1		*TANK, WINDSHIELD WASHER (Supplementary)	Crushed	74.00 FL	*74.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	11,492.00	7,284.00
- List Item Discount on L Items 23.00/23.00% (S\$)	2,245.95	1,662.90
- Nett Item Discount on N Items 20.00/20.00% (S\$)	328.60	0.00

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	8,917.45
						5,621.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER FACE, RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR DAMAGE, REPAIR LH FRONT DOOR	New	2,250.00	2,025.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK	New	100.00	100.00
3	TOP UP AIR CON FREE GAS AND CHECK A/CON SYSTEM	New	80.00	80.00
4	TO REMOVE AND INSTALL FRONT BODY KITS	New	80.00	80.00
5	APPLY BODY SEALANT	New	120.00	40.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	PERFORM RUST PREVENTION	New	80.00	40.00
8	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST	New	120.00	120.00
10	PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT AIR DAM, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR, LH FRONT DOOR AND AFFECTED PORTION	New	3,150.00	2,450.00
Gross Labour Cost (S\$)			6,060.00	5,015.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >