

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001547/KGS3Q2
Date: 11/06/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900262018
Claimant Vehicle No :	SKZ8104P	Insured Vehicle No :	SMR4200P
Date of Loss:	31/01/2021	Nature of Claim:	TP
		Claim No:	0060049271SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ8104P	Engine No:	L15B31020512
Make & Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Chassis No:	JHMGK5850GX201454
Reg. Date:	03/02/2016 (Man. Year: 2015)	Odometer:	82695 km
Colour:	Metallic Red		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,517.44	669.68	847.76	55.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	910.00	390.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,817.44	1,579.68	1,237.76	43.93
Approved Total (Overridden) (S\$)		1,250.00		

Adjuster Report

	(S\$)	2,817.44	1,250.00	1,567.44	55.63
	+ GST 7.00/7.00% (S\$)	197.22	87.50	109.72	55.63
	Nett Amount (S\$)	3,014.66	1,337.50	1,677.16	55.63
	+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
	+ Doc/Search Fee (S\$)		2.00		
	Nett Liability (S\$)		1,639.50		

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 03/02/2021

Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR WINDSCREEN MOULDING	Necessary	95.60 FL	*95.60 FL	
2	1		*TAILGATE	Bent	730.60 FL	*730.60 FL	
3	1		*TAILGATE CHROME MOULDING	Serviceable	234.40 FL	*- FL	
4	1		*TAILGATE EMBLEM	Not Necessary	15.70 FL	*- FL	
5	1		*TAILGATE JAZZ LOGO	Necessary	10.90 FL	*10.90 FL	
6	1		*REAR BUMPER	Repair	492.60 FL	*- FL	
7	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	25.00 FL	*- FL	
8	12		*REAR BUMPER CLIPS	Not Necessary	42.00 FL	*- FL	
9	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS	
					Sub Total (\$\$)	1,846.80	837.10
					- List Item Discount on L Items 20.00/20.00% (\$\$)	329.36	167.42
					Total Parts (\$\$)	1,517.44	669.68

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
2	TO REMOVE AND REINSTALL /REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	60.00	60.00
3	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	0.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
5	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD ,TO KNOCK & REPAIR END PANEL ,SPARE TYRE PANELS AND AFFECTED AREAS	New	500.00	300.00
6	TO SPRAY TAILGATE ,REAR BUMPER	New	500.00	400.00
			Gross Labour Cost (S\$)	1,300.00
				910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >