

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21001548/T1QF3E2

Date: 16/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SLF4507E **Insured Vehicle No :** SLH7291X
Date of Loss: 30/01/2021 Nature of Claim: TP Claim No: MFL2021D0000579

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF4507E**
Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4405518
Reg. Date: 26/08/2016 (Man. Year: 2016) Chassis No: RU11205518
Colour: Red Odometer: 95069 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,916.32	5,126.20	2,790.12	35.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,125.00	2,050.00	1,075.00	34.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,041.32	7,176.20	3,865.12	35.01
Approved Total (Overridden) (S\$)		5,700.00		
Nett Amount (S\$)	11,041.32	5,700.00	5,341.32	48.38

INSPECTION

Date of Assignment: 02/02/2021
Date Inspected: 03/02/2021 Inspected At: Manwell Auto (HQ)
1 Kaki Bukit Ave 6 #01-111, Autobay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF4507E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAIL GATE ASSY	Badly Dented / Bent/ Distorted	1,450.70 FL	*1,122.60 FL
2	1	*TAIL GATE LOCK ASSY	Bent / Distorted	167.40 FL	*167.40 FL
3	1	*TAIL GATE LOCK LOWER STRIKER	Bent	22.40 FL	*22.40 FL
4	1	*TAIL GATE VEZEL EMBLEM	Necessary	56.40 FL	*56.40 FL
5	1	*TAIL GATE CENTRE GARNISH	Clip bracket broken	325.00 FL	*290.00 FL
6	1	*TAIL GATE CENTRE GARNISH LOGO	Necessary	28.70 FL	*28.70 FL
7	4	*TAIL GATE CENTRE GARNISH CLIP	Necessary	23.20 FL	*23.20 FL
8	1	*TAIL GATE SIDE REFLECTOR LAMP ASSY LH	Casing cracked	378.60 FL	*280.00 FL
9	2	*TAIL GATE GAS SHOCK STAY LH / RH	Repair	221.00 FL	*- FL
10	1	*TAIL GATE WEATHERSTRIP	Grip channel deformed	198.20 FL	*198.20 FL
11	1	*TAIL GATE TRIM BOARD C/RETAINING CLIP	Inner ribs bent / Deformed	225.50 FL	*225.50 FL
12	1	*TAIL GATE HAND OPEN BEZEL	Bent / Ribs broken	25.80 FL	*25.80 FL
13	1	*TAIL GATE OPEN SWITCH ASSY	Bracket broken	108.50 FL	*108.50 FL
14	1	*REAR WINDSCREEN MOULDING	Necessary	148.20 FL	*148.20 FL
15	1	*REAR WIPER MOTOR	Not Necessary	283.70 FL	*- FL
16	1	*LH TAILLAMP ASSY	Leg bent / cracked	482.40 FL	*482.40 FL
17	1	*LH TAILLAMP SIDE CLIP	Necessary	6.50 FL	*6.50 FL
18	1	*LH TAIL LAMP BASE PANEL	Repair	178.90 FL	*- FL
19	1	*RH TAILLAMP ASSY	Leg bent / Cracked	482.40 FL	*482.40 FL
20	1	*RH TAILLAMP SIDE CLIP	Necessary	6.50 FL	*6.50 FL
21	1	*RH TAIL LAMP BASE PANEL	Repair	178.90 FL	*- FL
22	1	*REAR BUMPER	Dented / Squashed / Deformed	532.10 FL	*532.10 FL
23	2	*REAR BUMPER SIDE COVER LH / RH	Lock tabs bent / Deformed	333.60 FL	*333.60 FL
24	2	*REAR BUMPER SIDE RETAINER LH / RH	Grip tabs broken	114.60 FL	*114.60 FL
25	2	*REAR BUMPER REFLECTOR LH / RH	Casing broken	282.40 FL	*282.40 FL
26	1	*REAR END PANEL	Dented / Bent / Distorted	482.70 FL	*420.00 FL
27	1	*REAR END PANEL TRIM C/W CLIP	Ribs bent / Deformed	145.70 FL	*145.70 FL
28	1	*REAR END PANEL BUZZER	Mounting leg broken	162.80 FL	*162.80 FL
29	1	*SPARE TYRE PANEL	Repair	693.50 FL	*- FL
30	1	*SPARE TYRE PANEL TOP BOARD	Serviceable	194.70 FL	*- FL
31	1	*SPARE TYRE PANEL STYROFOAM TOOL TRAY	Serviceable	232.70 FL	*- FL
32	2	*REAR LICENSE PLATE LAMP LH / RH	Leg bent / Fractured	80.60 FL	*80.60 FL
33	1	*REAR WINDSCREEN GUM	Necessary	80.00 FS	*60.00 FS
34	1	*SET REVERSE SENSOR	Broken / Shorted	280.00 FS	*200.00 FS
35	1	*SET PARKING CAMERA	Not Necessary	580.00 FS	*- FS
36	1	*SET REAR NUMBER PLATE C/FAME	Scraped	70.00 FS	*45.00 FS
37	1	*TAIL GATE SIDE REFLECTOR LAMP ASSY RH	Casing cracked	378.60 FL	*280.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,642.90	6,331.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,726.58	1,205.30
Total Parts (\$\$)	7,916.32	5,126.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND LIGHTING AND RECTIFY FAULTS WHERE NEEDED	New	45.00	30.00
2	TO INSTALL REVERSE SENSORS AND CHECK SENSING FUNCTIONS	New	80.00	30.00
3	TO APPLY ANTI-RUST UNDERCOAT	New	120.00	30.00
4	TO REMOVE AND REINSTALL REAR WINDSCREEN GLASS	New	140.00	120.00
5	TO REMOVE AND TRANSFER TAIL GATE FITTINGS AND ATTACHMENTS TO NEW TAIL GATE	New	120.00	60.00
6	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEATING AFFECTED AND DAMAGED PARTS	New	1,000.00	750.00
7	SPRAY PAINTING CHARGES TO PAINT THE REAR END PANEL, SPARE TYRE PANEL, TAIL GATE, TAIL LIGHT BASE PANELS, REAR BUMPER SIDE COVERS AND NECESSARY AREAS	New	1,500.00	1,000.00
8	TO INSTALL PARKING CAMERA AND CHECK FUNCTIONS	New	120.00	30.00
Gross Labour Cost (\$\$)			3,125.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >