

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001550/EVF3E2

Date: 24/02/2021

REFERENCE

Insured/Claimant:	CHAN HWEE MIN,FELICIA	Policy No:	1900099739		
Date of Loss:	30/01/2021	Nature of Claim:	OD	Claim No:	5240863524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM7878R	Engine No:	4J11AC6616
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0600727
Reg. Date:	24/05/2019 (Man. Year: 2018)	Odometer:	26975 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$102,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,758.00	9,738.94	8,019.06	45.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,370.00	5,020.00	1,350.00	21.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,128.00	14,758.94	9,369.06	38.83
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	23,528.00	14,158.94	9,369.06	39.82
+ GST 7.00/7.00% (S\$)	1,646.96	991.13	655.83	39.82
Nett Amount (S\$)	25,174.96	15,150.07	10,024.89	39.82

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 02/02/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, FR BUMPER	Broken	859.00 F	*859.00 FL
3	1		*GARNISH, FR BUMPER, LH	Not Necessary	48.00 F	*- FL
4	1		*GARNISH, FR BUMPER, RH	Not Necessary	48.00 F	*- FL
5	1		*BRACKET, FR BUMPER SIDE, LH	Broken	18.00 F	*18.00 FL
6	1		*BRACKET, FR BUMPER SIDE, RH	Not Necessary	18.00 F	*- FL
7	1		*EXTENSION, FR BUMPER	Broken	515.00 F	*515.00 FL
8	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 F	*220.00 FL
9	1		*GARNISH, FR BUMPER SIDE	Broken	112.00 F	*112.00 FL
10	1		*COVER, FR BUMPER	Broken	359.00 F	*359.00 FL
11	1		*GARNISH, FR LICENCE PLATE	Broken	23.00 F	*23.00 FL
12	1		*REINFORCEMENT, FR BUMPER	Bent	490.00 F	*490.00 FL
13	1		*BAR, FR BUMPER GUARD	Bent	130.00 F	*130.00 FL
14	1		*REINFORCEMENT, FR BUMPER	Bent	134.00 F	*134.00 FL
15	1		*REINF, FR BUMPER SIDE, RH	Bent	69.00 F	*69.00 FL
16	1		*REINFORCEMENT, FR BMPR SIDE	Not Necessary	22.00 F	*- FL
17	1		*REINF, FR BUMPER SIDE, LH	Bent	60.00 F	*60.00 FL
18	1		*COVER, HEADLAMP SUPT PANEL	Crushed	50.00 F	*50.00 FL
19	1		*COVER, FR BUMPER	Not Necessary	25.00 F	-
20	1		*GRILLE ASSY, RADIATOR	Broken	548.00 F	*548.00 FL
21	1		*BRACKET, RADIATOR GRILLE, LH	Not Necessary	13.00 F	*- FL
22	1		*BRACKET, RADIATOR GRILLE, RH	Not Necessary	17.00 F	*- FL
23	1		*HOOD	Dented	975.00 F	*975.00 FL
24	1		*INSULATOR, HOOD	Crushed	133.00 F	*133.00 FL
25	1		*HINGE, HOOD, RH	Not Necessary	68.00 F	*- FL
26	1		*HINGE, HOOD, LH	Not Necessary	68.00 F	*- FL
27	1		*WEATHERSTRIP, HOOD	Not Necessary	40.00 F	*- FL
28	1		*WEATHERSTRIP, HOOD	Not Necessary	41.00 F	*- FL
29	1		*LATCH, HOOD	Bent	76.00 F	*76.00 FL
30	1		*FENDER, FR LH	Dented	688.00 F	*688.00 FL
31	1		*FENDER, FR RH	Repair	688.00 F	*- FL
32	1		*SHIELD, FR WHEELHOUSE, LH	Not Necessary	164.00 F	*- FL
33	1		*MOULDING, FR BUMPER, LH	Necessary	116.00 F	*116.00 FL
34	1		*MOULDING, FR BUMPER, RH	Necessary	116.00 F	*116.00 FL
35	1		*MOULDING, FR WHEEL ARCH, RH	Necessary	160.00 F	*160.00 FL
36	1		*MOULDING, FR WHEEL ARCH, LH	Necessary	160.00 F	*160.00 FL
37	1		*PANEL, HEADLAMP SUPPORT, UPR	Dented	182.00 F	*182.00 FL
38	1		*PNL, HEADLAMP SUPT, UPR RH	Not Necessary	58.00 F	*- FL
39	1		*PNL, HEADLAMP SUPT, UPR LH	Dented	58.00 F	*58.00 FL
40	1		*PANEL, HEADLAMP SUPPORT, LWR	Not Necessary	107.00 F	*- FL
41	1		*COVER, ENG ROOM UNDER, FR	Not Necessary	348.00 F	*- FL
42	1		*HEADLAMP ASSY, LH	Broken	1,938.00 F	*1,938.00 FL
43	1		*HEADLAMP ASSY, RH	Broken	1,938.00 F	*1,938.00 FL
44	1		*LAMP ASSY, FOG, FR RH	Not Necessary	348.00 F	*- FL
45	1		*TRAY, BATTERY	Not Necessary	27.00 F	*- FL
46	1		*CONDENSER ASSY, A/C REFRIGE	Bent	857.00 F	*857.00 FL
47	1		*HOSE, A/C COMPR DISCHARGE	Not Necessary	191.00 F	*- FL
48	1		*HOSE, A/C COMPR SUCTION	Not Necessary	235.00 F	*- FL
49	1		*PIPE, A/C CONDENSER OUTLET	Not Necessary	262.00 F	*- FL
50	1		*RADIATOR ASSY	Broken	1,091.00 F	*1,091.00 FL
51	1		*TANK ASSY, RADIATOR COND	Not Necessary	103.00 F	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FAN, COOLING, LH	Not Necessary	78.00 F	*- FL
53	1		*FAN, COOLING, LH	Not Necessary	78.00 F	*- FL
54	1		*SHROUD, COOLING FAN	Not Necessary	258.00 F	*- FL
55	1		*MOTOR, COOLING FAN, LH (120W)	Not Necessary	479.00 F	*- FL
56	1		*MOTOR, COOLING FAN, LH (120W)	Not Necessary	479.00 F	*- FL
57	1		*HOSE, RADIATOR, UPR	Not Necessary	58.00 F	*- FL
58	1		*HOSE, RADIATOR, UPR	Not Necessary	27.00 F	*- FL
59	1		*DUCT, A/CLNR INTAKE	Not Necessary	187.00 F	*- FL
60	1		*DUCT, A/CLNR TO THROT BODY	Not Necessary	161.00 F	*- FL
61	1		*BODY ASSY, AIR CLEANER	Not Necessary	146.00 F	*- FL
62	1		*COVER, AIR CLEANER	Not Necessary	156.00 F	*- FL
63	1		*BRACKET, AIR CLEANER	Not Necessary	70.00 F	*- FL
64	1		*BRKT, FR BUMPER SIDE, LWR RH	Broken	5.00 F	*5.00 FL
65	1		*BRKT, FR BUMPER SIDE, LWR LH	Broken	6.00 F	*6.00 FL
66	1		*PANEL, HEADLAMP SUPPORT LH (Supplementary)	Bent	58.00 F	*58.00 FL
67	6		*RIVET, FRONT BUMPER (Supplementary)	Necessary	30.00 F	*30.00 FL
68	1		*COVER, ENG ROOM UNDER, FR (Supplementary)	Broken	348.00 F	*348.00 FL
69	20		*CLIPS (Supplementary)	Necessary	40.00 F	*40.00 FL
70	20		*CLIPS (Supplementary)	Necessary	60.00 F	*60.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,758.00	12,642.00
- List Item Discount on L Items 0.00/23.00% (\$\$)	0.00	2,903.06
Total Parts (\$\$)	17,758.00	9,738.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER LH. REPAIR FRT FENDER RH, FRT DOOR RH & LH, FRT PILLAR LH	New	3,150.00	1,800.00
2	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
3	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT DOOR RH & LH, A-PILLAR LH, FRT SUPPORT PANEL	New	2,800.00	2,800.00
4	TOP UP AIRCON GAS	New	80.00	80.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	SUPPLY FRT NUMBER WITH FRAME	New	50.00	50.00
8	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
Gross Labour Cost (\$\$)			6,370.00	5,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >