

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

WIP No

Company and the second		day key no			
Invoice Name & Address	Owner Name & Vehicle Info				
CHAN HWEE MIN FELICIA	Cust No/Name	KCV11369/CHAN HWEE MIN FELICIA			
	Reg No/Reg Date	And the second of the second o			
APT BLK 233A SUMANG LANE	Date In/Mileage				
#06-345 SINGAPORE 821233	Chassis No	GF7W0600727			
31110AFORE 821233	Engine No	4J11AC6616			
Contact No	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)			
	Colour/Trim	XO4 BLACK / BK BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP NO		
KCV11369	CRDVCH	02/02/2021/ 11:53	BLC	442 / CocoLu		62529	5 : 0/	and the second
The second secon		Description of Good	is / Services		Qty	Unit Price	Disc%	Amount
REPAIR F	T ¹ BUMPER, RT FENDER	BONNET, FRT SUPPOR R RH, FRT DOOR RH &	RT PANEL, FR	T FENDER LH LLAR LH,	4× 450		1	3150.00 800 100.00
E PNT88000	INSTALL	AIRCON CONDEMSOR &	RADIATOR					
								2800.00
SPRAY PA FR1 DOOR	INT FOR F	FRT BUMPER, BONNET, , A-PILLAR LH, FRT/S	FRT ⁴ FENDER I SUPPORT PANEI	RH & LH, 8	X 350			80.00,
A 54900099 TOP UP A	TOCON GAS						de la company	
			- n E	3	П			30.00
CHECK WII A 10028901 TO CARRY	RING & Et	ECTRICAL SYSTEM	SITE OF THE SEALURE					120.00
USING HI	-SCAN PRO) TEST						50.00
M SUNDRY								30.00
SUPPLY F	RT NUMBER	R PLATE WITH FRAME						40.00
M SUNDRY		ACCIDENT DODITION						
	ALANT FOR	R ACCIDENT PORTION						20.00
M SUNDRY								10 at 15
Sundry S SPECIALIS	T 10R							a a
MO-12494	33 ACCIDE	ENT TOWED FROM TAI	SENG AVE TO	CNC PG				R 3
Date 30/	1/2021(Sa	at); Time Start 18.9), Add: Accident \$10	58pm, Time E	nd 19.40pm				
Total Co		. 00			1.00	859 00	00.00	859.00
M FACE, FR					1.00		00.00	ſ
M GARNISH,	FR BUMPE				1.00		00.00	
M GARNISH,	FR BUMPE	R,RH X NN R STDF.LH / OR	_		1.00	18.00	00.00	18.00
		R SIDE, LH / UK R SIDE, RH X NN			1.00	18.00	00.00	18.00
		PER (SIM) - SR			1.00		00.00	
		IDE, LWR RH / BR			1.00	5.00	00.00	5.00
		, 51/					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Reg No : 1977014696

GST Reg No : MR-8500111-X **ESTIMATE** Invoice Name & Address Owner Name & Vehicle Info KCV11369/CHAN HWEE MIN FELICIA CHAN HWEE MIN FELICIA Cust No/Name / 24/05/201 Reg No/Reg Date SMM7878R APT BLK 233A SUMANG LANE Date In/Mileage #06-345 GF7W0600727 Chassis No SINGAPORE 821233 4J11AC6616 Engine No MIT/19MY OUTLANDER 2.0 MODERN (995) Make/Model Contact No / BK BLACK XO4 BLACK Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
			BLC	442 / CocoLu		62529		
KCV11369	CRDVCH	02/02/2021/ 11:53		Colored Color (Colored Colored	Qty	Unit Price	Disc%	Amount
		Description of Good	s / Services	and the state of the particular and the state of the stat	1.00	6.00	00.00	6.00
		IDE, LWR LH / UK	0		1.00	220.00	00.00	220.00
M GARNISH,		,	CO.		1.00	112.00	00.00	112.00
M GARNISH,			OK		1.00	359.00	00.00	359.00
M COVER, FR	BUMPER	(Black) - BR			1.00	23.00	00.00	23.00
M GARNISH,	FR LICENS	SE PLATÉ / BR BUMPER 1 / 07	•		1.00	490.00	00.00	490.00
M REINFORC	EMENT, FR	22 0			1.00	130.00	00.00	130.00
M BAR, FR B	UMPER GUA	ARD ? - BT DT CH	leadky)		1.00	134.00		134.00
M REINFORC	EMENI, FK	BUMPER 2- CI	feadlage)		1.00	69.00		69.00
M REINF, FR	BUMPER 3	TOC, KII	MN		1.00	22.00		22.00
M REINFORCE	EMENI, FR		عرامه) ٦ [1	$\Box^{1.00}$	60.00		60.00
M REINF, FR	BUMPER 2				\$ \f \f. \square		00.00	50.00
M COVER, HE	AULAMP 30	PT PANEL LEGG	COPY FRY		1.00	25.00		25.0
		Change (m)	(C)	111111(9)	((4.60)		00.00	548.0
M GRILLE AS	SST, KAULA	ADTILE III "I A	MAI		1.00		00.00	13.0
M BRACKET,	CADIATOR	ONICLE, CIT	MIN		1.00		00.00	17.0
	ADIATUK	GRILLE, RH - X			1.00	975.00		975.0
	00	- Cly			1.00	133.00		133.0
M INSULATOR		X NN			1.00	68.00	00.00	68.0
M HINGE, HOO	7	2 MM x			1.00	68.00	and the second s	68.0
M HINGE, HOO		1 x NN			1.00	40.00		40.0
M WEATHERST		1 4 MN			1.00	41.00	00.00	41.0
M WEATHERST					1.00	76.00		76.0
M LATCH, HOC		00			1.00	688.00	00.00	688.0
M FENDER, FR		(2)			1.00	688.00	00.00	688.00
M FENDER, FR		ILSE IN 1 XAIN			1.00	164.00		164.0
M SHIELD, FR	K WHEFTHO	OUL JEIL			1.00		00.00	116.0
M MOULDING,	FK BUMPE	A11			1.00		00.00	116.00
M MOULDING,	FK ROWLF	1, 1011			1.00	160.00	00.00	160.00
M MOULDING,	FR WHEEL	ARCH, RI			1.00		00.00	160.00
M MOULDING	FR WHEEL	ARCHITE	- 00		1.00	182.00	00.00	182.00
M PANEL, HEA	AULAMP SU	PPORT, UPR (VAPY)	I X NAI		1.00	58.00	00.00	58.00
M PNL, HEADI	LAMP SUPT	UPR RH (VIII)	- 00		1.00	58.00	00.00	58.00
M PNL, HEADI	LAMP SUPI	UPR LH (Upp") -	(UL)					

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

keg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

The second secon		day was				
Invoice Name & Address	Owner Name & Vehicle Info					
CHAN HWEE MIN FELICIA	Cust No/Name Reg No/Reg Date	KCV11369/CHAN HWEE MIN FELICIA				
APT BLK 233A SUMANG LANE #06-345	Date In/Mileage	0				
SINGAPORE 821233	CITA SOLO III	GF7W0600727 4J11AC6616				
Contact No	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)				
	Colour/Trim	XO4 BLACK / BK BLACK				

Account No	Terms	Date/Time Printed	CSE	Operator	AND RESIDENCE OF STREET	WIP No		
KCV11369	CRDVCH	02/02/2021/ 11:53	BLC	442 / CocoLu		62529		
CV11309	CRUVEN	Description of Goods	Participation of the Commission of the Commissio	and the second second second	Qty	Unit Price	Disc%	Amount
54151			AI		1.00	107.00	00.00	107.0
		//	.~		1.00	348.00	00.00	348.0
M COVER, ENG		0.0			1.00	1938.00		1938.0
M HEADLAMP		ÕÕ			1.00	1938.00		1938.0
M HEADLAMP					1.00	348.00		348.0
M LAMP ASSY		n √ûN			1.00	27.00		27.0
M TRAY, BATT	EKT	C DEEDICE / DI			1.00	857.00		857.0
M CONDENSER	(A551,A/	C REFRIGE O X MN			1.00	191.00		191.0
M HOSE,A/C	COMPR DI	STICK 1 X MM			1.00	235.00		235.0
M HOSE,A/C	COMPENSE	CITON - / WAIAI			1.00	262.00		262.0
PIPE,A/C					$\Box^{1.00}$	1091.00		1091.0
RADIATOR	DADTATO	COND T XTUN	\sim 57	ima	⊃ ₹₹%⊃	103.00		103.0
TANK ASSY		X NKI	211	111(1(1)[7]	 1.00=	78.00		78.0
FAN, COOLI		1 XNNL	ال ا	0 [] [] [] []			00.00	78.0
FAN, COOLI		7 X MA			1.00	258.00	and the second of the second o	258.0
SHROUD, CO	ULING FAI	THE REPORT OF THE PARTY OF THE			1.00	479.00		479.0
MOTOR, COOL	LING FAN,	LH(120W) 1 X MAJ			1.00	479.00		479.0
MOTOR, COOL		? XNN			1.00	58.00	00.00	58.0
HOSE, RADIA		1 X NAI			1.00	27.00	00.00	27.0
HOSE, RADIA		4 .7 A/A1			1.00	187.00	00.00	187.0
DUCT, A/CL	NR INTAKE	T DODY 1 V MAI		8.18	1.00	161.00	Valid All the Mark Table	161.0
DUCT, A/CL	VR TO THE	ROT BODY ? X NAI	Ctou	(LKK)	1.00	146.00	00.00	146.0
BODY ASSY,	AIR CLEA		Jievi	CLINN	1.00	156.00	00.00	156.0
COVER, AIR	CLEANER	- / / / / / /	011	171 7.0000	1.00	70.00	00.00	70.0
BRACKET, AT	IR CLEANE	RIXMM	111	121, 2.00pm				
			01	7- AM AL				
				^				
			Fx	((855 - ?			i	
			_	•				
			ρ	IP				
LKK Auto Co	nsultants h	ence notify	1					
the Renairer	of the follow	wing:	\wedge	1 BL Sy				
 To resurvey be 	efore/after spr	ay painting	ų o					
. To display dar	naged part(s)	during resurvey						
Dane mires 2	re subject to a	rememmen	10	days				
Confirm & ac	cepted by	Without Prejudice" basis	70	Civiy		A1 - A		23,592.0
 No illegal mod 	dification(s) is	allowed		*		Net		1651.4
 Supplemental 	ry item(s) mus	t be resurveyed and			7% GST on	23592.0	U	2002.4
is subject to fi	nal approval I	from Insurance Company				4-1 P	•	25,243.4
9					To	tal Payabl	E	20,210.1
Acknowledged	by Renairer	1						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 3 of 3