

## **CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED** PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

### **ESTIMATE**

GST Reg No : MR-8500111-X

eg No : 197701469G		451 Reg III T III		
Invoice Name & Address	Owner Name & Vehicle Info			
	Cust No/Name	KCV11369/CHAN HWEE MIN FELICIA		
CHAN HWEE MIN FELICIA	Reg No/Reg Date	SMM7878R / 24/05/201		
APT BLK 233A SUMANG LANE	Date In/Mileage	/ 0		
#06-345 SINGAPORE 821233 Contact No	Chassis No	GF7W0600727		
	Engine No	4J11AC6616		
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)		
CONTROL NO	Colour/Trim	XO4 BLACK / BK BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
	///	02/02/2021/ 11:53	BLC	442 / CocoLu		62529		
KCV11369	CRDVCH	Description of Good			Qty	Unit Price	Disc%	Amount
	3650.21	Description of Good	S / Sel vice					3150.00
E PNT88000	T DIMBED	, BONNET, FRT SUPPOR	T PANFI I	FRT FENDER LH				
KENEW FK	DT EENDE	R RH, FRT DOOR RH &	IH. FRT A	PTLLAR LH.				
E PNT88000	KI FENDE	K KII, I'KI DOOK KII G	L. 119 1 100 100					100.00
E PINTOOUUU	LIATOIA	AIRCON CONDEMSOR &	RADIATOR					
E PNT98000	INSIACE	MINCON CONDENSON &						2800.0
CDDQV DQ	INT FOR	FRT BUMPER, BONNET,	FRT FENDE	R RH & LH,				
FRT DOOR	RH & LH	, A-PILLAR LH, FRT S	UPPORT PA	NEL.				00.0
A 54900099		,						80.0
	IRCON GA	S						30.0
A 54900099			П		几一			30.0
CHECK WI	RING & E	LECTRICAL SYSTEM	257	SMI	$)$ 1 $'$ ( $\bigcirc$			120.0
A 10028901			2011		HUC	7		
TO CARRY	OUT DIA	GNOSTIC CHECK USING	HI-SCAN 4	KO IFZI II II C	200			
	-SCAN PR	O TEST						50.0
M SUNDRY		D DI ATE LIZTU EDAME						
	-KI NOWRE	R PLATE WITH FRAME						40.0
M SUNDRY	TALANT FO	D ACCIDENT DODITION						
	ALANI FU	R ACCIDENT PORTION						20.0
M SUNDRY Sundry								
S SPECIALIS	ST.10B							
3 3FLUTALIX	133 ACCIL	ENT TOWED FROM TAI S	SENG AVE T	TO CNC PG				
Date 30	/1/2021(S	Sat); Time Start 18.5	8pm, Time	e End 19.40pm				
Normal	Towing \$5	50, Add: Accident \$10	)					
Total Co					1 00	859.00	ا مم مما	859.0
M FACE, FR	BUMPER				1.00 1.00		00.00	48.0
M GARNISH					1.00		00.00	48 (
M GARNISH					1.00		00.00	18.0
		R SIDE,LH			1.00		00.00	18.0
		R SIDE,RH			1.00		00.00	515.0
	ON, FR BU				1.00		00.00	5.0
M BRKT,FR	ROWNER ?	SIDE,LWR RH						

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

#### **ESTIMATE**

Co Reg No : 197701469G

197701469G	ESTIMATE	GST Reg No : MR-8500111-X		
Invoice Name & Address	Owner Name & Vehicle Info			
	Cust No/Name	KCV11369/CHAN HWEE MIN FELICIA		
CHAN HWEE MIN FELICIA	Reg No/Reg Date	SMM7878R / 24/05/201		
APT BLK 233A SUMANG LANE	Date In/Mileage			
#06-345	Chassis No	GF7W0600727		
SINGAPORE 821233	Engine No	4J11AC6616		
Contact No	Make/Mode1	MIT/19MY OUTLANDER 2.0 MODERN(995)		
	Colour/Trim	XO4 BLACK / BK BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
KCV11369	CRDVCH	02/02/2021/ 11:53	BLC	442 / CocoLu		62529		
KC411303	CRETCH	Description of Goods			Qty	<b>Unit Price</b>	Disc%	Amount
M BRKT.FR	RIIMDED SI	IDE, LWR LH			1.00	6.00	00.00	6.00
M GARNISH,					1.00	220.00		220.00
M GARNISH,					1.00	112.00		112.00
M COVER, FR		( JIDL			1.00	359.00		359.00
	FR LICENS	SF DI ATF			1.00	23.00	00.00	23.00
	EMENT,FR				1.00	490.00		490.00
	UMPER GU/				1.00	130.00		130.00
	EMENT, FR				1.00	134.00		134.00
	BUMPER				1.00		00.00	69.00
		BMPR SIDE			1.00		00.00	22.00
	BUMPER		П		1.00		00.00	60.00
		UPT PANEL			J.90		00.00	50.00
M COVER, FR			5		1.(0 <del>0</del>		00.00	25.00
	SSY,RADI	ATOR L	O) (L	ima	(4.b)		00.00	548.00
		GRILLE, LH			1.00		00.00	13.00
		GRILLE, RH			1.00		00.00	17.00
M HOOD		·			1.00		00.00	975.00
M INSULATO	R.HOOD				1.00		00.00	133.00
M HINGE, HO	-				1.00		00.00	68.00
M HINGE, HO					1.00		00.00	68.00
	TRIP, HOO	D			1.00	40.00		40.00
	TRIP, HOO				1.00	41.00		41.00 76.00
M LATCH, HO					1.00	76.00		688.00
M FENDER, F	R LH				1.00	688.00		688.00
M FENDER, F	R RH				1.00		00.00	164.00
M SHIELD, F	R WHEELH	OUSE,LH			1.00		00.00	116.00
M MOULDING	FR BUMP	ER,LH			1.00			116.00
	FR BUMP				1.00		00.00	160.00
		L ARCH,RH			1.00	160.00		160.00
		L ARCH,LH			1.00	182.00		182.00
		UPPORT,UPR			1.00 1.00	58.00	1	58.00
M PNL,HEAD	DLAMP SUP	T,UPR RH			1.00	58.00		58.00
M PNL,HEAD	OLAMP SUP	T,UPR LH			1.00	30.00	30.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after month beautiful and another than the standard and the sta after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# **CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED** PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

#### **ESTIMATE**

eg No : 197701469G	ESTIMATE	GST Reg No : MR-850011
Invoice Name & Address		Owner Name & Vehicle Info
	Cust No/Name	KCV11369/CHAN HWEE MIN FELICIA
CHAN HWEE MIN FELICIA	Reg No/Reg Date	SMM7878R / 24/05/201
APT BLK 233A SUMANG LANE	Date In/Mileage	/ 0
#06-345	Chassis No	GF7W0600727
SINGAPORE 821233	Engine No	4J11AC6616
Contact No	Make/Mode1	MIT/19MY OUTLANDER 2.0 MODERN(995)
politing a 110	Colour/Trim	XO4 BLACK / BK BLACK

ccount No	Terms	Date/Time I	Printed	CSE	Operator		WIP No		
CV11369	CRDVCH	02/02/2021	/ 11:53	BLC	442 / CocoLu		62529		
		Descriptio	n of Goods	/ Services		Qty	Unit Price		Amount
PANEL, HE	ADLAMP SI	JPPORT,LWR				1.00	107.00		107.00
1 COVER, EN						1.00	348.00 1938.00		348.00 1938.00
MEADLAMP	ASSY,LH					1.00	1938.00		1938.00
I HEADLAMP						1.00 1.00	348.00		348.00
I LAMP ASS		RH				1.00		00.00	27.00
TRAY, BAT		/c permice				1.00	857.00		857.00
		/C REFRIGE				1.00	191.00		191.00
HOSE,A/C HOSE,A/C						1.00	235.00		235.00
I HOSE,A/C	COMPENS	ER OUTLET				1.00	262.00	00.00	262.00
1 PIPE,A/C 1 RADIATOR		LIC OUTLL!		_ D	1	1.00	1091.00		1091.0
	Y,RADIAT	OR COND			ima	1.00		00.00	103.00
FAN.COOL	-			5111		1.00		00.00	78.00
1 FAN, COOL				<i>의</i> 년 L		7 (7.96)		00.00	78.0
	OOLÍNG F	AN				1.00		00.00	258.00 479.00
MOTOR,CO	OLING FA	N,LH(120W)				1.00		00.00	479.0
1 MOTOR,CC	OLING FA	N,LH(120W)				1.00		00.00	58.0
	IATOR,UP					1.00 1.00	27.00		27.0
	IATOR, UP					1.00	187.00		187.0
	LNR INTA					1.00		00.00	161.0
		HROT BODY				1.00		00.00	146.0
	SY,AIR CL					1.00		00.00	156.0
	R CLEANE					1.00		00.00	70.0
1 BRACKET,	AIR CLEA	MEK							
Confirm &	accepted	by					Na Na	ett	23,592.
						7% GST o			1651.
							Total Payal	ole	25,243.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include Estimated costs quoted are excluding usl. We would mention that the above estimate is pased on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.