

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21001552/ATD3E2

**Date:** 11/08/2021

### REFERENCE

Insured/Claimant: LOW POOI FONG Policy No: 2100365393  
Date of Loss: 18/01/2021 Nature of Claim: OD Claim No: 9829512599SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFP3193B**  
Make & Model: AUDI A3, 999cc SEDAN TFSI (A) Engine No: CXS052756  
Reg. Date: 25/02/2014 (Man. Year: 2013) Chassis No: WAUZZZ8V0E1014142  
Colour: Silver Odometer: 49669 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$44,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,666.00	2,600.00	1,066.00	29.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,602.00	1,822.00	2,780.00	60.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,268.00</b>	<b>4,422.00</b>	<b>3,846.00</b>	<b>46.52</b>
<b>- Excess (S\$)</b>	<b>1,100.00</b>	<b>1,100.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>7,168.00</b>	<b>3,322.00</b>	<b>3,846.00</b>	<b>53.66</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>501.76</b>	<b>232.54</b>	<b>269.22</b>	<b>53.66</b>
<b>Nett Amount (S\$)</b>	<b>7,669.76</b>	<b>3,554.54</b>	<b>4,115.22</b>	<b>53.66</b>

### INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 28/01/2021 Inspected At:

24 Benoi Sector

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*EXTERIOR MIRROR MOUNTING - RH	Cut	1,024.00 FS	*819.20 FS	
2	1		*MIRROR CAP - RH	Repair	169.00 FS	*- FS	
3	1		*MIRROR GLASS - RH	Missing	1,687.00 FS	*1,349.60 FS	
4	1		*FRONT DOOR WINDOW - RH	Cut	231.00 FS	*184.40 FS	
5	1		*FRONT WINDOW SLOT SEAL - RH	Cut	309.00 FS	*246.80 FS	
6	1		*CORNER TRIM - RH	Not Necessary	46.00 FS	*- FS	
7	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS	
					<b>Total Parts (\$)</b>	<b>3,666.00</b>	<b>2,600.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO INSTALL SOLAR FILM ON RHS FRONT DOOR WINDOW GLASS	New	400.00	400.00
2	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY	New	280.00	280.00
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	250.00
4	TO RESPRAY RHS FRONT DOOR, RHS WING MIRROR COVER, RHS FRONT FENDER	New	2,400.00	700.00
5	TO TOW VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (\$)</b>	<b>1,822.00</b>
			<b>4,602.00</b>	<b>1,822.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >