

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001557/T1PA3Q2**Date:** 27/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900057751
Claimant Vehicle No :	SMG5378L	Insured Vehicle No :	SGV5357P
Date of Loss:	31/01/2021	Nature of Claim:	TP
		Claim No:	8905862525SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG5378L	Engine No:	G4LEJU167553
Make & Model:	HYUNDAI AE IONIQ HEV DCT SR, 1.6 (A)	Chassis No:	KMHC851CVKU133989
Reg. Date:	26/12/2018 (Man. Year: 2018)	Odometer:	50849 km
Colour:	Red		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,979.44	18,135.04	14,844.40	45.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,500.00	4,220.00	8,280.00	66.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,479.44	22,355.04	23,124.40	50.85
Approved Total (Overridden) (S\$)		17,800.00		
(S\$)	45,479.44	17,800.00	27,679.44	60.86
+ GST 7.00/7.00% (S\$)	3,183.56	1,246.00	1,937.56	60.86
Nett Amount (S\$)	48,663.00	19,046.00	29,617.00	60.86
+ Car Rental (13.0 x S\$100.00/day + 7.00% GST) (S\$)		1,391.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		20,444.45		
Global Sum Settlement (S\$)		20,200.00		

INSPECTION

Date of Assignment:	02/02/2021		
Date Inspected:	03/02/2021	Inspected At:	AP Automotive Services Pte Ltd (HQ) Blk 9006 Tampines Street 93, #01-202 Singapore 528840
Estimated Period of Repair:	12.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,253.00 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	198.00 FL	*- FL
3	1		*BONNET HINGE L+R	Not Necessary	64.00 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	137.00 FL	*- FL
5	1		*BONNET LOCK CATCH	Not Necessary	68.00 FL	*- FL
6	1		*BONNET INNER RUBBER STRIP L+R	Not Necessary	35.00 FL	*- FL
7	1		*BONNET INNER RUBBER STRIP CENTER	Not Necessary	101.00 FL	*- FL
8	2		*HEADLAMP L+R	Cracked	2,396.00 FL	*2,396.00 FL
9	2		*HEADLAMP BRACKET L+R	Cracked	130.00 FL	*130.00 FL
10	1		*FRONT GRILLE ASSY	Cracked	1,409.00 FL	*1,409.00 FL
11	1		*FRONT GRILLE LOGO -HYUNDAI	Cut	49.00 FL	*49.00 FL
12	1		*FRONT GRILLE TOP GARNISH	Deformed	55.00 FL	*55.00 FL
13	1		*FRONT GRILLE TOP GARNISH RUBBER SEAL	Not Necessary	35.00 FL	*- FL
14	1		*FRONT BUMPER	Deformed	418.00 FL	*418.00 FL
15	1		*FRONT BUMPER GRILLE LOWER GRILLE	Deformed	115.00 FL	*115.00 FL
16	1		*FRONT BUMPER FOG LAMP L+R	N/S Cracked / O/S Not Necessary	970.00 FL	*485.00 FL
17	2		*FRONT BUMPER FOG LAMP GRILLE L+R	Not Necessary	130.00 FL	*- FL
18	2		*FRONT BUMPER FOG LAMP GARNISH L+R	N/S Cracked / O/S Cut	84.00 FL	*84.00 FL
19	1		*FRONT BUMPER LOWER LIP	Not Necessary	45.00 FL	*- FL
20	2		*FRONT BUMPER RETAINER L+R	Deformed	58.00 FL	*58.00 FL
21	1		*FRONT BUMPER REINFORCEMENT BAR	Bent	650.00 FL	*650.00 FL
22	1		*FRONT BUMPER BEAM	Not Necessary	78.00 FL	*- FL
23	1		*FRONT BUMPER SPONGE	Cracked	105.00 FL	*105.00 FL
24	1		*FRONT BUMPER UNDERCOVER	Torn	335.00 FL	*235.00 FL
25	2		*FRONT FENDER L+R	Not Necessary	1,176.00 FL	*- FL
26	2		*FRONT FENDER COWLING L+R	Torn	229.40 FL	*229.40 FL
27	1		*FRONT SUPPORT PANEL	Cracked	949.00 FL	*949.00 FL
28	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	85.00 FL	*- FL
29	1		*AIRCON CONDENSOR	Dented	560.00 FL	*560.00 FL
30	2		*AIRCON CONDENSOR AIR GUIDE L+R	Deformed	49.00 FL	*49.00 FL
31	1		*HIGH PRESSURE HOSE	Dented	380.00 FL	*380.00 FL
32	2		*LOW PRESSURE HOSE	Not Necessary	320.00 FL	*- FL
33	1		*RADIATOR	Not Necessary	510.00 FL	*- FL
34	1		*SUCTION PIPE (NPA)	Not Necessary	0.00 FL	*- FL
35	1		*DISHCHARGE PIPE (NPA)	Not Necessary	0.00 FL	*- FL
36	1		*RADIATOR COWLING	Not Necessary	363.00 FL	*- FL
37	1		*RADIATOR FAN BLADE (NPA)	Not Necessary	0.00 FL	*- FL
38	1		*RADIATOR SPARE TANK	Not Necessary	57.00 FL	*- FL
39	2		*ALTERNATOR	Not Necessary	1,430.00 FL	*- FL
40	2		*FRONT HORN	Cracked	216.00 FL	*216.00 FL
41	1		*WIPER WASHER TANK	Not Necessary	191.00 FL	*- FL
42	1		*REAR WINDSCREEN MOULDING	Necessary	850.00 FL	*240.50 FL
43	1		*BOOTLID	Bent	2,480.00 FL	*2,480.00 FL
44	1		*BOOTLID SPOILER (NPA)	Not Necessary	0.00 FL	*- FL
45	1		*BOOTLID WINDSCREEN (NPA)	Not Necessary	0.00 FL	*- FL
46	1		*BOOTLID WINDSCREEN MOULDING (NPA)	Not Necessary	0.00 FL	*- FL
47	1		*BOOTLID LOGO -HYUNDAI	Necessary	48.00 FL	*48.00 FL
48	1		*BOOTLID LOGO GARNISH	Not Necessary	46.00 FL	*- FL
49	1		*BOOTLID SWITCH	Not Necessary	468.00 FL	*- FL
50	1		*BOOTLID EMBLEM -IONIQ	Necessary	31.30 FL	*31.30 FL
51	1		*BOOTLID EMBLEM -HYBRID	Necessary	24.60 FL	*24.60 FL
52	2		*BOOTLID LAMP L+R	Cracked	1,588.00 FL	*1,588.00 FL
53	1		*BOOTLID LOCK	Bent	147.00 FL	*147.00 FL
54	1		*BOOTLID LOCK CATCH	Not Necessary	53.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	2		*BOOTLID INNER TRIM TOP L+R	Not Necessary	58.00 FL	*- FL
56	1		*BOOTLID INNER BOARD	Deformed	126.00 FL	*126.00 FL
57	1		*BOOTLID INNER BOARD INNER COVER L+R	N/S Not Necessary /O/S Deformed	56.00 FL	*28.00 FL
58	2		*BOOTLID INNER HANDLE	Not Necessary	38.00 FL	*- FL
59	2		*BOOTLID HINGE L+R	Not Necessary	164.00 FL	*- FL
60	1		*BOOTLID WEATHERSTRIP	Cut	27.00 FL	*27.00 FL
61	1		*BOOTLID TONNEAU COVER (NPA)	Not Necessary	0.00 FL	*- FL
62	2		*TAIL LAMP L+R	Cracked	1,740.00 FL	*1,740.00 FL
63	2		*TAIL LAMP PANLE L+R	Repair	282.00 FL	*- FL
64	1		*REAR BUMPER	Deformed	489.00 FL	*489.00 FL
65	1		*REAR BUMPER CENTER GARNISH	Deformed	270.00 FL	*155.00 FL
66	4		*SET REAR BUMPER REVERSE SENSOR	Not Working	528.00 FL	*528.00 FL
67	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Torn	162.00 FL	*162.00 FL
68	1		*REAR BUMPER REFLECTOR L+R	N/S Not Necessary / O/S Cut	76.00 FL	*38.00 FL
69	2		*REAR BUMPER NUMBER PLATE LAMP L+R	Distorted	80.00 FL	*80.00 FL
70	1		*REAR BUMPER LOWER LIP	Cut	48.00 FL	*48.00 FL
71	2		*REAR BUMPER RETAINER L+R	Necessary	66.00 FL	*66.00 FL
72	2		*REAR BUMPER BRACKET L+R	Not Necessary	210.00 FL	*- FL
73	1		*REAR BUMPER REINFORCEMENT BAR	Cracked	238.00 FL	*238.00 FL
74	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
75	1		*REAR BUMPER UNDERCOVER	Torn	38.00 FL	*38.00 FL
76	1		*REAR FENDER L+R	N/S Repair / O/S Bent	2,456.00 FL	*1,228.00 FL
77	2		*REAR FENDER INNER TRIM L+R	Torn	396.00 FL	*396.00 FL
78	2		*REAR FENDER COWLING L+R	Not Necessary	110.00 FL	*- FL
79	2		*REAR FENDER AIRVENT L+R	Not Necessary	96.00 FL	*- FL
80	1		*END PANEL	Bent	532.00 FL	*532.00 FL
81	1		*END PANEL TOP GARNISH	Deformed	65.00 FL	*65.00 FL
82	1		*REAR SMART LOCK ANTENNA	Cracked	45.00 FL	*45.00 FL
83	1		*SPAREWHEEL PANEL	Bent	350.00 FL	*350.00 FL
84	1		*SPAREWHEEL PANEL TOP BOARD	Deformed	90.00 FL	*90.00 FL
85	1		*SPAREWHEEL PANEL ACCESSORIES TRAY L+R	Deformed	85.00 FL	*85.00 FL
86	1		*SPAREWHEEL PANEL ACCESSORIES TRAY CENTER	Deformed	265.00 FL	*265.00 FL
87	1		*SPAREWHEEL PANEL SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
88	1		*EXHAUST PIPE	Bent	572.00 FL	*572.00 FL
89	2		*EXHAUST MOUNTING	Deformed	52.00 FL	*52.00 FL
90	1		*EXHAUST HEAT SHIELD	Bent	48.00 FL	*48.00 FL
91	1		*REAR DOOR RH	Repair	1,789.00 FL	*- FL
92	1		*REAR DOOR LOCK RH	Not Necessary	140.00 FL	*- FL
93	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	113.00 FL	*- FL
94	1		*REAR DOOR INNER WEATHERSTRIP RH	Not Necessary	159.00 FL	*- FL
95	1		*FAN BLADE ECU	Cracked	225.00 FL	*225.00 FL
96	1		*BONNET INSULATOR CLIPS	Not Necessary	100.00 FS	*- FS
97	1		*FRONT GRILLE TOP GARNISH CLIPS	Necessary	100.00 FS	*10.00 FS
98	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
99	1		*FRONT NUMBER PLATE	Bent	120.00 FS	*45.00 FS
100	1		*FRONT FENDER COWLING CLIPS	Necessary	200.00 FS	*10.00 FS
101	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
102	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS
103	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
104	1		*BOOTLID SPOILER CLIPS	Not Necessary	100.00 FS	*- FS
105	1		*BOOTLID WINDSCREEN SEALANT	Necessary	120.00 FS	*30.00 FS
106	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	300.00 FS	*- FS
107	1		*REVERSE CAMERA	Not Necessary	850.00 FS	*- FS
108	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
109	2		*TAIL LAMP PANEL SEALANT	Not Necessary	240.00 FS	*- FS
110	1		*REAR NUMBER PLATE	Missing	120.00 FS	*45.00 FS
111	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
112	2		*REAR FENDER SEALANT	Necessary	500.00 FS	*60.00 FS
113	1		*REAR FENDER INNER TRIM CLIPS	Necessary	200.00 FS	*30.00 FS
114	1		*REAR FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
115	1		*END PANEL SEALANT	Necessary	250.00 FS	*40.00 FS
116	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*10.00 FS
117	1		*SPARE WHEEL PANEL SEALANT	Necessary	300.00 FS	*60.00 FS
118	1		*FRONT GRILLE FAN BLADE ECU	Cracked	397.90 FL	*397.90 FL
119	1		*FRONT GRILLE PROXIMITY SENSOR	Not Working	196.50 FL	*196.50 FL
120	1		*FRONT HYBRID SPEAKER	Cracked	237.00 FL	*237.00 FL
121	1		*FRONT NUMBER PLATE HOLDER	Deformed	72.20 FL	*72.20 FL
122	2		*REAR MUDGUARD L+R	Deformed	159.00 FL	*159.00 FL
123	1		*REAR SMART LOCK INNER ANTENNA	Cracked	120.90 FL	*120.90 FL
124	1		*REAR MUDGUARD CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	40,106.80	22,541.30
- List Item Discount on L Items 20.00/20.00% (\$)	7,127.36	4,406.26
Total Parts (\$)	32,979.44	18,135.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	3,600.00	1,600.00
2	SPRAY PAINT ON AFFECTED AREAS	New	3,000.00	1,600.00
3	TO RNR REAR WINDSCREEN }	New	400.00	180.00
4	TO RNR BOOTLID WINDSCREEN }	New	300.00	0.00
5	TO RNR REAR EXHAUST	New	250.00	80.00
6	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
7	TO CHECK WIRING AND FOGLAMP FUNCTION	New	150.00	20.00
8	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
9	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	600.00	60.00
10	TO CHECK WATER LEAK	New	150.00	30.00
11	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	New	300.00	100.00
12	TO RNR FRONT RADIATOR	New	250.00	0.00
13	TO RNR ALTERNATOR	New	600.00	0.00
14	TO RNR FUEL TANK	New	250.00	60.00
15	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	150.00
16	TO RNR REAR BOOTLID MECHANISM	New	350.00	60.00
17	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
18	TO RNR REAR DOOR MECHANISM	New	400.00	0.00
19	TO RNR HORN AND TEST FUNCTION	New	150.00	0.00
20	TO PERFORM RUST PROOFING	New	400.00	40.00
21	TO RNR FRONT PROXIMITY SENSOR AND TEST FUNCTION	New	300.00	150.00
Gross Labour Cost (\$\$)			12,500.00	4,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >