

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001559/T1GS3Q2
Date: 03/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100450467
Claimant Vehicle No :	SKE7510S	Insured Vehicle No :	SGE7407E
Date of Loss:	29/01/2021	Nature of Claim:	TP
		Claim No:	1502359765SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE7510S	Engine No:	CDN176251
Make & Model:	AUDI A5, 2.0 TFSI QUATTRO (A)	Chassis No:	WAUZZZ8T8BA053779
Reg. Date:	29/03/2012 (Man. Year: 2011)	Odometer:	59488 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,012.77	3,851.33	6,161.44	61.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	810.00	4,640.00	85.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,462.77	4,661.33	10,801.44	69.85
Approved Total (Overridden) (S\$)		3,750.00		

Adjuster Report

(S\$)	15,462.77	3,750.00	11,712.77	75.75
+ GST 7.00/7.00% (S\$)	1,082.39	262.50	819.89	75.75
Nett Amount (S\$)	16,545.16	4,012.50	12,532.66	75.75
+ Car Rental (6.0 x S\$128.40/day) (S\$)		770.40		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,790.35		
Global Sum Settlement (S\$)		4,700.00		

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 03/02/2021

Estimated Period of Repair: 3.0 days

Inspected At:

AP Automotive Services Pte Ltd (HQ)
Blk 9006 Tampines Street 93, #01-202
Singapore 528840**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (NPA)	Not Necessary	0.00 FL	*- FL
2	1		*BONNET LOCK (NPA)	Not Necessary	0.00 FL	*- FL
3	1		*BONNET LOCK CATCH	Not Necessary	81.50 FL	*- FL
4	2		*SET BONNET HINGE	Not Necessary	106.90 FL	*- FL
5	2		*SET BONNET DAMPER	Not Necessary	205.20 FL	*- FL
6	1		*FRONT GRILLE CHROME	Cracked	489.70 FL	*489.70 FL
7	1		*FRONT GRILLE LOGO-AUDI	Necessary	102.00 FL	*102.00 FL
8	1		*HEADLAMP L+R	N/S Not Necessary / O/SCracked	1,480.00 FL	*740.00 FL
9	2		*HEADLAMP BALLAST L+R (NPA)	Not Necessary	0.00 FL	*- FL
10	2		*HEADLAMP LOWER BRACKET L+R	Not Necessary	344.00 FL	*- FL
11	2		*HEADLAMP NOZZLE L+R	Not Necessary	395.10 FL	*- FL
12	1		*FRONT BUMPER	Deformed	1,004.00 FL	*1,004.00 FL
13	2		*FRONT BUMPER NOZZLE COVER L+R	Not Necessary	103.40 FL	*- FL
14	1		*FRONT BUMPER TOW COVER	Not Necessary	47.80 FL	*- FL
15	4		*SET FRONT BUMPER SENSOR (NPA)	Not Necessary	0.00 FL	*- FL
16	2		*FRONT BUMPER FOG LAMP L+R (NPA)	Not Necessary	0.00 FL	*- FL
17	2		*FRONT BUMPER FOG LAMP CHROME L+R (NPA)	Not Necessary	0.00 FL	*- FL
18	2		*FRONT BUMPER FOG LAMP GARNISH L+R	Not Necessary	347.80 FL	*- FL
19	2		*FRONT BUMPER RETAINER L+R	Not Necessary	182.80 FL	*- FL
20	1		*FRONT BUMPER REINFORCEMENT BAR	Bent	516.30 FL	*516.30 FL
21	1		*FRONT BUMPER SPONGE	Deformed	221.45 FL	*221.45 FL
22	1		*FRONT BUMPER UNDERCOVER	Not Necessary	351.80 FL	*- FL
23	1		*FRONT FENDER COWLING RH (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*FRONT SUPPORT PANEL (NPA)	Not Necessary	0.00 FL	*- FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	342.90 FL	*- FL
26	1		*AIRCON CONDENSOR	Not Necessary	1,356.70 FL	*- FL
27	2		*AIRCON CONDENSOR AIRGUIDE L+R	Not Necessary	285.30 FL	*- FL
28	1		*WIPER WASHER TANK	Not Necessary	182.30 FL	*- FL
29	2		*FRONT HORN L+R	Not Necessary	159.60 FL	*- FL
30	1		*AIR GUIDE	Torn	949.00 FL	*949.00 FL
31	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
32	1		*FRONT GRILLE GARNISH -QUATTRO	Not Necessary	800.00 FS	*- FS
33	1		*FRONT NUMBER PLATE	Not Necessary	120.00 FS	*- FS
34	1		*FRONT FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
35	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$)	10,475.55	4,052.45
					- List Item Discount on L Items 5.00/5.00% (\$)	462.78	201.12
					Total Parts (\$)	10,012.77	3,851.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	300.00
2	SPRAY PAINT ON AFFECTED AREAS	New	800.00	300.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION	New	150.00	0.00
5	TO RNR INNER TRIM AND UPHOLSTERY	New	600.00	0.00
6	TO CHECK WATER LEAK	New	150.00	0.00
7	TO RNR INNER TRIM AND UPHOLSTERY	New	600.00	0.00
8	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	New	300.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	1,000.00	180.00
10	TO RNR FRONT PARKING SENSOR AND CHECK FUNCTION	New	150.00	0.00
11	TO PERFORM RUST PROOFING	New	400.00	0.00
12	TO RNR HORN AND TEST FUNCTION	New	150.00	0.00
Gross Labour Cost (S\$)			5,450.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >