

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21001568/ATF3N2**Date:** 15/12/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00005252000

Claimant Vehicle No : SKW4572M **Insured Vehicle No :** PA7525L

Date of Loss: 28/01/2021 Nature of Claim: TP Claim No: SNM21D200585/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW4572M**

Make & Model: HONDA FIT, 1.5 RS (A) Engine No: L13B1221351

Reg. Date: 29/10/2015 (Man. Year: 2015) Chassis No: GK31121349

Colour: Grey Odometer: 68396 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 175/65R14 Rear Tyre Size: 175/65R14

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,179.04	3,563.36	2,615.68	42.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,690.00	1,980.00	53.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,849.04	5,253.36	4,595.68	46.66
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	9,849.04	4,200.00	5,649.04	57.36

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 02/02/2021 Inspected At: Ace Autolution Pte Ltd (KAKI BUKIT)
13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
Singapore 417807

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Dec 2021)
Parts: 144	HONDA FIT 1.5 RS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKW4572M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	610.30 FL	*495.00 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	111.50 FL	*38.00 FL
3	1		*FRONT BUMPER BEAM RH	Not Necessary	219.40 FL	*- FL
4	1		*FRONT BUMPER FOGLAMP COVER RH	Not Necessary	261.80 FL	*- FL
5	1		*FRONT HEADLAMP RH	Cracked	1,118.60 FL	*1,118.60 FL
6	1		*FRONT HEADLAMP BRACKET RH	Not Necessary	91.00 FL	*- FL
7	1		*FRONT FENDER RH	Distorted	325.60 FL	*325.60 FL
8	1		*FRONT FENDER INNER SHIELD RH	Deformed	86.20 FL	*86.20 FL
9	1		*FRONT FENDER PANEL RH	Repair	415.00 FL	*- FL
10	1		*FRONT SIGNAL LAMP RH	Not Necessary	361.40 FL	*- FL
11	1		*FRONT SIGNAL LAMP COVER RH	Missing	145.00 FL	*145.00 FL
12	1		*FRONT SIGNAL LAMP MOTOR RH	Damaged	525.60 FL	*525.60 FL
13	1		*FRONT DOOR RH	Repair	870.80 FL	*- FL
14	1		*FRONT DOOR UPPER HINGE RH	Not Necessary	81.00 FL	*- FL
15	1		*FRONT DOOR LOWER HINGE RH	Not Necessary	81.00 FL	*- FL
16	1		*FRONT BEARING HUB RH	Damaged	210.00 FL	*210.00 FL
17	1		*FRONT BEARING RH	Necessary	167.40 FL	*167.40 FL
18	1		*FRONT LOWER ARM RH	Bent	189.80 FL	*189.80 FL
19	1		*FRONT KNUCKLE ARM RH	Bent	175.60 FL	*175.60 FL
20	1		*FRONT STABILIZER LINK RH	Not Necessary	111.90 FL	*- FL
21	1		*FRONT SHOCK ABSORBER	Bent	302.40 FL	*302.40 FL
22	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
23	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*FRONT RIM RH	Cut	550.00 FS	*480.00 FS
25	1		*SET FRONT PARKING SENSOR	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,471.30	4,319.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,292.26	755.84
Total Parts (\$\$)	6,179.04	3,563.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	600.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	700.00
3	TO RMEOVE AND REFIX WIRING AT DAMAGED AREAS	New	150.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	120.00	50.00
5	TO REMOVE & REFIX/REPLACE FRONT TRIMS,GARNISH AND FITTING SO AS TO FACILITATE REPAIRS AS REAR COMPARTMENT	New	150.00	0.00
6	TO REMOVE AND REPLACE PARKING SENSOR AND CHECK FOR PROPER FUNCTIONS	New	120.00	50.00
7	TO REMOVE AND REPLACE UNDERCARRIAGE PART	New	210.00	180.00
8	TO CONDUCT WHEEL ALIGNMENT TEST	New	120.00	80.00
			Gross Labour Cost (\$\$)	3,670.00
				1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >