

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21001569/UTF3Q2

**Date:** 10/03/2021

#### REFERENCE

|                                                        |                             |                  |
|--------------------------------------------------------|-----------------------------|------------------|
| Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. | Policy No:                  | A80471199QMX     |
| <b>Claimant</b>                                        |                             |                  |
| <b>Vehicle No :</b> GBH3013C                           | <b>Insured Vehicle No :</b> | SJQ1023U         |
| Date of Loss: 21/01/2021                               | Nature of Claim: TP         | Claim No: 633208 |

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | GBH3013C                          | Engine No:  | 263A90008105299   |
| Make & Model:               | OPEL COMBO, 1.6 (M)               | Chassis No: | W0L6WZS1BJ9625031 |
| Reg. Date:                  | 12/04/2018 (Man. Year: 2017)      | Odometer:   | 120197 km         |
| Colour:                     | White                             |             |                   |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

#### CONDITION OF TYRES

|                   |                |                  |                |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size:  | 205/55R16      | Rear Tyre Size:  | 205/55R16      |
| Front Left Side:  | Premio 60 6 mm | Rear Left Side:  | Premio 60 6 mm |
| Front Right Side: | Premio 60 6 mm | Rear Right Side: | Premio 60 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                    | 8,158.00         | 1,348.20        | 6,809.80        | 83.47        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00            |              |
| Labour                                   | 2,720.00         | 1,160.00        | 1,560.00        | 57.35        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00            |              |
| Towing                                   | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>10,878.00</b> | <b>2,508.20</b> | <b>8,369.80</b> | <b>76.94</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>2,000.00</b> |                 |              |
| <b>(S\$)</b>                             | 10,878.00        | 2,000.00        | 8,878.00        | 81.61        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 761.46           | 140.00          | 621.46          | 81.61        |
| <b>Nett Amount (S\$)</b>                 | <b>11,639.46</b> | <b>2,140.00</b> | <b>9,499.46</b> | <b>81.61</b> |

#### INSPECTION

|                             |                          |                                                                                                                                |
|-----------------------------|--------------------------|--------------------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 04/02/2021               |                                                                                                                                |
| Date Inspected:             | 08/02/2021 Inspected At: | Automobile Integrated Management<br>Pte Ltd (HQ)<br>23 Kaki Bukit Ave 4 #04-01, Kaki Bukit<br>(South Wing)<br>Singapore 415933 |
| Estimated Period of Repair: | 3.0 days                 |                                                                                                                                |

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                            |                                                                                                                                                                              |
|----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 02 Mar 2021)                                                                                                                                |
| <b>Parts:</b> 144          | OPEL COMBO 1.6 (M) (Catalogue:Merimen Singapore 1.0)                                                                                                                         |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for GBH3013C)                                                                                                                                    |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

### Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT FENDER-LH               | Repair        | 1,150.00 FL | *- FL        |
| 2   | 1   |          | *FRONT FENDER INNER SHIELD     | Not Necessary | 185.00 FL   | *- FL        |
| 3   | 1   |          | *FRONT BUMPER                  | Deep Cut      | 1,350.00 FL | *1,050.00 FL |
| 4   | 1   |          | *FRONT BUMPER SIDE RETAINER LH | Not Necessary | 45.00 FL    | *- FL        |
| 5   | 1   |          | *FRONT DOOR-LH                 | Repair        | 2,550.00 FL | *- FL        |
| 6   | 1   |          | *FRONT DOOR PROTECTOR          | Grazed        | 315.00 FL   | *268.00 FL   |
| 7   | 1   |          | *FRONT WHEEL RIM-LH            | Not Necessary | 265.00 FL   | *- FL        |
| 8   | 1   |          | *FRONT WHEEL RIM CAP           | Cut           | 220.00 FL   | *180.00 FL   |
| 9   | 1   |          | *FRONT SHOCK ABSORBER-LH       | Not Necessary | 685.00 FL   | *- FL        |
| 10  | 1   |          | *FRONT LOWER ARM               | Not Necessary | 865.00 FL   | *- FL        |
| 11  | 1   |          | *FRONT KNUCKLE ARM             | Not Necessary | 895.00 FL   | *- FL        |
| 12  | 1   |          | *FRONT WHEEL BEARING           | Not Necessary | 245.00 FL   | *- FL        |
| 13  | 1   |          | *FRONT TYRE                    | Not Necessary | 220.00 FS   | *- FS        |
| 14  | 1   |          | *R.O.V STICKER                 | Not Necessary | 45.00 FS    | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>9,035.00</b> | <b>1,498.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 877.00          | 149.80          |
| <b>Total Parts (\$\$)</b>                                  | <b>8,158.00</b> | <b>1,348.20</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars                                           | Lab.Type | Repairer's                      | Amount          |
|---------------------|-------------------------------------------------------|----------|---------------------------------|-----------------|
| <b>Labour Items</b> |                                                       |          |                                 |                 |
| 1                   | TO REMOVE/REFIT FRONT UNDERCARRIAGE                   | New      | 300.00                          | 0.00            |
| 2                   | TO CHECK WHEEL ALIGNMENT                              | New      | 120.00                          | 60.00           |
| 3                   | TO CHECK FRONT ELECTRICAL WIRING                      | New      | 50.00                           | 20.00           |
| 4                   | TO RESPRAY UNDERCOATING                               | New      | 120.00                          | 30.00           |
| 5                   | TO RESPRAY PAINTING AND ETC                           | New      | 1,080.00                        | 550.00          |
| 6                   | PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS | New      | 1,050.00                        | 500.00          |
|                     |                                                       |          | <b>Gross Labour Cost (\$\$)</b> | <b>2,720.00</b> |
|                     |                                                       |          |                                 | <b>1,160.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >