

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21001570/T1TF3E2

Date: 17/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100453329
Claimant Vehicle No : SCE2323T Insured Vehicle No : SLA4941K
Date of Loss: 26/01/2021 Nature of Claim: TP Claim No: 8539043951SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCE2323T**
Make & Model: TOYOTA VOXY HYBRID V, 1.8 (A) Engine No: 2ZR0C48958
Reg. Date: 03/04/2019 (Man. Year: 2018) Chassis No: ZWR800349054
Colour: White Odometer: 83792 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/02/2021
Date Inspected: 02/02/2021 Inspected At: Eco Automobile Claims & Repair Pte Ltd - Bartley Biz Center (HQ)
15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTER
Singapore 417808
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT BUMPER	Deformed	0.00 F	*- F	
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F	
3	1		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F	
4	1		*FRT LH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F	
5	1		*FRT LH BUMPER FOG LAMP	* Check	0.00 F	*- F	
6	1		*FRT LH HEADLAMP ASSY	Cut	0.00 F	*- F	
					Total Parts (\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >