

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001572/T1BA3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000003363
Claimant Vehicle No :	SHC358H	Insured Vehicle No :	SMR9212Y
Date of Loss:	02/02/2021	Nature of Claim:	TP
		Claim No:	8696624683SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC358H		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS061520
Reg. Date:	13/09/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU403563369
Colour:	Yellow	Odometer:	438356 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	960.60	960.60	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	630.00	150.00	19.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,740.60	1,590.60	150.00	8.62
Approved Total (Overridden) (S\$)		1,250.00		

(S\$)	1,740.60	1,250.00	490.60	28.19
+ GST 7.00/7.00% (S\$)	121.84	87.50	34.34	28.18
Nett Amount (S\$)	1,862.44	1,337.50	524.94	28.19
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$125.40/day) (S\$)		250.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,690.30		

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 02/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	10		*BUMPER PIECE	Necessary	22.00 FL	*22.00 FL
3	1		*GUARD -REAR BUMPER CENTER	Deformed	552.60 FL	*552.60 FL
4	1		*BUMPER PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS
5	1		*REVERSE SENSOR ASSY	Not Working	135.70 FS	*135.70 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					1,218.90	1,218.90
- List Item Discount on L Items 25.00/25.00% (\$\$)					258.30	258.30
Total Parts (\$\$)					960.60	960.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT ON AFFECTED AREA	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			780.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >