### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001576/KVF3E2

12/03/2021 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMB1SNW00012072005

**Claimant Vehicle** 

Date of Loss:

SKT9701R

Insured Vehicle CB6351B

No:

29/01/2021

No: Nature of Claim: TP

Claim

SNM21D200604/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SKT9701R** Reg No:

NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: Make & Model: HRA2512750A

Reg. Date: 26/06/2015 (Man. Year: 2015) Chassis No: SJNFEAJ11U1400999

Colour: Metallic Grey Odometer: 120683 km

**Engine Capacity:** 1197 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17 Front Left Side: Continental 9 mm Rear Left Side: Continental 9 mm Front Right Side: Continental 9 mm Rear Right Side: Continental 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 26,876.43  | 6,159.23   | 20,717.20  | 77.08  |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 5,260.00   | 2,480.00   | 2,780.00   | 52.85  |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 32,136.43  | 8,639.23   | 23,497.20  | 73.12  |
| Approved Total (Overridden) (S\$) |            | 6,900.00   |            |        |
| (S\$)                             | 32,136.43  | 6,900.00   | 25,236.43  | 78.53  |
| + GST 7.00/7.00% (S\$)            | 2,249.55   | 483.00     | 1,766.55   | 78.53  |
| Nett Amount (S\$)                 | 34,385.98  | 7,383.00   | 27,002.98  | 78.53  |

**INSPECTION** 

Date of Assignment: 02/02/2021

Yee Auto Pte Ltd (HQ)

160 SIN MING DRIVÉ, #02-17 SIN MING 02/02/2021 Inspected At: Date Inspected:

AUTOCITY

Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: **KENNETH KONG** Manager: **VERON CHEN** 

## REPAIR DETAILS

# Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Mar 2021)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SKT9701R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

| No.                 | Qty | Part No. | Particulars                                  | Condition     | Repairer's | Amount               |
|---------------------|-----|----------|--|---------------|------------|----------------------|
| 1                   | 1   |          | *FRONT BONNET                                | Repair        | 1,061.30 F | *- FL                |
| 2                   | 1   |          | *FRONT BONNET RUBBER                         | Serviceable   | 55.00 F    | *-FL                 |
| 3                   | 1   |          | *FRONT BUMPER                                | Buckled       | 872.90 F   | *689.00 FL           |
| 4                   | 1   |          | *SET FRONT BUMPER CLIPS                      | Necessary     | 60.00 F    | *60.00 FL            |
| 5                   | 1   |          | *FRONT BUMPER SIDE RETAINER - LH             | Distorted     | 83.50 F    | *83.50 FL            |
| 6                   | 1   |          | *FRONT BUMPER SIDE RETAINER - RH             | Distorted     | 83.50 F    | *83.50 FL            |
| 7                   | 1   |          | *FRONT FENDER - RH                           | Repair        | 507.96 F   | *- FL                |
| 8                   | 1   |          | *FRONT GRILLE                                | Cracked       | 525.00 F   | *461.20 FL           |
| 9                   | 1   |          | *FRONT GRILLE CHROME                         | Dented        | 320.15 F   | *285.00 FL           |
| 10                  | 1   |          | *FRONT GRILLE LOGO                           | Necessary     | 285.15 F   | *65.00 FL            |
| 11                  | 1   |          | *FRONT HEADLAMP - LH                         | Serviceable   | 955.50 F   | *- FL                |
| 12                  | 1   |          | *FRONT HEADLAMP - RH                         | Mtg Cracked   | 955.50 F   | *559.10 FL           |
| 13                  | 1   |          | *FRONT HEADLAMP LOWER BRACKET                | Distorted     | 185.15 F   | *185.15 FL           |
| 14                  | 1   |          | *FRONT SUPPORT PANEL (TOP)                   | Repair        | 588.10 F   | *- FL                |
| 15                  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH             | Serviceable   | 320.15 F   | *-FL                 |
| 16                  | 1   |          | *SET FRONT SUPPORT PANEL TOP GARNISH CLIPS   | Not Necessary | 50.00 F    | *- FL                |
| 17                  | 1   |          | *REAR AIR VENT - LH                          | Serviceable   | 60.50 F    | *- FL                |
| 18                  | 1   |          | *REAR BUMPER                                 | Buckled       | 1,212.75 F | *796.70 FL           |
| 19                  | 1   |          | *REAR BUMPER BRACKET - LH                    | Repair        | 118.98 F   | *- FL                |
| 20                  | 1   |          | *REAR BUMPER BRACKET - RH                    | Repair        | 118.98 F   | *- FL                |
| 21                  | 1   |          | *REAR BUMPER CENTRE PAD                      | Not Necessary | 593.10 F   | *- FL                |
| 22                  | 1   |          | *SET REAR BUMPER CLIPS                       | Necessary     | 50.00 F    | *50.00 FL            |
| 23                  | 1   |          | *REAR BUMPER LOWER GARNISH SILVER            | Serviceable   | 346.95 F   | *- FL                |
| 24                  | 1   |          | *REAR BUMPER REFLECTOR - LH                  | Serviceable   | 141.39 F   | *- FL                |
| 25                  | 1   |          | *REAR BUMPER REFLECTOR - RH                  | Serviceable   | 141.39 F   | *-FL                 |
| 26                  | 1   |          | *REAR BUMPER SIDE RETAINER - LH              | Distorted     | 70.50 F    | *70.50 FL            |
| 27                  | 1   |          | *REAR BUMPER SIDE RETAINER - RH              | Distorted     | 70.50 F    | *70.50 FL            |
| 28                  | 1   |          | *REAR BUMPER TOWING COVER - RH               | Serviceable   | 60.00 F    | *-FL                 |
| 29                  | 1   |          | *REAR BUZZER SENSOR                          | Serviceable   | 170.00 F   | *- FL                |
| 30                  | 1   |          | *REAR ELECTRONICS ANTENNA SENSOR             | Cracked       | 178.00 F   | *178.00 FL           |
| 31                  | 1   |          | *REAR END PANEL INNER GARNISH                | Serviceable   | 253.71 F   | *-FL                 |
| 32                  | 1   |          | *REAR END PANEL LOWER GARNISH                | Serviceable   | 259.20 F   | *- FL                |
| 33                  | 1   |          | *REAR END PANEL OUTER                        | Repair        | 792.05 F   | *- FL                |
| 34                  | 1   |          | *REAR END PANEL TOP GARNISH                  | Mtg Distorted | 288.90 F   | *65.00 FL            |
| 35                  | 1   |          | *REAR FENDER INNER TRIMBOARD - LH            | Serviceable   | 772.38 F   | *- FL                |
| 36                  | 1   |          | *REAR FENDER INNER TRIMBOARD - RH            | Serviceable   | 772.38 F   | *- FL                |
| 37                  | 1   |          | *REAR INNER TRIM SIDE COVER - LH             | Serviceable   | 166.50 F   | *- FL                |
| 38                  | 1   |          | *REAR INNER TRIM SIDE COVER - RH             | Serviceable   | 166.50 F   | *- FL                |
| 39                  | 1   |          | *REAR NUMBER PLATE LAMP - LH                 | Serviceable   | 92.16 F    | *- FL                |
| 40                  | 1   |          | *REAR NUMBER PLATE LAMP - RH                 | Serviceable   | 92.16 F    | *-FL                 |
| 41                  | 1   |          | *REAR SPARE WHEEL PANEL                      | Repair        | 855.80 F   | *-FL                 |
| 42                  | 1   |          | *REAR TAIL LAMP - LH                         | Serviceable   | 653.58 F   | *-FL                 |
| 43                  | 1   |          | *REAR TAIL LAMP - RH                         | Serviceable   | 653.58 F   | *-FL                 |
| 43<br>44            | 1   |          | *REAR TAILGATE                               | Bent          | 1,625.49 F | *1,625.49 FL         |
| <del>44</del><br>45 | 1   |          | *REAR TAILGATE  *REAR TAILGATE ABSORBER - LH | Serviceable   | 1,025.49 F | 1,025.49 FL<br>*- FL |
| 45<br>46            | 1   |          | *REAR TAILGATE EMBLEM LOGO                   |               | 85.60 F    | *85.60 FL            |
| +0                  | 1   |          | INLAIN TAILGATE LINIDELINI LUGU              | Necessary     | 03.00 F    | 03.00 FL             |

Report was unsubmitted during this print-out.

| No.   | Qty    | Part No.    | Particulars                         | Condition         | Repairer's | Amount     |
|-------|--------|-------------|-------------------------------------|-------------------|------------|------------|
| 47    | 1      |             | *REAR TAILGATE EMBLEM QASHQAI       | Necessary         | 113.31 F   | *113.31 FL |
| 48    | 1      |             | *REAR TAILGATE INNER HOLDER         | Serviceable       | 55.89 F    | *- FL      |
| 49    | 1      |             | *REAR TAILGATE INNER TRIMBOARD      | Serviceable       | 558.09 F   | *- FL      |
| 50    | 1      |             | *REAR TAILGATE LOCK                 | Dented            | 410.31 F   | *173.20 FL |
| 51    | 1      |             | *REAR TAILGATE LOCK COVER           | Serviceable       | 53.37 F    | *- FL      |
| 52    | 1      |             | *REAR TAILGATE OUTER GARNISH        | Mtg Cracked       | 288.15 F   | *288.15 FL |
| 53    | 1      |             | *REAR TAILGATE OUTER OPENING SWITCH | Serviceable       | 166.95 F   | *- FL      |
| 54    | 1      |             | *REAR TAILGATE REFLECTOR - LH       | Serviceable       | 772.38 F   | *- FL      |
| 55    | 1      |             | *REAR TAILGATE REFLECTOR - RH       | Serviceable       | 772.38 F   | *- FL      |
| 56    | 1      |             | *REAR TAILGATE WEATHERSTRIP         | Serviceable       | 212.31 F   | *- FL      |
| 57    | 1      |             | *REAR TAILGATE WIPER MOTOR          | Serviceable       | 436.95 F   | *- FL      |
| 58    | 1      |             | *REAR WHEEL PANEL TOOL BOX          | Serviceable       | 410.58 F   | *- FL      |
| 59    | 1      |             | *REAR WHEEL PANEL TRIMBOARD         | Serviceable       | 459.00 F   | *- FL      |
| 60    | 1      |             | *REAR WINDSCREEN MOULDING           | Necessary         | 120.96 F   | *120.96 FL |
| 61    | 1      |             | *REAR WINDSCREEN SOLAR FILM         | Not Necessary     | 252.00 F   | *- FL      |
| 62    | 1      |             | *REAR WIPER BLADE                   | Serviceable       | 60.20 F    | *- FL      |
| 63    | 1      |             | *REAR WIPER MOTOR                   | Serviceable       | 511.38 F   | *- FL      |
| 64    | 1      |             | *SPARE WHEEL TOP COVER              | Serviceable       | 346.63 F   | *- FL      |
| 65    | 1      |             | *REAR NUMBER PLATE                  | Dented            | 60.00 FS   | *45.00 FS  |
| 66    | 1      |             | *REAR WINDSCREEN SEALANT            | Necessary         | 60.00 FS   | *40.00 FS  |
| 67    | 1      |             | *REVERSE CAMERA                     | Serviceable       | 252.00 FS  | *- FS      |
| 68    | 1      |             | *REVERSE SENSOR CENTRE - LH }       | Dented            | 270.00 FS  | *350.00 FS |
| 69    | 1      |             | *REVERSE SENSOR CENTRE - RH }       | Dented            | 270.00 FS  | *- FS      |
| 70    | 1      |             | *REVERSE SENSOR CORNER - LH }       | Shorted           | 270.00 FS  | *-FS       |
| 71    | 1      |             | *REVERSE SENSOR CORNER - RH         | Serviceable       | 270.00 FS  | *- FS      |
| 72    | 1      |             | *REAR END PANEL INNER               | Repair            | 504.80 F   | *- FL      |
| 73    | 1      |             | *FRONT BUMPER SPONGE                | Cracked           | 375.00 F   | *125.00 FL |
| 74    | 1      |             | *REAR BUMPER SPONGE                 | Cracked           | 375.00 F   | *126.40 FL |
| 75    | 1      |             | *REAR TAILGATE ABSORBER - RH        | Serviceable       | 198.45 F   | *- FL      |
| F=Fra | nchise | part. S=Spc | Nett. L=ListItemDisc.               | -                 |            |            |
|       |        |             |                                     | Sub Total (S\$)   | 26,876.43  | 6,795.26   |
|       |        |             | - List Item Discount on L Items     | 0.00/10.00% (S\$) | 0.00       | 636.03     |
|       |        |             |                                     | Total Parts (S\$) | 26,876.43  | 6,159.23   |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

| No         | Particulars  | Lab.Type   | Repairer's | Amount   |
|------------|--|------------|------------|----------|
| <u>Lab</u> | our Items  |            |            |          |
| 1          | TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY | New        | 2,000.00   | 1,000.00 |
| 2          | TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION     | New        | 2,300.00   | 1,200.00 |
| 3          | TO REMOVE / REFIT REAR WINDSCREEN TO FACILITATE REPAIRS          | New        | 200.00     | 120.00   |
| 4          | TO REMOVE / TRANSFER TAILGATE COMPONENTS                         | New        | 80.00      | 60.00    |
| 5          | TO CHECK DIAGNOSTIC RESET  | New        | 80.00      | 40.00    |
| 6          | COMPUTER DIAGNOSTIC RESET  | New        | 280.00     | 0.00     |
| 7          | TO TOW VEHICLE TO WORKSHOP                                       | New        | 120.00     | 0.00     |
| 8          | TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL               | New        | 200.00     | 60.00    |
|            | Gross Labour Cost (S\$)  |            | 5,260.00   | 2,480.00 |
|            | Report was unsubmitted during this                               | print-out. |            |          |

< END OF ESTIMATES >