

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001577/T1GA3Q2
Date: 17/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100442532-05
Claimant Vehicle No :	SHD3442Y	Insured Vehicle No :	GBE4304Y
Date of Loss:	29/01/2021	Nature of Claim:	TP
		Claim No:	0548051298SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3442Y		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU668328
Reg. Date:	28/07/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU093253
Colour:	Blue	Odometer:	491059 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,308.56	0.00	1,308.56	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	720.00	560.00	160.00	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,028.56	560.00	1,468.56	72.39
+ GST 7.00/7.00% (S\$)	142.00	39.20	102.80	72.39

Nett Amount (S\$)	2,170.56	599.20	1,571.36	72.39
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	02/02/2021			
Date Inspected:	02/02/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969	
Estimated Period of Repair:	2.0 days			

Adjuster:	MOHD TAUFIKH BIN HAMID	Manager:	Chong Pui Lin
------------------	------------------------	-----------------	---------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,106.00 FL	*- FL
2	1		*REAR BUMPER UNDER COVER (Deformed)	Old Damaged	228.00 FL	*- FL
3	1		*REAR WHEEL CAP RH (CUT)	Old Damaged	217.20 FL	*- FL
4	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
5	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					1,623.20	0.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					314.64	0.00
Total Parts (\$\$)					1,308.56	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAYPAINT CHARGE	New	300.00	250.00
3	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			720.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >