



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2105303

INV Date 29/07/2021

Reference CC4/LPC21001578/Abs3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. YN 5837A

Insured Veh. GBD 261T

Claim No. 20/21/21/VC05/024199

Policy No. Z20VC05005046

Accident Date 02/02/2021

Inspection Date 03/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21001578/Abs3q2 Date: 29/07/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 261T		Veh. Inspected	YN 5837A
Policy No.	Z20VC05005046		Coverage (\$)	0.00
Claim No.	20/21/21/VC05/024199		Excess (\$)	0.00
Assign From	KENNY		Assign Date	02/02/2021
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER		c.c	2998
Engine No.	HIDDEN		Year of Reg.	2014
Chassis No.	FEB71EA00153		Colour	WHITE
Odometer	208109 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/75 R17.5	FALKEN	6 mm
	L/H Front Tyre	215/75 R17.5	FALKEN	6 mm
	R/H Rear Tyre	215/75 R17.5	FALKEN	6 mm
	L/H Rear Tyre	215/75 R17.5	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/02/2021	Inspection Date	03/02/2021
	Survey held at	RYDER AUTO WORKSHOP LLP 2 Kaki Bukit Ave 2# 02-19 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 5837A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR O/S TAIL -LAMP	CRACKED	352.20	352.20
1	REAR O/S TAIL -LAMP BRACKET	BENT	344.00	220.00
1	REAR O/S STOPPER BRACKET	BENT	120.00	120.00
1	REAR TAIL-GATE	DEFORMED	2,675.40	1,988.00
2	REAR TAIL-GATE HINGES	NOT NECESSARY	60.00	-
1	REAR TAIL-GATE O/S LOCK	DENTED	210.00	210.00
1	REAR TAIL-GATE O/S LOCK LEVER HANDLE	NOT NECESSARY	110.00	-
1	REAR TAIL-GATE 'MITSUBISHI' EMBLEM	NECESSARY	120.00	120.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	680.00	-
	LESS 25% DISCOUNT		-1,167.90	-752.55
			3,503.70	2,257.65
	<u>SPECIAL NETT ITEMS</u>			
1	REAR O/S STOPPER (SN)	MISSING	30.00	30.00
1	REAR TAIL-GATE '60KMPH' EMBLEM (SN)	NECESSARY	15.00	15.00
1	REAR TAIL-GATE INNER WOODEN COVER (SN)	NOT NECESSARY	300.00	-
1	REAR GUARD (LTA APPROVED)(SN)	NOT NECESSARY	1,200.00	-
1	REAR O/S GUARD BRACKET (SN)	NOT NECESSARY	110.00	-
1	REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			1,935.00	245.00
	<u>LABOUR</u>			
	TO DISMANTLE ,STRAIGHTEN AND WELDING .INCLUSIVE OF THE REPAIR OF REAR END PANEL .		800.00	600.00
	TO SPRAY PAINTING .		500.00	500.00
	TO CHECK WIRING .		80.00	30.00
	TO RE-SEAL ANTI-RUST .		80.00	50.00
			1,460.00	1,180.00
	GRAND TOTAL		6,898.70	3,682.65

Report Ref No. CC4/LPC21001578/Abs3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,950.00
---	--	--	-----------------

Report Ref No. CC4/LPC21001578/Abs3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 5837A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

