

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001585/DGA3Q2
Date: 17/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900099739
Claimant Vehicle No :	SMS442D	Insured Vehicle No :	SMM7878R
Date of Loss:	30/01/2021	Nature of Claim:	TP
		Claim No:	5240863524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS442D		
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Engine No:	L13B3935213
Reg. Date:	07/02/2020 (Man. Year: 2019)	Chassis No:	GK33420722
Colour:	Blue	Odometer:	29212 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,761.98	15,314.08	10,447.90	40.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,980.00	4,030.00	3,950.00	49.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,741.98	19,344.08	14,397.90	42.67
Approved Total (Overridden) (S\$)		15,400.00		

(S\$)	33,741.98	15,400.00	18,341.98	54.36
+ GST 7.00/7.00% (S\$)	2,361.94	1,078.00	1,283.94	54.36
Nett Amount (S\$)	36,103.92	16,478.00	19,625.92	54.36
+ Car Rental (15.0 x S\$100.00/day) (S\$)		1,500.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		18,014.45		

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 02/02/2021

Estimated Period of Repair: 9.0 days

Inspected At:

Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,012.81 FL	*845.20 FL
2	2		*TAILGATE HINGE	Repair	89.02 FL	*- FL
3	2		*TAILGATE DAMPER	Serviceable	277.62 FL	*- FL
4	1		*TAILGATE LOCK	Damaged	234.00 FL	*146.30 FL
5	1		*TAILGATE LOCK STRIKER	Bent	36.84 FL	*36.84 FL
6	1		*TAILGATE INNER TRIM	Not Necessary	336.00 FL	*- FL
7	1		*TAILGATE GLASS MOULDING	Necessary	122.90 FL	*122.90 FL
8	1		*TAILGATE OUTER GARNISH	Broken	348.00 FL	*250.80 FL
9	1		*TAILGATE EMBLEM LOGO	Necessary	45.60 FL	*45.60 FL
10	1		*TAILGATE EMBLEM-FIT	Necessary	43.20 FL	*43.20 FL
11	1		*TAILGATE WIPER MOTOR	Bent	354.00 FL	*274.40 FL
12	1		*TAILGATE INNER HANDLE COVER	Deformed	45.60 FL	*45.60 FL
13	1		*REAR WIPER BLADE	Not Necessary	158.56 FL	*- FL
14	1		*REAR WIPER ARM	Not Necessary	170.56 FL	*- FL
15	1		*REAR BUMPER	Dented	622.68 FL	*495.00 FL
16	1		*REAR BUMPER RETAINER	O/S Cracked / N/S Not Necessary	78.48 FL	*39.24 FL
17	1		*REAR BUMPER SIDE COVER	O/S Cut / N/S Not Necessary	116.88 FL	*58.44 FL
18	1		*REAR BUMPER LOWER GARNISH	Bent / Dented	482.44 FL	*178.70 FL
19	1		*REAR BUMPER TOW COVER	Serviceable	42.00 FL	*- FL
20	1		*REAR BUMPER UNDERCOVER	Not Necessary	126.48 FL	*- FL
21	1		*KEYLESS SENSOR	Not Necessary	148.05 FL	*- FL
22	1		*KEYLESS SPEAKER	Not Necessary	161.60 FL	*- FL
23	1		*END PANEL	Dented	692.00 FL	*373.50 FL
24	1		*END PANEL TOP GARNISH	Deformed	296.84 FL	*127.50 FL
25	2		*REAR EXTENSION PANEL RH/LH	Repair	689.68 FL	*- FL
26	1		*FLOOR COMPARTMENT	Dented	956.88 FL	*780.40 FL
27	1		*SPARE TYRE TOP BOARD	Bent	347.64 FL	*240.30 FL
28	1		*SPARE TYRE TOOL SPONGE	Torn / Deformed	294.00 FL	*198.20 FL
29	2		*REAR AIRVENT	Not Necessary	140.88 FL	*- FL
30	1		*REAR FENDER	O/S Dented / N/S Repair	2,809.44 FL	*726.00 FL
31	2		*REAR FENDER INNER TRIM	Deformed / Bent	816.00 FL	*667.68 FL
32	2		*REAR TAILLAMP	Broken	740.88 FL	*740.88 FL
33	2		*REAR TAILLAMP PANEL	Dented	284.88 FL	*284.88 FL
34	1		*REAR EXHAUST SILENCER	Bent	744.44 FL	*476.60 FL
35	2		*REAR EXHAUST MOUNTING	Not Necessary	68.88 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*REAR EXHAUST MUFFLER	Not Necessary	1,088.88 FL	*- FL
37	1		*BONNET	Broken	680.04 FL	*551.50 FL
38	2		*BONNET HINGE	Bent	116.88 FL	*116.88 FL
39	1		*BONNET INSULATOR	Bent	140.04 FL	*140.04 FL
40	1		*BONNET LOCK	Bent	182.44 FL	*182.44 FL
41	1		*FRONT GRILLE ASSY	No such part	309.60 FL	*- FL
42	1		*FRONT GRILLE CASING	Broken	462.00 FL	*302.00 FL
43	1		*FRONT GRILLE TOP CHROME MOULDING	Cut	201.60 FL	*201.60 FL
44	1		*FRONT GRILLE BOTTOM CHROME MOULDING	Broken	189.60 FL	*189.60 FL
45	1		*FRONT GRILLE EMBLEM LOGO	Cut / Necessary	82.44 FL	*82.44 FL
46	1		*FRONT BUMPER	Dented	669.60 FL	*517.70 FL
47	2		*FRONT BUMPER RETAINER	Serviceable	91.20 FL	*- FL
48	2		*FRONT BUMPER SIDE GARNISH	Not Necessary	213.12 FL	*- FL
49	1		*FRONT BUMPER REINFORCEMENT	Dented	336.00 FL	*336.00 FL
50	1		*FRONT BUMPER TOW COVER	Serviceable	38.40 FL	*- FL
51	1		*FRONT BUMPER LOWER GRILLE	Deformed	238.44 FL	*152.30 FL
52	2		*FRONT BUMPER LOWER GRILLE SIDE GARNISH	Not Necessary	124.60 FL	*- FL
53	2		*FRONT HEADLAMP	Broken	3,780.52 FL	*2,340.00 FL
54	2		*FRONT HEADLAMP BRACKET	Not Necessary	187.20 FL	*- FL
55	1		*SUPPORT PANEL	Dented	482.40 FL	*482.40 FL
56	1		*SUPPORT PANEL TOP GARNISH	Cracked / Broken	182.44 FL	*182.44 FL
57	1		*AIRCON CONDENSER ASSY	Bent / Punctured	863.31 FL	*863.31 FL
58	1		*RADIATOR	Punctured / Mtg Broken	1,102.90 FL	*1,102.90 FL
59	1		*RADIATOR FAN COWLING	Broken	761.90 FL	*761.90 FL
60	1		*FRONT NUMBER PLATE	Bent / Necessary	80.00 FS	*45.00 FS
61	1		*SET FRONT BUMPER CLIP	Necessary	30.00 FS	*20.00 FS
62	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	20.00 FS	*- FS
63	1		*BOT COOLANT	Not Necessary	60.00 FS	*- FS
64	1		*REAR NUMBER PLATE	Necessary	80.00 FS	*45.00 FS
65	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*20.00 FS
66	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	30.00 FS	*15.00 FS
67	1		*SER REAR TAILGATE INNER TRIM CLIP	Not Necessary	20.00 FS	*- FS
68	1		*SET REAR REVERSE SENSOR	Damaged	400.00 FS	*220.00 FS
69	1		*REAR REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
70	1		*FLOOR INSULATOR	Necessary	120.00 FS	*50.00 FS
71	1		*JOINT SEALANT	Necessary	120.00 FS	*40.00 FS
72	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
73	1		*INTAKE MANIFOLD	Cracked / Broken	700.92 FL	*700.92 FL
74	1		*BATTERY	Distorted / Deformed	232.32 FS	*80.00 FS
75	1		*TAILGATE WEATHERSTRIP	Deformed	166.20 FL	*166.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	2		*TAILGATE LAMP	Mtg Cracked	621.12 FL	*621.12 FL
77	2		*FRONT FENDER BRACKET	Bent	180.80 FL	*180.80 FL
78	2		*FRONT FENDER	Dented	1,410.82 FL	*817.80 FL
79	1		*BATTERY TRAY	Cracked / Broken	76.60 FL	*76.60 FL
80	1		*WIPER TANK	Deformed	156.80 FL	*156.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	31,716.89	18,998.85
- List Item Discount on L Items 20.00/20.00% (\$)	5,954.91	3,684.77
Total Parts (\$)	25,761.98	15,314.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ALL WIRING AND LIGHTING SYSTEM	New	80.00	30.00
2	REMOVE ,REFIT CONDENSER AND TOP UP GAS	New	150.00	120.00
3	REMOVE,REFIT RADIATOR AND TOP UP COOLANT	New	150.00	50.00
4	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	40.00
5	REMOVE AND RENEW KEYLESS SENSOR	New	120.00	0.00
6	REMOVE,REFIT LINING ,TRIM AND GARNISH	New	200.00	120.00
7	REMOVE AND RENEW REAR EXHAUST	New	120.00	60.00
8	REMOVE AND REFIT FUEL TANK	New	120.00	0.00
9	REMOVE AND REFIT REAR WINDSCREEN	New	120.00	80.00
10	CHASSIS MENCHMENT FOR CHASSIS ALIGNMENT	New	500.00	0.00
11	TRANSFER PARTS ,ATACHMENT FROM OLD TAILGATE TO NEW	New	200.00	60.00
12	PANEL BEATING ON AFFECTED AREAS	New	2,600.00	1,600.00
13	SPRAY PAINTING ON AFFECTED AREAS	New	2,600.00	1,600.00
14	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
15	R&R REAR SEAT TO FACILITATE REPAIR	New	300.00	0.00
16	R&R INTAKE MANIFOLD	New	300.00	150.00
17	RE-SEAL WEEKEND SEAL	New	150.00	80.00
Gross Labour Cost (S\$)			7,980.00	4,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >