

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21001593/ABS3Q2
Date: 10/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100417610
Claimant Vehicle No :	SMG4877U	Insured Vehicle No :	SKT9249E
Date of Loss:	04/01/2021	Nature of Claim:	TP
		Claim No:	8024514324SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG4877U	Engine No:	FB20YE52505
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Chassis No:	JF1SJ5KC5JG112661
Reg. Date:	21/12/2018 (Man. Year: 2018)	Odometer:	61027 km
Colour:	Bronze		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,686.10	4,105.12	8,580.98	67.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,620.00	2,390.00	4,230.00	63.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,306.10	6,495.12	12,810.98	66.36
Approved Total (Overridden) (S\$)		5,200.00		

Nett Amount (S\$)	19,306.10	5,200.00	14,106.10	73.07
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
		5,802.00		
Nett Liability (S\$)		5,802.00		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment: 01/02/2021

Date Inspected: 01/02/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Cn Motors Pte Ltd (HQ)
 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,192.30 F	*1,192.30 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	110.00 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	308.00 F	*- FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	65.00 F	*65.00 FL
5	1		*REAR BOOT LID SUBARU LOGO	Necessary	68.00 F	*68.00 FL
6	1		*REAR BOOT LID FORESTER LOGO	Necessary	68.00 F	*68.00 FL
7	1		*REAR BOOT LID AWD LOGO	Necessary	65.00 F	*65.00 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	1		*REAR BOOT LID INNER LOCK	Damaged	560.30 F	*264.00 FL
10	1		*REAR BOOT LID WEATHERSTRIP	Not Necessary	160.30 F	*- FL
11	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	220.30 F	*- FL
12	10		*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	65.00 F	*- FL
13	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	85.00 F	*85.00 FL
14	2		*REAR BOOT LID WINDSCREEN SIDE SEAL	Necessary	150.00 F	*150.00 FL
15	1		*REAR BOOT LID REVERSE CAMERA	Not Necessary	850.00 F	*- FL
16	1		*REAR BUMPER	Deformed	980.30 F	*600.30 FL
17	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
18	2		*REAR BUMPER SIDE RETAINER	Necessary	76.00 F	*76.00 FL
19	1		*REAR BUMPER SIDE REFLECTOR	Not Necessary	42.00 F	*- FL
20	1		*REAR BUMPER TOWING COVER	Not Necessary	22.00 F	*- FL
21	1		*REAR BUMPER REINFORCEMENT	Bent	320.80 F	*320.80 FL
22	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	57.20 F	*- FL
23	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
24	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	972.60 F	*- FL
25	8		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
26	1		*REAR END PANEL	Dented	332.00 F	*332.00 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	90.00 F	*90.00 FL
28	1		*REAR SPARE TYRE PANEL	Not Necessary	632.40 F	*- FL
29	1		*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	336.00 F	*- FL
30	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*- FL
31	2		*REAR SPARE TYRE PANEL SIDE FOAM TOOL BOX	Not Necessary	171.00 F	*- FL
32	1		*REAR SPARE TYRE PANEL FOAM TOOL BOX	Not Necessary	161.20 F	*- FL
33	1		*REAR CENTRE EXHAUST	Not Necessary	1,048.40 F	*- FL
34	1		*REAR BUMPER LOWER SPOILER	Deformed	1,800.00 FS	*800.00 FS
35	1		*REAR BUMPER TOP FORESTER CHROME	Dented	680.00 FS	*380.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$)	12,686.10	4,786.40
					- List Item Discount on L Items 0.00/20.00% (\$)	0.00	681.28
					Total Parts (\$)	12,686.10	4,105.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	60.00
3	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	60.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	150.00	120.00
5	TO REMOVE & REFIT REAR EXHAUST	New	200.00	0.00
6	CERAMIC COATING	New	800.00	0.00
7	GUM	New	60.00	60.00
8	TO CHECK WIRING	New	100.00	30.00
9	TUFF KOTE	New	150.00	80.00
10	PANEL BEATING	New	2,400.00	800.00
11	SPRAY PAINTING	New	2,000.00	1,000.00
12	TO REMOVE & REFIT BODY KIT	New	200.00	100.00
			Gross Labour Cost (S\$)	6,620.00
				2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >