



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD TOYOTA (GBH3969U)
Date of Loss	1 February 2021
Time of Loss	15.40
Loss Description	EU1222A (INSD) C/W GBH3969U
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="21917"/>
Nett Loss Amount	\$40,083.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	GBH3969U	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>16/05/2018</div> <div></div>
Mileage	<div>63534</div>	Age of Vehicle	2

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2018</div>
Make	TPVD	<div>TOYOTA</div>
		<div></div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	PHANG SUE MIN	<div></div>
Date of Birth		<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	TOYOTA POLICY INFORMATION	HIACE VAN TURBO 5D ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="JTFHT02P900241695"/>
Engine No		<input type="text" value="1KD2791938"/>
Engine Capacity		<input type="text" value="2982"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="62000"/>

CATEGORY Age	FNOL INFORMATION 0	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

02/02/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="25"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts














Add












Approve













Deny










Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT BUMPER	Damaged	0	541.2	No		25			405.9	Reviewing
<input type="checkbox"/>		0	2		FRONT BUMPER SIDE HOLDER	Necessary	0	66.5	No		25			99.75	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER FOG LAMP N/S	Cracked	0	284.1	No		25			213.08	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER FOG LAMP O/S	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER FOG LAMP COVER N/S	Deformed	0	62.1	No		25			46.58	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER FOG LAMP COVER O/S	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER LOWER GRILLE	Deformed	0	178.1	No		25			133.58	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT BUMPER REINFORCEMENT	Bent	0	361	No		25			270.75	Reviewing
<input type="checkbox"/>		0	2		FRONT BUMPER REINFORCEMENT STAY	Bent	0	198	No		25			297	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER TOP BEAM	Bent	0	189.6	No		25			142.2	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER BRACKET N/S	Bent	0	98.2	No		25			73.65	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER BRACKET O/S	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT GRILLE	Cracked	0	496.8	No		25			372.6	Reviewing
<input type="checkbox"/>		0	1		FRONT GRILLE BASE	Cracked	0	326.4	No		25			244.8	Reviewing
<input type="checkbox"/>		0	3		FRONT GRILLE CHROME MOULDING	Cut	0	155	No		25			348.75	Reviewing
<input type="checkbox"/>		0	2		HEADLAMP	Cracked	0	745	No		25			1117.5	Reviewing
<input type="checkbox"/>		0	1		BONNET	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		BONNET LOGO	Necessary	0	75	No		25			56.25	Reviewing
<input type="checkbox"/>		0	2		BONNET HINGE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		BONNET LOCK	Damaged	0	88.9	No		25			66.68	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT BRACE PANEL	Bent	0	98.4	No		25			73.8	Reviewing
<input type="checkbox"/>		0	2		FRONT CORNER PANEL	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT SUPPORT PANEL	Buckled	0	464.2	No		25			348.15	Reviewing
<input type="checkbox"/>		0	1		FRONT SUPPORT PANEL TOP COVER	Deformed	0	187.4	No		25			140.55	Reviewing
<input type="checkbox"/>		0	1		AIR CON CONDENSER	Damaged	0	1216.1	No		25			912.08	Reviewing
<input type="checkbox"/>		0	2		AIR CON CONDENSER LOWER MOUNTING	Necessary	0	25	No		25			37.5	Reviewing
<input type="checkbox"/>		0	1		AIR CON CONDENSER DISCHARGE PIPE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		AIR CON CONDENSER SUCTION PIPE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		AIR CON CONDENSER LIQUID PIPE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		AIR CON FAN ASSY	Cracked	0	415.6	No		25			311.7	Reviewing
<input type="checkbox"/>		0	1		RADIATOR	Dented	0	1495	No		25			1121.25	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		RADIATOR TOP HOSE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		RADIATOR FAN ASSY	Cracked	0	428.9	No		25			321.68	Reviewing
<input type="checkbox"/>		0	1		FAN COMBINATION SHROUD	Cracked	0	295	No		25			221.25	Reviewing
<input type="checkbox"/>		0	1		INTERCOOLER	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		INTERCOOLER COWLING	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		WIPER WASHER TANK	Cracked	0	89.7	No		25			67.28	Reviewing
<input type="checkbox"/>		0	1		WIPER WASHER TANK MOTOR	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT LH DOOR	Buckled	0	1438.5	No		25			1078.88	Reviewing
<input type="checkbox"/>		0	1		FRONT LH DOOR HINGE (LOWER BENT)	Bent	0	131	No		25			98.25	Reviewing
<input type="checkbox"/>		0	1		FRONT LH DOOR WEATHERSTRIPE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT LH DOOR PILLAR	Buckled	0	631.4	No		25			473.55	Reviewing
<input type="checkbox"/>		0	1		FRONT LH DOOR STEP PANEL	Repair	0	0	No		25			0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT LH DOOR STEP PANEL GARNISH	Damaged	0	220.5	No		25			165.38	Reviewing
<input type="checkbox"/>		0	1		AIR CON BLOWER	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		AIR CON EVAPORATOR	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT LH SHOCK ABSORBER	Bent	0	325	No		25			243.75	Reviewing
<input type="checkbox"/>		0	1		FRONT LH LOWER ARM	Bent	0	385.5	No		25			289.13	Reviewing
<input type="checkbox"/>		0	1		FRONT LH KNUCKLE ARM	Damaged	0	451.5	No		25			338.63	Reviewing
<input type="checkbox"/>		0	1		FRONT LH WHEEL HUB C/W BEARING	Necessary	0	304.7	No		25			228.53	Reviewing
<input type="checkbox"/>		0	1		STEERING RACK & PINION	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT WINDSCREEN MOULDING	Serviceable	0	0	No		25			0	Deny

Labour














Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		PANEL BEATING, REMOVE AND REFIT PARTS	0	1400	0	0	Reviewing

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		SPRAY PAINTING TO AFFECTED AREA	0	1200	0	0	Reviewing	
<input type="checkbox"/>		0		WIRING CHECK	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		TO SPRAY TUFF COAT	0	120	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE CONDENSER AND TO TOP UP AIR CON GAS	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AND REFIT RADIATOR	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE DASHBOARD	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO REMOVE FRONT WINDSCREEN	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO TRANSFER DOOR FITTINGS	0	80	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE INTERCOOLER	0	40	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AIR CON BLOWER & EVAPORATOR	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO REMOVE FRONT UNDERCARRIAGE	0	220	0	0	Reviewing	
<input type="checkbox"/>		0		TO PERFORM WHEEL ALIGNMENT	0	80	0	0	Reviewing	
<input type="checkbox"/>		0		TOWING FEES	0	60	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary













Add











Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 12 DAYS	Reviewing		0		
<input type="checkbox"/>		0	FRONT NUMBER PLATE	Reviewing		30	MISSING	
<input type="checkbox"/>		0	FRONT NUMBER PLATE HOLDER	Reviewing		30	DEFORMED	

<input type="checkbox"/>		SR 0 NO	1 SET FRONT NAME PER CLIPS	ACTIONing	ESTIMATED AMOUNT	ADJUSTED 30 AMOUNT	COMMENT NECESSARY	 JVE
<input type="checkbox"/>		0	1 SET FRONT GRILLE CLIPS	Reviewing		30	NECESSARY	
<input type="checkbox"/>		0	1 SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Reviewing		20	NECESSARY	
<input type="checkbox"/>		0	RADIATOR COOLANT	Reviewing		40	NECESSARY	
<input type="checkbox"/>		0	1 SET INTERCOOLER COWLING CLIPS	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	FRONT LH DOOR VISOR	Reviewing		60	NECESSARY	
			1 SET FRONT HUB CAP					

<input type="checkbox"/>		SR NO	LH DOOR STEP PANEL NAME GARNISH CLIPS	Reviewing	ESTIMATED AMOUNT	ADJUSTED 20 AMOUNT	NECESSARY COMMENT	 JVE
<input type="checkbox"/>		0	FRONT LH DOOR COMPANY ADDRESS STICKER	Reviewing		30	NECESSARY	
<input type="checkbox"/>		0	FRONT LH WHEEL RIM	Reviewing		200	BENT	
<input type="checkbox"/>		0	FRONT LH TYRE	Reviewing		180	CUT	
<input type="checkbox"/>		0	FRONT WINDSCREEN SEALANT	Deny		0	NOT NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$14,380.41	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$10,360.41			
Labour		\$0.00		\$3,350.00			
Miscellaneous		\$0.00		\$670.00			

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add	Approve	Deny	Submit All				
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	11500		

Submit for Review