

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE PTE LTD		Ref:	CS3/ASM21001599/Gtf3e2	
	8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date	29/03/2021	
	ATTN : JOHNNY Y	ONG	Code	: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMC 6531A	Veh. Inspected	FBN 5914H	
	Policy No.	VPA/P2157615	Coverage (\$)	0.00	
	Claim No.	S1M030WT	Excess (\$)	0.00	
	Assign From	JOHNNY YONG	Assign Date	02/02/2021	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA XABRE TFX150	c.c	150	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	MH3RG3710JK027725	Colour	RED	
	Odometer	31818 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	110/70-17	METZELER	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	140/70-17	METZELER	5 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, N/S AND O/S BODY.				
5.	5. General Information				
	Accident Date	18/01/2021	Inspect Date / Time	03/02/2021 (11:30 AM)	
	Survey held at JC MOTORS PTE LTD 13 KAKI BUKIT ROAD 4 #01-16 BARTLEY BIZ CENTRE SINGAPORE 417807				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM21001599/Gtf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor