

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21001602/ATD3E2

Date: 10/08/2021

REFERENCE

Insured/Claimant: MASAGOS ZULKIFLI BIN MASAGOS MOHAMAD
Date of Loss: 22/01/2021

Policy No: 2100284233

Nature of Claim: OD Claim No: 6657595506SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD7013R**
Make & Model: AUDI A6, 2.0 TFSI MU (A) Engine No: CDN235119
Reg. Date: 29/12/2011 (Man. Year: 2011) Chassis No: WAUZZZ4G9CN067063
Colour: Grey Odometer: 162789 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$38,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,524.00	2,275.28	3,248.72	58.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,752.00	1,602.00	1,150.00	41.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,276.00	3,877.28	4,398.72	53.15
+ GST 7.00/7.00% (S\$)	579.32	271.41	307.91	53.15
Nett Amount (S\$)	8,855.32	4,148.69	4,706.63	53.15

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 02/02/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,832.00 FS	*2,265.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	276.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Not Necessary	347.00 FS	*- FS
4	1		*REAR BUMPER SECURING STRIP	Not Necessary	172.00 FS	*- FS
5	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,012.00 FS	*- FS
6	2		*REAR BUMPER REINFORCEMENT BEAM SEAL - LH / RH	Not Necessary	28.00 FS	*- FS
7	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	66.00 FS	*- FS
8	2		*REAR BUMPER CONNECTING PIECE - LH / RH	Not Necessary	25.00 FS	*- FS
9	2		*REAR BUMPER GUIDE PROFILE - LH / RH UPPER	Not Necessary	116.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION - CENTER	Not Necessary	106.00 FS	*- FS
11	2		*REAR SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
12	4		*REAR SENSOR SEAL RING	Not Necessary	6.00 FS	*- FS
13	1		*REAR LID WEATHERSTRIP	Not Necessary	205.00 FS	*- FS
14	1		*REAR TRIM FOR CROSS PANEL	Not Necessary	133.00 FS	*- FS
15	1		*SUNDRIES	Necessary	200.00 FS	*9.68 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 5,524.00 2,275.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$)	2,752.00
				1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >