

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI21001605/KQF3E2  
**Date:** 04/03/2021

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MS002701  
**Claimant Vehicle No :** SMP7136H **Insured Vehicle No :** GBJ2742C  
Date of Loss: 31/01/2021 Nature of Claim: TP Claim No: M2100561

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP7136H**  
Make & Model: TOYOTA COROLLA ALTIS, 1.6 Standard (A) Engine No: 1ZR0E07246  
Reg. Date: 11/10/2019 (Man. Year: 2019) Chassis No: MR053REH604598945  
Colour: Metallic Silver Odometer: 70700 km  
Engine Capacity: 1598 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm  
Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,660.65	1,022.77	2,637.88	72.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,130.00	800.00	5,330.00	86.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,790.65</b>	<b>1,822.77</b>	<b>7,967.88</b>	<b>81.38</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>685.35</b>	<b>127.59</b>	<b>557.76</b>	<b>81.38</b>
<b>Nett Amount (S\$)</b>	<b>10,476.00</b>	<b>1,950.36</b>	<b>8,525.64</b>	<b>81.38</b>

### INSPECTION

Date of Assignment: 09/02/2021  
Date Inspected: 02/02/2021 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
2, Ang Mo Kio Street 63  
Singapore 569111  
Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$1,822.78

# REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 Standard (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMP7136H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	419.48 FL	-	*419.48 FL
2	1		*SEAL,REAR BUMPER SIDE,LH	Serviceable	57.86 FL	-	*- FL
3	1		*SEAL,REAR BUMPER SIDE,RH	Serviceable	57.86 FL	-	*- FL
4	1		*RETAINER,REAR BUMPER SIDE,LH	Serviceable	114.77 FL	-	*- FL
5	1		*RETAINER,REAR BUMPER SIDE,RH	Serviceable	114.77 FL	-	*- FL
6	1		*RETAINER,REAR BUMPER UPPER,LH	Serviceable	63.42 FL	-	*- FL
7	1		*RETAINER,REAR BUMPER UPPER,RH	Serviceable	63.42 FL	-	*- FL
8	1		*PAD,REAR BUMPER,CENTER	Serviceable	6.62 FL	-	*- FL
9	1		*PAD,REAR BUMPER	Serviceable	15.96 FL	-	*- FL
10	1		*BRACKET,REAR BUMPER SEAL,LH	Serviceable	8.09 FL	-	*- FL
11	1		*BRACKET,REAR BUMPER SEAL,RH	Serviceable	8.09 FL	-	*- FL
12	1		*ARM,REAR BUMPER LH	Repair	71.61 FL	-	*- FL
13	1		*ARM,REAR BUMPER RH	Repair	71.61 FL	-	*- FL
14	1		*PIECE,REAR BUMPER	Serviceable	4.31 FL	-	*- FL
15	1		*COVER,REAR BUMPER	Buckled	584.22 FL	-	*584.22 FL
16	1		*WEATHERSTRIP,LUGGAGE COMPARTMENT DOOR	Serviceable	184.59 FL	-	*- FL
17	1		*PANEL SUB-ASSY,LUGGAGE COMPARTMENT DOOR	Repair	832.86 FL	-	*- FL
18	1		*SET PARKING AID	Dented	700.00 FS	-	*220.00 FS
19	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	-	*50.00 FS
20	1		*SET REAR LH SIDE BUMPER RETAINER CLIP	Not Necessary	35.00 FS	-	*- FS
21	1		*SET REAR RH SIDE BUMPER RETAINER CLIP	Not Necessary	35.00 FS	-	*- FS
22	1		*SET REAR RH UPPER BUMPER RETAINER CLIP	Not Necessary	35.00 FS	-	*- FS
23	1		*SET REAR LH UPPER BUMPER RETAINER CLIP	Not Necessary	35.00 FS	-	*- FS
24	1		*REAR BUMPER REFLECTOR SCREW	Not Necessary	15.00 FS	-	*- FS
25	2		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	-	*- FS
26	1		*WINDSCREEN MOULDING	Not Necessary	150.00 FS	-	*- FS
27	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	-	*- FS
28	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	-	*- FS
29	1		*SET REAR BOOT OUTER GARNISH CLIP	Not Necessary	35.00 FS	-	*- FS
30	1		*SET REAR LAMP CLIP	Not Necessary	25.00 FS	-	*- FS
31	1		*SET REAR COMBINATION LAMP CLIP	Not Necessary	25.00 FS	-	*- FS
32	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	-	*- FS
33	1		*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	-	*- FS
34	1		*SET LUGGAGE COMPARTMENT TRIM LH COVER CLIP	Not Necessary	35.00 FS	-	*- FS
35	1		*SET LUGGAGE COMPARTMENT TRIM RH COVER CLIP	Not Necessary	35.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,330.54</b>	<b>1,273.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	669.89	250.93
<b>Total Parts (S\$)</b>	<b>3,660.65</b>	<b>1,022.77</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
5	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,000.00	300.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
10	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,000.00	440.00
13	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
			<b>Gross Labour Cost (S\$)</b>	<b>800.00</b>
			<b>6,130.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >