



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 4500L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FORK INNER TUBES	SERVICEABLE	440.00	-
2	FORK OUTER TUBES	SERVICEABLE	460.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	245.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	155.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING	NOT NECESSARY	38.00	-
1	FRONT RIM	NOT NECESSARY	380.00	-
1	FRONT FENDER	TO REPAIR SEE LABOUR	120.00	-
1	TOP COWLING	CRACKED	180.00	180.00
1	SIDE COWLING	CRACKED	80.00	80.00
1	SIDE INNER COWLING	CRACKED	120.00	120.00
1	HEADLAMP	CRACKED	380.00	280.00
1	FRONT SIGNALS	SCRATCHED	160.00	160.00
1	HANDLE-BAR	BENT	145.00	145.00
1	HANDLE-BAR BALANCER	CUT	35.00	35.00
1	SET HAND GRIP	CUT	85.00	85.00
1	BRAKE LEVER (CUT)	NOT CONSISTENT WITH THE IMPACT	35.00	-
1	CLUTCH LEVER	NOT NECESSARY	22.00	-
2	SIDE MIRROR-R/L	CUT / BROKEN	160.00	160.00
1	FUEL TANK SIDE COVER-R/H	CRACKED	230.00	198.00
2	FRONT FOOTRESTS	NOT NECESSARY	80.00	-
2	FRONT FOOTREST BRACKETS	NOT NECESSARY	180.00	-
1	BRAKE PEDAL	NOT NECESSARY	45.00	-
2	REAR FOOTRESTS	NOT NECESSARY	110.00	-
1	REAR FOOTREST BRACKET	NOT NECESSARY	145.00	-
1	REAR TAILBOARD	TO REPAIR SEE LABOUR	150.00	-
2	REAR SIGNALS	NOT NECESSARY	120.00	-
1	EXHAUST ASSY	NOT NECESSARY	485.00	-

Report Ref No. CS/AGI21001621/Uvf3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST END CAP (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	52.00	-
1	EXHAUST PROTECTOR (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	65.00	-
	LESS 10% DISCOUNT		-494.70	-144.30
			4,452.30	1,298.70
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	NOT NECESSARY	28.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	95.00	-
1	REAR BOX (SN)(CUT)	NOT CONSISTENT WITH THE IMPACT	580.00	-
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-
			969.00	-
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE.		80.00	50.00
	TO CHECK WIRING AND RESET HEADLAMP FORCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	380.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FRONT FENDER AND REAR TAILBOARD.		480.00	220.00
			1,020.00	270.00
GRAND TOTAL			6,441.30	1,568.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/AGI21001621/Uvf3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.