

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21001623/GTF3E2

Date: 11/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100406397
Claimant Vehicle No : SMD6204P **Insured Vehicle No :** SFT8946S
Date of Loss: 02/02/2021 Nature of Claim: TP Claim No: 8383702593SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD6204P**
Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B5556704
Reg. Date: 28/08/2018 (Man. Year: 2018) Chassis No: RU11306696
Colour: White Odometer: 32319 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/02/2021
Date Inspected: 04/02/2021 Inspected At: Sin Hock Lee Motor Repair (HQ)
51 Ubi Ave 1, #01-09 Paya Ubi Industrial Park
Singapore 408933
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE BASE	Scratched	0.00 F	*- F
2	1		*REAR BUMPER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
6	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	* Check	0.00 F	*- F
9	1		*REAR LH TAILLAMP	* Check	0.00 F	*- F
10	1		*REAR RH TAILLAMP	* Check	0.00 F	*- F
11	1		*TAILGATE	Buckled	0.00 F	*- F
12	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
13	2		*TAILGATE LAMP	* Check	0.00 F	*- F
14	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
15	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
16	1		*TAILGATE RUBBER	* Check	0.00 F	*- F
17	1		*TAILGATE INNER BOARD	* Check	0.00 F	*- F
18	1		*SPARE TYRE BOARD	* Check	0.00 F	*- F
19	1		*SPARE TYRE PANEL	* Check	0.00 F	*- F
20	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >