

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001628/ETD3Q2

Date: 19/03/2021

REFERENCE

Insured/Claimant:	SIM POH KOK	Policy No:	1900105468	
Date of Loss:	02/02/2021	Nature of Claim:	OD	Claim No: 2019981948SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML9311B	Engine No:	G4FGKH737201
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF1416MK5044410
Reg. Date:	12/06/2019 (Man. Year: 2018)	Odometer:	20719 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,788.00	9,490.40	3,297.60	25.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,855.00	10,105.00	2,750.00	21.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,643.00	19,595.40	6,047.60	23.58
- Excess (S\$)	3,600.00	3,600.00	0.00	0.00
(S\$)	22,043.00	15,995.40	6,047.60	27.44
+ GST 7.00/7.00% (S\$)	1,543.01	1,119.68	423.33	27.44
Nett Amount (S\$)	23,586.01	17,115.08	6,470.93	27.44

INSPECTION

Date of Assignment: 03/02/2021

Date Inspected: 03/02/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 20.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL-SIDE SILL OUTREAR,RH	Dented	1,208.00 F	*1,208.00 FL
2	1		*PANEL ASSY-QUARTER OUTER,RH	Dented	1,349.00 F	*1,349.00 FL
3	1		*PANEL ASSY-QUARTER OUTER,LH	Dented	1,349.00 F	*1,349.00 FL
4	1		*PANEL ASSY-RR COMB LAMP HSG,RH	Bent	135.00 F	*135.00 FL
5	1		*PANEL ASSY-RR COMB LAMP HSG,LH	Bent	139.00 F	*139.00 FL
6	1		*PANEL ASSY-REAR DOOR,RH	Dented	1,377.00 F	*1,377.00 FL
7	1		*BLACK TAPE-RR DR FRAME RR OTR	Necessary	8.00 F	*8.00 FL
8	1		*BLACK TAPE-RR DR FR,RH	Necessary	13.00 F	*13.00 FL
9	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 F	*1,297.00 FL
10	1		*PANEL ASSY-BACK	Dented	324.00 F	*324.00 FL
11	1		*HINGE ASSY-TRUNK LID,RH	Bent	97.00 F	*97.00 FL
12	1		*HINGE ASSY-TRUNK LID,LH	Bent	97.00 F	*97.00 FL
13	1		*LOCK ASSY-KIA SUB	Cut	32.00 F	*32.00 FL
14	1		*EMBLEM-CERATO	Necessary	28.00 F	*28.00 FL
15	1		*COVER-RR BUMPER	Broken	651.00 F	*651.00 FL
16	1		*COVER-RR BUMPER LWR	Cut	241.00 F	*241.00 FL
17	1		*COVER-RR BUMPER FOG LAMP,RH	Cut	19.00 F	*19.00 FL
18	1		*COVER-RR BUMPER FOG LAMP,LH	Not Necessary	19.00 F	*- FL
19	1		*LAMP ASSY-SIDE T/SIGNAL,RH	Cut	181.00 F	*181.00 FL
20	1		*LAMP ASSY-SIDE T/SIGNAL,LH	Not Necessary	181.00 F	*- FL
21	1		*BRACKET-RR BEAM UPR MTG,RH	Not Necessary	9.00 F	*- FL
22	1		*BRACKET-RR BEAM UPR MTG,LH	Not Necessary	9.00 F	*- FL
23	1		*BRACKET-RR BEAM LWR,CTR	Not Necessary	6.00 F	*- FL
24	2		*BRACKET-RR BEAM LWR MTG	Broken	12.00 F	*12.00 FL
25	1		*BEAM-RR BUMPER	Not Necessary	318.00 F	*- FL
26	1		*STAY-RR BUMPER RH	Bent	65.00 F	*65.00 FL
27	1		*STAY-RR BUMPER LH	Bent	65.00 F	*65.00 FL
28	1		*BRACKET-ASSY RR BPR SIDE UPR,R	Not Necessary	31.00 F	*- FL
29	1		*BRACKET-ASSY RR BPR SIDE UPR,L	Not Necessary	25.00 F	*- FL
30	1		*TRIM ASSY-TRUNK LID	crushed	202.00 F	*202.00 FL
31	1		*W/STRIP-TRUNK LID OPNG	Crushed	100.00 F	*100.00 FL
32	1		*LATCH ASSY-TRUNK LID	Cut	112.00 F	*112.00 FL
33	1		*STRIKER ASSY-TRUNK LID	Not Necessary	40.00 F	*- FL
34	1		*LAMP ASSY-REAR COMB INSIDE,RH	Broken	242.00 F	*242.00 FL
35	1		*LAMP ASSY-REAR COMB INSIDE,LH	Broken	242.00 F	*242.00 FL
36	1		*LAMP ASSY-REAR COMB OUTSIDE,RH	Broken	274.00 F	*274.00 FL
37	1		*LAMP ASSY-REAR COMB OUTSIDE,LH	Broken	274.00 F	*274.00 FL
38	1		*LAMP ASSY-CENTER GARNISH	Broken	638.00 F	*638.00 FL
39	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 F	*- FL
40	1		*TRIM ASSY-LUGGAGE SIDE RH	crushed	200.00 F	*200.00 FL
41	1		*TRIM ASSY-LUGGAGE SIDE LH	crushed	200.00 F	*200.00 FL
42	1		*MAT ASSY-LUGGAGE COVERING	Not Necessary	211.00 F	*- FL
43	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
44	1		*NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
45	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
46	1		*GLASS & MOULDING ASSY-QUARTER SUPPLEMENTARY	Necessary	252.00 F	*252.00 FL
47	1		*GLASS & MOULDING ASSY-QUARTER SUPPLEMENTARY	Necessary	252.00 F	*252.00 FL
48	1		*CLIPS (X15) SUPPLEMENTARY	Necessary	15.00 F	*15.00 FL
49	1		*FILM-ANTI CHIPPG RH SUPPLEMENTARY	Necessary	27.00 F	*27.00 FL
50	1			Necessary	27.00 F	*27.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FILM-ANTI CHIPPG LH SUPPLEMENTARY			
51	1		*MOULDING ASSY-RR DR FRAME, RH SUPPLEMENTARY	Necessary	44.00 F	*44.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					12,788.00	11,848.00
- List Item Discount on L Items 0.00/20.00% (\$\$)					0.00	2,357.60
Total Parts (\$\$)					12,788.00	9,490.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW SIDE SILL RH,REAR DOOR RH,REPAIR FRT DOOR RH	New	1,600.00	1,200.00
2	REMOVE & INSTALL REAR DOOR TRIMS AND GLASS	New	150.00	150.00
3	SPRAY PAINT FOR REAR DOOR RH,SIDE SILL RH,FRT DOOR RH	New	1,050.00	1,050.00
4	APPLY SEALANT FOR REAR DOOR RH	New	40.00	40.00
5	RENEW REAR BUMPER,REAR FENDER RH & LH,BOOTLID,REAR LAMP HOUSING RH & LH,REAR END PANEL	New	5,200.00	3,200.00
6	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
7	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	300.00	300.00
8	REAR MOVE & INSTALL REAR FENDER RH & LH TRIMS,CARPET AND SEATS	New	400.00	400.00
9	REMOVE & INSTALL REAR WINDSCREEN	New	240.00	240.00
10	APPLY SEALANT FOR REAR WINDSCREEN	New	80.00	80.00
11	SPRAY PAINT FOR REAR BUMPER,BOOTLID,REAR END PANEL,REAR FENDER RH & LH,REAR LAMP HOUSING RH & LH	New	2,450.00	2,100.00
12	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
13	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
14	APPLY SEALANT FOR ACCIDENT REAR PORTION	New	160.00	160.00
15	REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR SUPPLEMENTARY	New	400.00	400.00
16	REPAIR SPEAKER PANEL BOARD SUPPLEMENTARY	New	225.00	225.00
17	RESPRAY SPEAKER PANEL BOARD SUPPLEMENTARY	New	350.00	350.00
Gross Labour Cost (\$)			12,855.00	10,105.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >