



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
SIM POH KOK	Cust No/Name LCV10160/SIM POH KOK
BLK 832 HOUGANG CENTRAL	Reg No/Reg Date SML9311B / 12/06/201
#04-540	Date In/Mileage / 0
SINGAPORE 530832	Chassis No KNAF1416MK5044410
Contact No 62880398	Engine No G4FGKH737201
	Make/Model KIA/CERATO 1.6 A L S116
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV10160	CRDVCH	02/02/2021/ 17:50		442 / CocoLu	28470		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW SIDE SILL RH, REAR DOOR RH, REPAIR FRT DOOR RH			400X3			1600.00
S SPECIALISTJOB	WO:1244344 ACCIDENT TOWED FROM HOUGANG CTR 830A TO CNC PG						
	Date 2/2/21(Tue); Time Start 10.22am, Time End 11.44am						
	Normal Towing \$50; Add: Accident \$10						
	Total Cost \$60						
E PNT88000	REMOVE & INSTALL REAR DOOR TRIMS AND GLASS						150.00
E PNT98000	SPRAY PAINT FOR REAR DOOR RH, SIDE SILL RH, FRT DOOR RH			350X3			1050.00
M SUNDRY	APPLY SEALANT FOR REAR DOOR RH						40.00
E PNT88000	RENEW REAR BUMPER, REAR FENDER RH & LH, BOOTLID, REAR LAMP HOUSING RH&LH			8 X 400			5200.00
	REAR END PANEL 1 (11pm)						3200
E PNT88000	REMOVE & INSTALL PARKING SENSOR						60.00
E PNT88000	REMOVE & INSTALL REAR COMPARTMENT TRIMS						300.00
E PNT88000	REAR MOVE & INSTALL REAR FENDER RH & LH TRIMS, CAR PET AND SEATS						400.00
E PNT88000	REMOVE & INSTALL REAR WINDSCREEN						240.00
M SUNDRY	APPLY SEALANT FOR REAR WINDSCREEN						80.00
E PNT98000	SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR FENDER RH & LH, REAR LAMP HOUSING RH & LH,			6 X 350			2450.00
A 90000001	CHECK WIRING & ELECTRICAL SYSTEM						30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST						120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
SIM POH KOK	Cust No/Name LCV10160/SIM POH KOK
BLK 832 HOUGANG CENTRAL	Reg No/Reg Date SML9311B / 12/06/201
#04-540	Date In/Mileage / 0
SINGAPORE 530832	Chassis No KNAF1416MK5044410
Contact No 62880398	Engine No G4FGKH737201
	Make/Model KIA/CERATO 1.6 A L S116
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV10160	CRDVCH	02/02/2021/ 17:50		442 / CocoLu	28470			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
USING HI-SCAN PRO TEST								160.00
M SUNDRY								
APPLY SEALANT FOR ACCIDENT REAR PORTION								40.00
M SUNDRY								
C&C LOGO								50.00
M SUNDRY								
NUMBER PLATE WITH FRAME								20.00
M SUNDRY								
Sundry					1.00	1208.00	00.00	1208.00
M PANEL-SIDE SILL OUTER,RH					1.00	1349.00	00.00	1349.00
M PANEL ASSY-QUARTER OUTER,RH					1.00	1349.00	00.00	1349.00
M PANEL ASSY-QUARTER OUTER,LH					1.00	135.00	00.00	135.00
M PANEL ASSY-RR COMB LAMP HSG,RH					1.00	139.00	00.00	139.00
M PANEL ASSY-RR COMB LAMP HSG,LH					1.00	1377.00	00.00	1377.00
M PANEL ASSY-REAR DOOR,RH					1.00	8.00	00.00	8.00
M BLACK TAPE-RR DR FRAME RR OTR,					1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FR,RH					1.00	1297.00	00.00	1297.00
M PANEL ASSY-TRUNK LID					1.00	324.00	00.00	324.00
M PANEL ASSY-BACK					1.00	97.00	00.00	97.00
M HINGE ASSY-TRUNK LID,RH					1.00	97.00	00.00	97.00
M HINGE ASSY-TRUNK LID,LH					1.00	32.00	00.00	32.00
M LOGO ASSY-KIA SUB					1.00	28.00	00.00	28.00
M EMBLEM-CERATO					1.00	651.00	00.00	651.00
M COVER-RR BUMPER					1.00	241.00	00.00	241.00
M COVER-RR BUMPER LWR					1.00	19.00	00.00	19.00
M COVER-RR BUMPER FOG LAMP,RH					1.00	19.00	00.00	19.00
M COVER-RR BUMPER FOG LAMP,LH					1.00	181.00	00.00	181.00
M LAMP ASSY-SIDE T/SIGNAL,RH					1.00	181.00	00.00	181.00
M LAMP ASSY-SIDE T/SIGNAL,LH					1.00	9.00	00.00	9.00
M BRACKET-RR BEAM UPR MTG,RH					1.00	9.00	00.00	9.00
M BRACKET-RR BEAM UPR MTG,LH					1.00	6.00	00.00	6.00
M BRACKET-RR BEAM LWR,CTR					2.00	6.00	00.00	12.00
P BRACKET-RR BEAM LWR MTG								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
SIM POH KOK BLK 832 HOUGANG CENTRAL #04-540 SINGAPORE 530832 Contact No 62880398	Cust No/Name LCV10160/SIM POH KOK Reg No/Reg Date SML9311B / 12/06/201 Date In/Mileage / 0 Chassis No KNAF1416MK5044410 Engine No G4FGKH737201 Make/Model KIA/CERATO 1.6 A L S116 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV10160	CRDVCH	02/02/2021/ 17:50		442 / CocoLu	28470			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BEAM-RR BUMPER				1.00	318.00	00.00	318.00
M	STAY-RR BUMPER RH				1.00	65.00	00.00	65.00
M	STAY-RR BUMPER LH				1.00	65.00	00.00	65.00
M	BRACKET-ASSY RR BPR SIDE UPR,R				1.00	31.00	00.00	31.00
M	BRACKET ASSY-RR BPR SIDE UPR,L				1.00	25.00	00.00	25.00
M	TRIM ASSY-TRUNK LID				1.00	202.00	00.00	202.00
M	W/STRIP-TRUNK LID OPNG				1.00	100.00	00.00	100.00
M	LATCH ASSY-TRUNK LID				1.00	112.00	00.00	112.00
M	STRIKER ASSY-TRUNK LID				1.00	40.00	00.00	40.00
M	LAMP ASSY-REAR COMB INSIDE,RH				1.00	242.00	00.00	242.00
M	LAMP ASSY-REAR COMB INSIDE,LH				1.00	242.00	00.00	242.00
M	LAMP ASSY-REAR COMB OUTSIDE,RH				1.00	274.00	00.00	274.00
M	LAMP ASSY-REAR COMB OUTSIDE,LH				1.00	274.00	00.00	274.00
M	LAMP ASSY-CENTER GARNISH				1.00	638.00	00.00	638.00
M	TRIM ASSY-RR TRANSVERSE				1.00	41.00	00.00	41.00
M	TRIM ASSY-LUGGAGE SIDE RH				1.00	200.00	00.00	200.00
M	TRIM ASSY-LUGGAGE SIDE LH				1.00	200.00	00.00	200.00
M	MAT ASSY-LUGGAGE COVERING				1.00	211.00	00.00	211.00

Steve CLKK)

3/2/21, 11.30am

00- AM AL

EXPRS - ?

P/P

By BL SM

20 days

Date: _____
 Signature: _____
 Acknowledged by Repairer

is subject to final approval from Insurance Company

- Supplementary item(s) must be resurveyed and
- No illegal modification(s) is allowed
- Third party survey is on a "Without Prejudice" basis
- Parts prices are subject to confirmation
- To display damaged part(s) during resurvey
- To resurvey before/after body painting

Confirm & accepted by the Repairer of the LKK Auto Consultants hence notified

Nett	24,051.00
7% GST on	1683.57
Total Payable	25,734.57

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.